



Expertise

Protocol number: 46791884
Order No. / Reference: 26639576
Inspection date: 29 Jul 2026

Manufacturer: Opel

Model: Insignia Sports Tourer 2.0 Diesel Business

VIN: W0VZT8EP9M1031563



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Insignia Sports Tourer 2.0 Diesel Business	
Vehicle Identification number	W0VZT8EP9M1031563
Mileage (Read)	142,299 km
First registration	31 Jan 2022
Number of holders	1
Next periodical technical inspection	02/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	128 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Carbon Braun Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	1 Monat(e)
Last service on / at	09/2025 at 119,132 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GF941308
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1844 / AMC 00241		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,205 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 97W	Summer tyres on Light alloy	Continental	3mm / 3mm
2)	225/55 R17 97W	Summer tyres on Light alloy	Continental	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 97H	Winter tyres on Light alloy	Continental	4mm / 4mm
2)	225/55 R17 97H	Winter tyres on Light alloy	Goodyear	7mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaanlage

Standard equipment

- Storage compartments
- Airbag: Front and rear outer head airbags
- Ambient lighting
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- Roof rails, silver anodized
- Tachometer
- Electronic Stability Program (ESP Plus)
- Front collision warning system with pedestrian detection and automatic emergency braking
- Speed controller
- rear window wiper
- Automatic climate control, two zones
- Rear headrests (3 pieces)
- LED fog lights
- Steering column adjustable for height and reach
- Illuminated makeup mirrors in both sun visors
- Package: Charging (Sports Tourer)
- Package: Innovations 1
- Electric parking brake
- Upholstery: Monita fabric/Premium leather look
- Radio: Digital radio reception DAB+
- Radio accessories: 2 USB ports
- Tire repair kit
- Wheels: Alloy wheels 8.5 J x 18 (multi-spoke)
- Power steering
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- Lane Keeping Assist
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control

Extra equipment

- Swiveling trailer hitch (including trailer stability program)

- Airbag: Front airbags (multi-stage) and side airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Hill Start Assist
- third brake light
- Diesel particulate filter
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Pedestrian protection including active hood
- luggage compartment cover
- Transmission: 6-speed manual transmission
- Child safety lock in the rear doors, manual
- Front headrests
- LED headlights
- LED daytime running lights including LED indicators, front and LED taillights
- Center armrest, front
- Package: Easy-Access
- Park & Go with reversing camera, digital
- Parkpilot, front and rear parking aid
- Quickheat rapid heating system
- Radio: Multimedia Navi Pro with 8" color touchscreen display
- Tire pressure gauge
- Rear seat backrest with FlexFold function, foldable in a 40:20:40 ratio
- safety net
- Seats: Ergonomic active seat (AGR) for driver and front passenger
- Bumpers painted in body color
- Pre-installation for child seat mounting system "ISOFIX"
- Thermal insulation glazing, green tinted
- Second folding ignition key

- Paint finish: Metallic special color



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front left side - Scratch(es) - No deduction
2	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - No deduction
3	Trim / covers	Floor mats - Damaged - Replace
4	Door - front left side	Door edge - Scratch(es) - Smart repair
5	Equipment	Tirefit filler - Expired - Replace
6	Door - front left side	Door handle - outside - Scratch(es) - Smart repair
7	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
8	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
9	Bonnet	Bonnet - dent(s) - Smooth repair work
10	Door - rear left side	Door - dent(s) - Smooth repair work
11	Mudguard - right side	Mudguard - right side - dent(s) - Smooth repair work
12	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
13	Door - front right side	Door - dent(s) - Smooth repair work
14	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
15	Boot lid / rear door	Trim - standard - lower - Scratched - Loss in value
16	Wheel / tyres	Alloy rim - front right side (Materialabtrag) - Scratch(es) - Replace
17	Body	C-pillar - left side - Dent / paintcoat damage - Repair and paint
18	Rear bumper	Rear bumper - Scratch(es) - Paint

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 22 Apr 2022	724,07 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Wartungshistorie gemäß Auftraggeber Informationen.
- Winterradsatz ist kein Bestandteil des Auslieferumfangs.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres



Figure 19: Additional tyres



Figure 20: Additional tyres



Figure 21: Navigation



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Damage 3: Trim / covers: Floor mats - Damaged - Replace



Damage 4: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 4: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 5: Equipment: Tirefit filler - Expired - Replace



Damage 6: Door - front left side: Door handle - outside - Scratch(es) - Smart repair



Damage 6: Door - front left side: Door handle - outside - Scratch(es) - Smart repair



Damage 7: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 7: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 8: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 8: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 9: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 9: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 10: Door - rear left side: Door - dent(s) - Smooth repair work



Damage 10: Door - rear left side: Door - dent(s) - Smooth repair work



Damage 11: Mudguard - right side: Mudguard - right side - dent(s) - Smooth repair work



Damage 11: Mudguard - right side: Mudguard - right side - dent(s) - Smooth repair work




Damage 12: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 12: Side panel - rear right side: Side panel - dent(s) - Smooth repair work




Damage 12: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 13: Door - front right side: Door - dent(s) - Smooth repair work




Damage 13: Door - front right side: Door - dent(s) - Smooth repair work



Damage 13: Door - front right side: Door - dent(s) - Smooth repair work




Damage 14: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 14: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 14: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 14: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 14: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 15: Boot lid / rear door: Trim - standard - lower - Scratched - Loss in value



Damage 15: Boot lid / rear door: Trim - standard - lower - Scratched - Loss in value



Damage 16: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratch(es) - Replace



Damage 16: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratch(es) - Replace



Damage 16: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratch(es) - Replace



Damage 17: Body: C-pillar - left side - Dent / paintcoat damage - Repair and paint



Damage 17: Body: C-pillar - left side - Dent / paintcoat damage - Repair and paint



Damage 18: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 18: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 18: Rear bumper: Rear bumper - Scratch(es) - Paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VZT8EP9M1031563

Hersteller / Modell: OPEL OPEL Insignia Sports Tourer 2.0 Diesel Business

Datum	KM-Stand	Beschreibung
13.01.2026	132.777	Reparatur Sonstiges
12.12.2025	130.499	Reparatur Sonstiges; Systemtest/Eigendiagnose
05.09.2025	119.132	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
11.04.2025	107.176	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v
10.02.2025	101.929	HU + AU; HU + AU
10.01.2025	101.929	HU + AU
17.09.2024	90.456	Lichtmaschine ern/inst
13.09.2024	89.632	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
18.10.2023	60.032	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
30.06.2023	51.277	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne
21.11.2022	30.384	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges