



Expertise

Protocol number: 46710467
Order No. / Reference: 26759860
Inspection date: 24 Jul 2026

Manufacturer: Mercedes-Benz	Model: C 220 d T 9G-TRONIC AMG Line
VIN: W1KAH0EB7PF114324	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz C 220 d T 9G-TRONIC AMG Line	
Vehicle Identification number	W1KAH0EB7PF114324
Mileage (Read)	153,203 km
First registration	29 Jun 2023
Number of holders	1
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,993 ccm / 4
Power	147 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Station wagon
Colour / colour code	GRAPHITGRAU - METALLICLACK
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	2,340 km
Last service on / at	12/2025 at 129,964 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV675785
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / AYH 00301		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,400 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 95Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	245/40 R18 97Y	Summer tyres on Light alloy	Pirelli	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 95H	Winter tyres on Light alloy	Pirelli	6mm / 6mm
2)	225/45 R18 95H	Winter tyres on Light alloy	Pirelli	4mm / 4mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Airbag for driver and front passenger
- Airbag: Center airbag
- Airbag: Windowbag for driver and front passenger
- AMG floor mats
- Left and right exterior mirrors are heated and electrically adjustable
- Brake system with larger brake discs on the front axle
- black roof rails
- Double cup holder at the front
- EASY-PACK tailgate
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Transmission: 9-speed automatic, 9G-TRONIC
- Heated rear window
- Instrument panel and door sills in ARTICO man-made leather in black nappa look
- Mechanical child safety lock for the rear doors
- Rear headrests (3)
- Paint finish: Solid
- LED High Performance Headlights
- Mercedes-Benz emergency call system
- Center console in high-gloss black
- Package: Interior lighting package
- Radio: Extended MBUX functions
- Radio accessories: Digital radio (DAB)
- Radio accessories: Central display
- Tire pressure monitoring system (TPMS)
- Wheels: 45.7 cm (18") AMG light-alloy wheels in a 5-spoke design
- Lane Keeping Assist, active
- High-visibility vest for drivers
- Central locking with remote control
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Ambient lighting with 64 light colors
- AMG sports pedal assembly made of brushed stainless steel with rubber studs
- Basic services
- Brake assist, active
- Diesel particulate filter
- DYNAMIC SELECT
- ECO start/stop function
- Chassis: Sport chassis with sport direct steering
- Speed Limit Assistant
- rear window wiper
- Interior headliner fabric crystal grey
- ISOFIX child seat attachment with top tether in the rear
- KEYLESS-GO start function
- THERMATIC automatic climate control with 1 climate zone
- Front headrests
- Cargo area cover including EASY-PACK safety net
- Steering wheel: Multifunction sports steering wheel in Nappa leather
- Package: Storage
- Upholstery: ARTICO leatherette/MICROCUT microfiber
- Radio: MBUX
- Radio accessories: Communication module (LTE) for using Mercedes me connect services
- Remote Services Plus
- Windscreen wipers with rain sensor
- Seats: Rear seat backrests foldable
- Cruise control
- Electronic immobilizer
- Decorative elements, metal structure



Extra equipment

- Towbar with ESP trailer stabilization
- Head-up display
- Black fabric headliner
- Fuel tank with larger capacity
- Paint finish: Metallic
- Package: Advanced Infotainment Package (MBUX Navigation Premium (hard drive navigation, pre-installation for Live Traffic Information), Traffic Sign Assist, Smartphone Integration (connects the mobile phone wirelessly to the multimedia system via Apple CarPlay and Android Auto), Wireless charging system for mobile devices in the front, Driver display - 31.2 cm (12.3") color LCD display, Central display - 30.2 cm (11.9") touch display with LCD technology)
- Package: Driving Assistance (Active Distance Assist DISTRONIC, Active Speed Limit Assist, Extended Automatic Restart on Highways, Route-Based Speed Adaptation with Traffic Jam End Function, Active Traffic Jam Assist, Active Steering Assist, Active Lane Change Assist, Active Emergency Stop Assist, Emergency Lane Function, Active Brake Assist with Vehicle, Bicycle and Pedestrian Detection; Intersection Function, Turn Function, Traffic Jam End Emergency Braking Function, Evasive Steering Assist, Active Lane Keeping Assist, Active Blind Spot Assist, Exit Warning Function)
- Package: Light (Adaptive Highbeam Assist - automatic switching of the high beams, camera on the inside of the windshield, detects oncoming and preceding illuminated vehicles, activated by pressing the steering wheel control lever to the high beam position)
- Package: Mirror package (both exterior mirrors electrically folding (button in the driver's door control panel) - interior mirror and exterior mirror on the driver's side automatically dimming continuously - ambient lighting of the exterior mirror to illuminate the entry area with projection of the Mercedes-Benz logo)
- Seats: Sports seats
- Heat-insulating dark tinted glass
- Chassis: AGILITY CONTROL chassis with selective damping system and lowered suspension
- THERMATIC automatic climate control with 2 climate zones (control via the central display or the climate control unit in the center console; sensor system for detecting, for example, indoor/outdoor temperature, sunlight, humidity, and dew point; automatic recirculation (only in conjunction with navigation system); ventilation system consisting of: 3 center vents and 2 side vents; fine dust activated carbon filter for filtering dust, soot, and pollen; dew point sensor; residual heat function for efficient use of engine waste heat)
- Package: Advanced Parking Package (12 ultrasonic sensors - 360° camera - Active Parking Assist with PARKTRONIC: detects free parking spaces, assisted parking, visual and acoustic warning, display of camera and ultrasonic data in the media display - Cross traffic warning: can provide visual and acoustic warnings when reversing out of a parking space and, if necessary, automatically initiate emergency braking - Reverse maneuvering brake: can trigger a braking process - Drive-away assist)
- Package: High-End Comfort Package (Seat heating for driver and front passenger - Memory Package: Driver and front passenger seats, steering column and exterior mirrors electrically adjustable and storable; Seat longitudinal position and headrest height additionally electrically adjustable; 3 memory settings each for driver and front passenger; 4-way lumbar support for driver and front passenger; Seat cushion depth adjustment with gapless cushion; PRE-SAFE positioning function for the front passenger seat)
- Wheels: Complete summer wheel sets fitted at the factory
- Wheels: Winter complete set of wheels M+S 4x 45.7 cm (18") multi-spoke alloy wheels (black painted and polished with 225/45 R 18 on 7.5 J x 18 ET 40)
- Type designation removed from trunk lid

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Instrument panel	Centre console - front - Scratch(es) - Loss in value
2	Trim / covers	Boot lid - interior trim - Scratch(es) - Loss in value
3	Sill - right side	Trim - Scratch(es) - Smart repair
4	Door - front right side	Door edge - Scratch(es) - Smart repair
5	Side panel - rear right side	Sill - Scratch(es) - Smart repair
6	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
7	Front axle	Axles / undercarriage (wegen der beschädigten Felgen) - Specify findings - Measure
8	Body	Underbody panelling - Broken / torn - Replace
9	Door - front left side	Door edge - Dent / paintcoat damage - Smart repair
10	2nd wheel set	2 tyres (4mm) - Does not meet the leasing specifications - Replace
11	2nd wheel set	1 alloy rim - Scratched - Loss in value
12	2nd wheel set	1 alloy rim - Scratched - Loss in value
13	Wheel / tyres	Alloy rim - front left side - Scratched - Loss in value
14	Wheel / tyres	Alloy rim - front right side - Scratched - Loss in value
15	Wheel / tyres	Alloy rim - rear right side - Scratched - Loss in value
16	Front bumper	Front bumper - Scratched - Repair and paint
17	Vehicle glazing	Windscreen - Stone chips - repair according to calculation

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Side panel - Scratch(es) - No deduction
2	Sill - left side	Sill - Scratch(es) - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Steering system	Steering wheel - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 4 Dec 2023	2.235,06 €
2	Side right, Provided by user / customer, from 11 Sept 2023	2.463,23 €

Accident damages

No.	Accident
1	Rear

Repainting

No.	Repainting
1	Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
2	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
3	Door - front right side, Professionally carried out, Invoice of repair done Non-existent



Paint coat thickness measurement

Mudguard - right side	165 µm	Door - rear right side	180 µm
Door - front right side	445 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Der beiliegende Winterradsatz ist Bestandteil der Auslieferungsumfangs.

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.

Die Felgen wurden aufgrund der Laufleistung gemindert.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.






Figure 29: Misc.



Figure 30: Misc.




Damage 1: Instrument panel: Centre console - front - Scratch(es) - Loss in value



Damage 1: Instrument panel: Centre console - front - Scratch(es) - Loss in value



Damage 2: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value



Damage 2: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value



Damage 3: Sill - right side: Trim - Scratch(es) - Smart repair




Damage 3: Sill - right side: Trim - Scratch(es) - Smart repair




Damage 4: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 4: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 5: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 5: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 6: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 6: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 6: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 8: Body: Underbody panelling - Broken / torn - Replace




Damage 8: Body: Underbody panelling - Broken / torn - Replace



Damage 9: Door - front left side: Door edge - Dent / paintcoat damage - Smart repair



Damage 9: Door - front left side: Door edge - Dent / paintcoat damage - Smart repair



Damage 9: Door - front left side: Door edge - Dent / paintcoat damage - Smart repair



Damage 9: Door - front left side: Door edge - Dent / paintcoat damage - Smart repair



Damage 10: 2nd wheel set: 2 tyres (4mm) - Does not meet the leasing specifications - Replace




Damage 10: 2nd wheel set: 2 tyres (4mm) - Does not meet the leasing specifications - Replace



Damage 10: 2nd wheel set: 2 tyres (4mm) - Does not meet the leasing specifications - Replace



Damage 10: 2nd wheel set: 2 tyres (4mm) - Does not meet the leasing specifications - Replace



Damage 11: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 11: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 12: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 12: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 13: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 13: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 13: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 14: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value




Damage 14: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 15: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 15: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint




Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint




Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 17: Vehicle glazing: Windscreen - Stone chips - repair according to calculation



Damage 17: Vehicle glazing: Windscreen - Stone chips - repair according to calculation



Wear and tear 1: Side panel - rear right side: Side panel - Scratch(es) - No deduction




Wear and tear 1: Side panel - rear right side: Side panel - Scratch(es) - No deduction



Wear and tear 3: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 3: Bonnet: Bonnet - Stone chips - No deduction




Wear and tear 3: Bonnet: Bonnet - Stone chips - No deduction




Wear and tear 4: Steering system: Steering wheel - Scratch(es) - No deduction




Wear and tear 4: Steering system: Steering wheel - Scratch(es) - No deduction



Accident 1: Rear



Accident 1: Rear




Accident 1: Rear



Accident 1: Rear




Accident 1: Rear



Accident 1: Rear



Accident 1: Rear



Accident 1: Rear




Accident 1: Rear



Accident 1: Rear




Accident 1: Rear



Accident 1: Rear



Accident 1: Rear




Accident 1: Rear



Accident 1: Rear



Accident 1: Rear



Accident 1: Rear



Accident 1: Rear



Repainting 1: Mudguard - right side



Repainting 2: Door - rear right side



Repainting 3: Door - front right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1KAH0EB7PF114324

Hersteller / Modell: MERCEDES-BENZ MB C 220 d T 9G-TRONIC AMG Line

Datum	KM-Stand	Beschreibung
09.12.2025	129.964	Bremsscheiben vorne; Regelwartungsdienst
02.07.2025	105.514	Bremsklötze hinten; Regelwartungsdienst
28.01.2025	80.912	Regelwartungsdienst
09.08.2024	56.700	Bremsscheiben vorne; Regelwartungsdienst
15.02.2024	30.816	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges