



2-FGR-234


2-FGR-234 · 50e M Sportpakket · 6 August 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FGR-234	Fuel Type	Hybrid Gasoline
Manufacturer	BMW	VIN	WBA41EU0309V97224
Model	X5	Cylinder Capacity	2.998 ^{cm3}
Model Versions	50e M Sportpakket	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	03-05-2024
Color	Grey	Odometer	74.550 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Black
KW	155	Number Headrests	5

Images





Accessories

ABS	Electric windows front
Airbags	Electrically adjustable driver's seat
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Front & rear parking sensors
Automatic air conditioning	Leather steering wheel
	Navigation system
Bluetooth car kit	Rear view camera
	Roller cover / parcel shelf
Central door locking	Seat heating
Centre armrest	Steering wheel multifunction
Charging cable - 230v	Steeringwheel - Heated
Charging cable - 380v	
Cruise control	
Electric rear windows	

Condition

Condition exterior	Adequate	Maintenance Remarks	Olie verversen over 14000 km
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 ^{mm}	Michelin	275 ^{mm}	45 ^{mm}	20 ^{inch}	All Season
Rear Left	5 ^{mm}	Michelin	275 ^{mm}	45 ^{mm}	20 ^{inch}	All Season
Front Right	5 ^{mm}	Michelin	275 ^{mm}	45 ^{mm}	20 ^{inch}	All Season
Rear Right	5 ^{mm}	Michelin	275 ^{mm}	45 ^{mm}	20 ^{inch}	All Season
Spare Tire Type	None					

Damages



Damage Part
Tailgate



Damage Type
Dislocated / Loose




Repair Type
Repair



Acceptable
No



Damage Part
Skirt - Right




Damage Type
Small scratch(es)



Repair Type
Touch-up / Polish




Acceptable
No




Damage Part
Alloys



Damage Type
Damaged



Notes
4 x



Repair Type
Rim repair

Acceptable
No




Damage Part
Reardoor - Right



Damage Type
Dent(s) & Scratch(es)



Repair Type
Panelbeating & Spray



Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Small dent(s)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Front	Dislocated / Loose	Luchtinlaat kapje	Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Grille	Broken	Replace	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Luchtinlaat	Panelbeating & Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Luchtinlaat	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Small scratch(es)	Touch-up	No



Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Cargohold	Scratch(es)	Plastic Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Scratch(es)	Spray	No