



Expertise

Protocol number: 46888351
Order No. / Reference: 26783107
Inspection date: 5 Aug 2026

Manufacturer: Opel

Model: Astra 1.5 D Start/Stop Sports Tourer Elegance

VIN: W0VBE8EV6N8037856



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Start/Stop Sports Tourer Elegance	
Vehicle Identification number	W0VBE8EV6N8037856
Mileage (Read)	92,830 km
First registration	29 Apr 2022
Number of holders	1
Next periodical technical inspection	06/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,496 ccm / 3
Power	90 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Argonsilber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	0 %
Last service on / at	06/2025 at 72,354 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ635164
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1844 / ALM 00227		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,945 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Light alloy	Dunlop	6mm / 6mm
2)	205/55 R16 91V	Summer tyres on Light alloy	Dunlop	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	115/70 R16 92M	Summer tires (with run-flat tires) on Steel	Continental	3 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaautomatik

Standard equipment

- Storage compartments
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- Decorative trim strips in piano black
- Tachometer
- Electric windows front and rear
- Speed controller with limiter
- Back window, heater
- Interior lighting, front and rear
- Automatic climate control, two zones
- trunk light
- Front headrests
- LED headlights
- Light alloy wheels 7 J x 16 in a "10-spoke" design
- Lighting equipment
- Electric parking brake
- Upholstery: Fabric/Premium leather look
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire pressure monitoring system
- Power steering
- Luggage compartment safety net
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control and interior switches
- Airbag for driver and passenger side
- Airbag: Head airbags, 1st and 2nd row (outer seats)
- Ambient lighting, front doors
- Automatic activation of the hazard warning lights
- Hill Start Assist
- On-board computer
- Roof rails, silver
- Diesel particulate filter (DPF)
- Electronic Stability Program Plus (ESP Plus)
- Front camera
- Transmission: 6-speed manual transmission
- rear window wiper
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- Rear headrests (3)
- Cargo area cover
- LED daytime running lights
- Steering column, height and reach adjustable
- Sliding center armrest, front
- Pedals: Disengaging safety pedals
- Quickheat rapid heating system
- Radio: Multimedia radio with 7" touchscreen color display
- Rear seat backrest folds forward in a 60:40 split
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- 12V power outlet in the center console
- Pre-installation for child seat mounting system "ISOFIX"
- Heat-insulating glazing, green tinted, and windshield



Extra equipment

- Connectivity services (emergency call)
- Heated windscreen, ThermoTec
- Ignition keys, two, both foldable
- Interior equipment Sports Tourer (rear seat backrest foldable in 40:20:40 ratio - rear center armrest with pass-through from the luggage compartment - FlexFold rear seat backrest)
- Package: Elegance Package (IntelliLux LED Matrix headlights - LED taillights - Multimedia Navi Pro voice control touchscreen color display multimedia radio Apple CarPlay/Android Auto Bluetooth - Solar Protect heat-insulating glazing, heavily tinted, in the rear)
- Seats: Ergonomic active seat, driver and front passenger (certified by the Campaign for Healthy Backs (AGR) Driver and front passenger seat: - Length, height and tilt adjustable - Electropneumatic lumbar support adjustable in height and length - Extendable thigh support - Pocket on the back of the front seats, driver and front passenger)
- Wheels: Emergency spare wheel, steel 4Jx16
- Digital reversing camera with steering guidelines
- Paint finish: Metallic
- Park & Go Digital (Automatic parking assistant including parking pilot, front and rear parking aid - blind spot warning in both exterior mirrors - electrically folding exterior mirrors - digital reversing camera with steering guidelines)
- Phone: Wireless charging including 2 USB ports, rear
- Steering wheel: Heated leather steering wheel and seat heating, multi-stage, driver and front passenger (including rear footwell heating)
- Traffic sign assistant with pedestrian detection, front (detection of speed limits, no-overtaking zones and their cancellation, additional information signs (e.g., for wet conditions, slippery surfaces, left/right directions) on standard traffic signs, beginning and end of motorways, expressways and traffic-calmed areas, display of the detected sign in the driver information display (depending on traffic sign quality, visibility and weather conditions), automatic activation between 14 km/h and 200 km/h (during the day) or 150 km/h (at night))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Screen cleaning	Wiper arm - rear - Damaged - Replace
2	Sill - left side	Sill - dent(s) - Smooth repair work
3	Door - front left side	Door - dent(s) - Smooth repair work
4	Door - front right side	Door - dent(s) - Smooth repair work
5	Door - front right side	Door handle - outside - Scratch(es) - Paint
6	Side panel - rear left side	Elbow - Scratched - Smart repair
7	Door - front left side	Door edge - Scratched - Smart repair
8	Engine	Engine cover - Broken / torn - Replace
9	Misc.	Inspection / maintenance - Due - Perform
10	Rear bumper	Rear bumper - Scratched - Repair and paint
11	Front bumper	Front bumper - Stone chips - Paint
12	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint



Wear and tear

No.	Component group	Description
1	Body	Underbody panelling - Scratched - No deduction
2	Bonnet	Bonnet (Vorn) - Stone chips - No deduction
3	Door - rear left side	Door - Stone chips - No deduction
4	Side panel - rear right side	Sill - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents




Figure 17: Documents




Figure 18: Documents



Figure 19: Documents




Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Damage 1: Screen cleaning: Wiper arm - rear - Damaged - Replace




Damage 1: Screen cleaning: Wiper arm - rear - Damaged - Replace




Damage 2: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 2: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 3: Door - front left side: Door - dent(s) - Smooth repair work



Damage 3: Door - front left side: Door - dent(s) - Smooth repair work



Damage 4: Door - front right side: Door - dent(s) - Smooth repair work




Damage 4: Door - front right side: Door - dent(s) - Smooth repair work



Damage 5: Door - front right side: Door handle - outside - Scratch(es) - Paint



Damage 5: Door - front right side: Door handle - outside - Scratch(es) - Paint



Damage 6: Side panel - rear left side: Elbow - Scratched - Smart repair




Damage 6: Side panel - rear left side: Elbow - Scratched - Smart repair



Damage 7: Door - front left side: Door edge - Scratched - Smart repair



Damage 7: Door - front left side: Door edge - Scratched - Smart repair



Damage 8: Engine: Engine cover - Broken / torn - Replace



Damage 8: Engine: Engine cover - Broken / torn - Replace



Damage 8: Engine: Engine cover - Broken / torn - Replace



Damage 8: Engine: Engine cover - Broken / torn - Replace




Damage 9: Misc.: Inspection / maintenance - Due - Perform



Damage 10: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 10: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 10: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage 10: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 10: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 10: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Wear and tear 1: Body: Underbody panelling - Scratched - No deduction



Wear and tear 2: Bonnet: Bonnet (Vorn) - Stone chips - No deduction



Wear and tear 3: Door - rear left side: Door - Stone chips - No deduction



Wear and tear 4: Side panel - rear right side: Sill - Scratch(es) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VBE8EV6N8037856

Hersteller / Modell: OPEL OPEL Astra 1.5 D Start/Stop Sports Tourer Elegance

Datum	KM-Stand	Beschreibung
10.02.2026	87.115	Ladeluftschlauch ern; Reparatur Sonstiges; Systemtest/Eigendiagnose; Turbolader ern
26.06.2025	72.354	Bremse Sonstiges; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
29.05.2024	52.147	Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Kraftstofffilter ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges
17.04.2023	24.277	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges