



Expertise

Protocol number: 46053681  
Order No. / Reference: 26453481  
Inspection date: 17 Jun 2026

Manufacturer: Mercedes-Benz  
VIN: W1N0J2DBXPG135582

Model: GLC-Coupe 400 d 4Matic 9G-TRONIC



| Vehicle details                                |                    |
|------------------------------------------------|--------------------|
| Manufacturer / Type / Model / Equipment        |                    |
| Mercedes-Benz GLC-Coupe 400 d 4Matic 9G-TRONIC |                    |
| Vehicle Identification number                  | W1N0J2DBXPG135582  |
| Mileage (Read)                                 | 187,082 km         |
| First registration                             | 20 Dec 2022        |
| Number of holders                              | 1                  |
| Next periodical technical inspection           | 12/2027            |
| (Report on hand)                               |                    |
| Power / Engine displacement                    | 243 kw / 2,925 ccm |
| Fuel type / Cylinder                           | Diesel / 6         |
| Gearbox / Number of gears                      | Automatic / 9      |
| Type of drive                                  | All-wheel drive    |
| Type of vehicle                                | SUV                |
| Colour / colour code                           | SCHWARZ - UNILACK  |
| Doors / Seats                                  | 5 / 5              |
| Upholstery type                                | Leather            |
| Colour of upholstery                           | Black              |
| readiness to drive                             | Roadworthy         |



## Vehicle details

|                                                  |                              |                                |                                                            |
|--------------------------------------------------|------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | Non-existent                 | <b>Next maintenance in</b>     | 154 Tag(e)                                                 |
| <b>Key is / should be</b>                        | 2 / 2                        | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                              | <b>Letter No.</b>              | GM950698                                                   |
| <b>Previous damage / Accident</b>                | Detectable                   | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient                   | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | Not performed                | <b>Engine function test</b>    | Performed                                                  |
| <b>readiness to drive</b>                        | Roadworthy                   |                                |                                                            |
| <b>Manufacturer key number/ type code number</b> | 2222 / AKS 00093             |                                |                                                            |
| <b>Emission standard</b>                         | EURO6;WLTP;AP;PI/CI; M, N1 I | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,585 kg                     | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/55 R19 101V | Summer tyres on Light alloy | Bridgestone  | 5mm / 5mm   |
| 2) | 235/55 R19 101V | Summer tyres on Light alloy | Bridgestone  | 4mm / 4mm   |

### Additional tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/60 R18 103H | Winter tyres on Light alloy | Bridgestone  | 5mm / 4mm   |
| 2) | 235/60 R18 103H | Winter tyres on Light alloy | Pirelli      | 3mm / 3mm   |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

## Equipment

### Standard equipment

- Storage compartments
- Airbag: Kneebag for driver
- Airbag: Windowbags
- 4MATIC all-wheel drive
- ATTENTION ASSIST
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Diesel particulate filter
- Third brake light in LED technology
- EASY-Pack tailgate with electric operation for opening and closing
- Driving light assistant
- Electric windows (4-way)
- Velour floor mats in interior color
- Rear window heated
- KEYLESS-GO start function
- Instrument cluster with 2 tubular round instruments, 13.97 cm (5.5") multifunction display
- Headrests 5-way
- Fuel tank with larger volume 66 l
- LED High Performance Headlights
- Steering column mechanically adjustable in height and length
- Navigation accessories: Extended MBUX functions
- Package: Chrome
- Upholstery: ARTICO man-made leather
- Radio accessories: Remote Online
- Tire pressure monitoring system (TPMS)
- Wheels: 45.7 cm (18") alloy wheels, 4-spoke design, 5-triple-spoke design
- Seats: Rear seat backrests foldable
- Seats: Front seats electrically adjustable
- Pre-installation for roof rack systems
- Immobiliser
- Central locking
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- Anti-lock braking system (ABS)
- Automatic passenger airbag deactivation
- On-board computer
- Brake system with larger brake discs on the front axle
- Tachometer
- DYNAMIC SELECT
- EASY-Pack cargo cover (removable)
- Electronic Stability Program (ESP)
- Chassis: Sport chassis
- electric parking brake
- Transmission: 9G-TRONIC
- Black fabric headliner
- Climate: THERMATIC automatic climate control with 2 climate zones
- Communication module (LTE) for the use of Mercedes me connect services
- Paint finish: Solid
- Steering wheel: Multifunction sports steering wheel in 3-spoke design in black leather
- Mercedes-Benz emergency call system
- Package: Storage
- Package: Interior light
- Radio accessories: Digital radio
- Radio accessories: Touchpad
- Remote Services Plus
- Rear view camera
- Windscreen wipers with rain sensor
- Seats: i-Size child restraint system on the outer rear seats
- Cruise control
- High-visibility vest for drivers
- Heat and sound insulating acoustic glass
- Decorative elements: Piano lacquer look in high-gloss black

### Extra equipment

- Paint finish: Special paint finish, solid color
- Package: Advanced Infotainment
- Package: Advanced Park
- Package: Comfort
- Package: Mirrors (Electrically folding exterior mirrors, lowering right exterior mirror, automatic dimming function)
- Wheels: 45.7 cm (18") alloy wheels, 4-spoke design (tremolite grey painted and polished with 235/60 R18 tires, 8 J x 18 ET 38)
- Wheels: M+S winter tires, 4x (instead of summer tires)
- Heated windshield washer system
- Auxiliary heating including auxiliary ventilation in summer
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: Business (Advanced Parking Package: Active Parking Assist PARKTRONIC with reversing camera; Advanced Infotainment Package: Media display with touch operation, smartphone integration - Apple CarPlay and Android Auto, connectivity package navigation, traffic sign assist; Comfort Package: Heated seats for driver and front passenger, seat comfort package - electric and manual adjustment options for the front seats; larger fuel tank capacity)
- Type designation removed from tailgate



## Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |
| readiness to drive   | The vehicle was roadworthy at the time of inspection.                                                                                                                        |

## Value reducing factors

| No. | Component group         | Description                                                  |
|-----|-------------------------|--------------------------------------------------------------|
| 1   | Misc.                   | Inspection / maintenance - No evidence - No deduction        |
| 2   | Wheel / tyres           | Alloy rim - front right side - Scratched - Loss in value     |
| 3   | 2nd wheel set           | 2 tyres - Does not meet the leasing specifications - Replace |
| 4   | Boot lid / rear door    | Boot lid - Corrosion - Repair and paint                      |
| 5   | Roof                    | Roof - Stone chips - Paint                                   |
| 6   | Bonnet                  | Bonnet (Steinschläge und Anätzung) - Paint defect - Paint    |
| 7   | Door - front right side | Door - Dent / paintcoat damage - Repair and paint            |

## Wear and tear

| No. | Component group        | Description                       |
|-----|------------------------|-----------------------------------|
| 1   | Door - front left side | Door - Scratch(es) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Previous damages

| No. | Previous damage                                     | Extent of damage (Net) |
|-----|-----------------------------------------------------|------------------------|
| 1   | Rear, Provided by user / customer, from 27 May 2025 | 2.735,80 €             |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres






Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.






Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.





Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.





**Figure 31:** Misc.



**Damage 2:** Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



**Damage 2:** Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



**Damage 3:** 2nd wheel set: 2 tyres - Does not meet the leasing specifications - Replace



**Damage 3:** 2nd wheel set: 2 tyres - Does not meet the leasing specifications - Replace




**Damage 3:** 2nd wheel set: 2 tyres - Does not meet the leasing specifications - Replace





**Damage 3:** 2nd wheel set: 2 tyres - Does not meet the leasing specifications - Replace




**Damage 4:** Boot lid / rear door: Boot lid - Corrosion - Repair and paint



**Damage 4:** Boot lid / rear door: Boot lid - Corrosion - Repair and paint



**Damage 5:** Roof: Roof - Stone chips - Paint



**Damage 5:** Roof: Roof - Stone chips - Paint



**Damage 5:** Roof: Roof - Stone chips - Paint



**Damage 5:** Roof: Roof - Stone chips - Paint



**Damage 5:** Roof: Roof - Stone chips - Paint




**Damage 6:** Bonnet: Bonnet (Steinschläge und Anätzung) - Paint defect - Paint



**Damage 6:** Bonnet: Bonnet (Steinschläge und Anätzung) - Paint defect - Paint




**Damage 6:** Bonnet: Bonnet (Steinschläge und Anätzung) - Paint defect - Paint



**Damage 6:** Bonnet: Bonnet (Steinschläge und Anätzung) - Paint defect - Paint






**Damage 6:** Bonnet: Bonnet (Steinschläge und Anätzung) - Paint defect - Paint



**Damage 7:** Door - front right side: Door - Dent / paintcoat damage - Repair and paint



**Damage 7:** Door - front right side: Door - Dent / paintcoat damage - Repair and paint



**Damage 7:** Door - front right side: Door - Dent / paintcoat damage - Repair and paint