

Vehicle details

VIN	VF7SXYHTU NT507959	Registration date	01/01/1900	Exterior Color	Unknown
Brand	CITROEN	Licence Plate	GF582DL	Odometer	34 738 km
Model	C3				

Inspection Details

Arrival Date	13/07/2026	Inspection ID	7062507	Inspection date	16/07/2026
Assign Date	13/07/2026	Fleet owner	LIZY Belgique	Inspection loc.	Parc Lizy



Generic equipment

Automated air-conditioning	✓
Rain and light sensor	✓
GPS system	✓

Removable element


Spare wheel kit	✓
Emergency compressor kit	✓
Triangle	✓
Safety vest	✓
Rear parcel shelf	✓
Fire extinguisher	✓

Technical Document

Service manual holder	✓
User manual	✓
First aid kit	✓
Certificate of conformity	✓
Title / License document	✓
Spare key	✗

Tyres

205/55/16 V All seasons 7.0 mm



205/55/16 V All seasons 7.0 mm



205/55/16 V All seasons 7.0 mm

205/55/16 V All seasons 7.0 mm

Damages

1



Part	Other bodywork	Repair Time	-	Part Cost	250.00€
Position	-	Repair Cost	-	Gross Cost	250.00€
Damages	Defective	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Repair	Flat Rate	-	Net Cost	250.00€
motor storing					

2



Part	Exterior complete	Repair Time	1.00	Part Cost	-
Position	-	Repair Cost	75.00€	Gross Cost	75.00€
Damages	Stained/dirty	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Cleaning	Flat Rate	75.00€	Net Cost	75.00€

DEKRA Automotive Solutions

3		Part	Turning signal side	Repair Time	0.20	Part Cost	49.82€
		Position	Front right	Repair Cost	15.00€	Gross Cost	64.82€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	64.82€
4		Part	Door	Repair Time	-	Part Cost	-
		Position	Front left	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
5		Part	Wing moulding	Repair Time	0.70	Part Cost	130.51€
		Position	Back left	Repair Cost	52.50€	Gross Cost	183.01€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	183.01€
6		Part	Unpainted bumper	Repair Time	1.00	Part Cost	292.91€
		Position	Back	Repair Cost	75.00€	Gross Cost	367.91€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	367.91€
7		Part	Bumper	Repair Time	2.40	Part Cost	-
		Position	Back	Repair Cost	180.00€	Gross Cost	248.00€
		Damages	Dented	Paint Time	0.80	Depreciation %	-
		Severity	-	Paint cost	68.00€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	248.00€
8		Part	Interior cleaning	Repair Time	0.50	Part Cost	-
		Position	-	Repair Cost	37.50€	Gross Cost	37.50€
		Damages	Stained/dirty	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Cleaning	Flat Rate	37.50€	Net Cost	37.50€
9		Part	Spare key	Repair Time	-	Part Cost	-
		Position	-	Repair Cost	-	Gross Cost	-
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-

Summary Inspection

Gross Price	1,226.24€	Depreciation	-	Net Price	1,226.24€
-------------	-----------	--------------	---	-----------	-----------

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	75.00€	5.80	435.00€	-	-	435.00€
Paintwork	85.00€	0.80	68.00€	-	-	68.00€
Paint preparation	85.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	723.24€	-	-	723.24€
Flat Rate	0.00€	-	-	0.00€

Signatures
Signature Receiver
Signature Expert
Signature Customer / Driver