



Expertise

Protocol number: 46055543  
Order No. / Reference: 26438889  
Inspection date: 19 Jun 2026

Manufacturer: Ford

Model: Kuga 2.5 Duratec FHEV TITANIUM

VIN: WF0FXXWPMHNR62056



| Vehicle details                         |                       |
|-----------------------------------------|-----------------------|
| Manufacturer / Type / Model / Equipment |                       |
| Ford Kuga 2.5 Duratec FHEV TITANIUM     |                       |
| Vehicle Identification number           | WF0FXXWPMHNR62056     |
| Mileage (Read)                          | 99,758 km             |
| First registration                      | 1 Mar 2023            |
| Number of holders                       | 1                     |
| Power / Engine displacement             | 112 kw / 2,488 ccm    |
| Fuel type / Cylinder                    | Hybrid Petrol / E / 4 |
| Gearbox / Number of gears               | Automatic / 1         |
| Type of drive                           | Front drive           |
| Type of vehicle                         | SUV                   |
| Colour / colour code                    | Blazer Blue           |
| Doors / Seats                           | 5 / 5                 |
| Upholstery type                         | Cloth                 |
| Colour of upholstery                    | Black                 |
| Vehicle with smoke odor                 | no                    |



| Vehicle details                              |                              |                         |                                                            |
|----------------------------------------------|------------------------------|-------------------------|------------------------------------------------------------|
| Maintenance booklet / proof                  | Available / complete         | Next maintenance in     | 83 %                                                       |
| Last service on / at                         | 03/2026 at 96,822 km         |                         |                                                            |
| Key is / should be                           | 2 / 2                        | FZG documents           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                              |                              | Letter No.              | GP476055                                                   |
| Previous damage / Accident                   | None detectable              | Repainting              | None detectable                                            |
| Inspection conditions                        | sufficient                   | Lifting equipment / pit | yes                                                        |
| Test drive                                   | Not performed                | Engine function test    | Performed                                                  |
| Manufacturer key number/<br>type code number | 8566 / BUS 00086             |                         |                                                            |
| Emission standard                            | EURO6;WLTP;AP;PI/CI; M, N1 I | fine dust sticker       |                                                            |
| Permitted total weight                       | 2,215 kg                     | Empty weight            |                                                            |

| Tyres            |                 |                             |              |             |
|------------------|-----------------|-----------------------------|--------------|-------------|
| Mounted tyres    |                 |                             |              |             |
| #                | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
| 1)               | 225/65 R17 102H | Winter tyres on Light alloy | Goodyear     | 6mm / 6mm   |
| 2)               | 225/65 R17 102H | Winter tyres on Light alloy | Goodyear     | 6mm / 6mm   |
| Additional tyres |                 |                             |              |             |
| #                | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
| 1)               | 225/65 R17 102V | Summer tyres on Light alloy | Bridgestone  | 3mm / 3mm   |
| 2)               | 225/65 R17 102V | Summer tyres on Light alloy | Bridgestone  | 3mm / 3mm   |
| Replacement      |                 |                             |              |             |
| Typ              | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|                  | Tirefit         | Expiration date 10/2026     |              |             |

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

## Equipment

### Standard equipment

- Acoustic Vehicle Alerting System (AVAS)
- Anti-lock braking system
- Passenger airbag deactivation
- Tires: Tire repair kit
- Fabric headliner
- Roof spoiler
- Tachometer
- Driving mode switch selective
- Electric front and rear windows with all-around closing function
- Ford EcoCoach
- FordPass Connect
- Luggage compartment lighting
- Transmission: continuously variable automatic transmission
- rear window wiper
- Intelligent Protection System (IPS)
- Air conditioning with automatic temperature control
- Front and rear headrests (5) height adjustable
- LED taillights
- Steering column, adjustable in height and reach
- Illuminated makeup mirrors in the driver's and passenger's sun visors
- Navigation system: Ford navigation system including Ford SYNC 3
- Front and rear parking pilot system
- Upholstery: Cloth
- Pre-Collision Assist
- Rear view camera
- Projection lens headlights with LED daytime running lights
- Headlight assistant with day/night sensor
- Seats: Passenger seat, 8-way manually adjustable
- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Front sports seats with integrated headrests
- Carpet floor mats front and rear, velour
- Immobiliser
- Ambient lighting at the front
- Electrically adjustable, heated and folding exterior mirrors
- Tires: 7 J x 17 alloy wheels (4) in 5x2-spoke design
- third brake light
- Roof rails, silver-colored
- 12.3-inch digital instrument panel
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto hold function
- Ford Easy Fuel
- Ford Power Start Function & Ford Key Free System
- Luggage compartment cover, roller blind, removable
- Cruise control
- Illuminated glove compartment
- Heated rear window
- Interior mirror, automatically dimming
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Paint finish: Solid
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- Front center console with integrated armrest
- MyKey key system
- Fog light
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Post-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Headlights with delayed shut-off
- Power steering
- Seats: Driver's seat, 8-way manually adjustable, including adjustable lumbar support
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front seats, individually and variably heated
- Variable radiator air intake
- Central locking with remote control and remote luggage compartment release

### Extra equipment

- Detachable towbar (including ESP trailer stabilization)



## Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |

## Value reducing factors

| No. | Component group | Description                                                         |
|-----|-----------------|---------------------------------------------------------------------|
| 1   | Misc.           | Inspection / maintenance - No evidence - No deduction               |
| 2   | Misc.           | Main inspection - No evidence - No deduction                        |
| 3   | Trim / covers   | Door trim - front left side - dent(s) - Loss in value               |
| 4   | Roof            | Roof - Stone chips - Smart repair                                   |
| 5   | Front bumper    | Spoiler - Scratch(es) - Replace                                     |
| 6   | Rear bumper     | Rear bumper - Scratch(es) - Paint                                   |
| 7   | Bonnet          | Bonnet (+Steinschläge) - Dent / paintcoat damage - Repair and paint |

## Wear and tear

| No. | Component group              | Description                               |
|-----|------------------------------|-------------------------------------------|
| 1   | Vehicle glazing              | Windscreen - Stone chips - No deduction   |
| 2   | Body                         | Body - Scratch(es) - No deduction         |
| 3   | Front bumper                 | Front bumper - Stone chips - No deduction |
| 4   | Side panel - rear right side | Side panel - dent(s) - No deduction       |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Missing parts

### Description

Documents - Owner's manual

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.





**Figure 1:** Diagonal front (left)



**Figure 2:** Diagonal front (right)



**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres





Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.





Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.





Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Damage 3: Trim / covers: Door trim - front left side - dent(s) - Loss in value



Damage 3: Trim / covers: Door trim - front left side - dent(s) - Loss in value





**Damage 3:** Trim / covers: Door trim - front left side - dent(s) - Loss in value



**Damage 4:** Roof: Roof - Stone chips - Smart repair



**Damage 4:** Roof: Roof - Stone chips - Smart repair



**Damage 4:** Roof: Roof - Stone chips - Smart repair



**Damage 4:** Roof: Roof - Stone chips - Smart repair



**Damage 4:** Roof: Roof - Stone chips - Smart repair





**Damage 4:** Roof: Roof - Stone chips - Smart repair



**Damage 5:** Front bumper: Spoiler - Scratch(es) - Replace




**Damage 5:** Front bumper: Spoiler - Scratch(es) - Replace



**Damage 5:** Front bumper: Spoiler - Scratch(es) - Replace



**Damage 6:** Rear bumper: Rear bumper - Scratch(es) - Paint



**Damage 6:** Rear bumper: Rear bumper - Scratch(es) - Paint






**Damage 6:** Rear bumper: Rear bumper - Scratch(es) - Paint



**Damage 7:** Bonnet: Bonnet (+Steinschläge) - Dent / paintcoat damage - Repair and paint




**Damage 7:** Bonnet: Bonnet (+Steinschläge) - Dent / paintcoat damage - Repair and paint



**Damage 7:** Bonnet: Bonnet (+Steinschläge) - Dent / paintcoat damage - Repair and paint



**Damage 7:** Bonnet: Bonnet (+Steinschläge) - Dent / paintcoat damage - Repair and paint



**Damage 7:** Bonnet: Bonnet (+Steinschläge) - Dent / paintcoat damage - Repair and paint