



Expertise

Protocol number: 46324613
Order No. / Reference: 26652653
Inspection date: 2 Jul 2026

Manufacturer: Skoda
VIN: TMBJJ7NX3NY065448

Model: Octavia Combi 2.0 TDI DSG Ambition



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG Ambition	
Vehicle Identification number	TMBJJ7NX3NY065448
Mileage (Read)	160,842 km
First registration	3 Feb 2022
Number of holders	1
Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Black Magic Pearlescent
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Grey-Black



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	13,500 km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG222881
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / AWL 00130		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,990 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92V	Summer tyres on Light alloy	Kumho	4mm / 4mm
2)	205/60 R16 92V	Summer tyres on Light alloy	Kumho	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	Winter tyres on Light alloy	Semperit	5mm / 5mm
2)	205/60 R16 92H	Winter tyres on Light alloy	Hankook	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- Child safety lock for the rear doors and windows
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger and anti-allergen filter & activated carbon filter - air-conditioned and illuminated glove compartment)
- Cruise control system
- Decorative strip in silver square
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Electrically folding exterior mirrors
- Electromechanical power steering
- Electronic parking brake
- Electronic Stability Control (ESC)
- Green tec: Start/stop system including brake energy recuperation
- Grey headliner
- Hill start assist including auto-hold function
- Hydraulic brake assist (HBA)
- Interior mirror automatically dimming
- LED headlights with LED daytime running lights
- LED taillights
- Multifunction display in the instrument cluster
- Radio accessories: 2 USB-C ports on the front
- Radio accessories: 8 speakers
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Voice control
- Rain sensor
- Seat belts (Three three-point seat belts in the rear)
- Seats: Rear seat backrest split 60:40, foldable
- SKODA Care Connect (SOS emergency call function (eCall+ including automatic activation in the event of an accident with airbag deployment) - Mobility service (connection option for rapid assistance in case of breakdown) - Information service (connection option to the hotline for all questions relating to vehicle functions) - Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level)
- Steering wheel: Leather steering wheel with multifunction buttons and paddle shifters (leather steering wheel and gearshift lever with leather elements - infotainment and driver assistance system operation)
- Storage compartments (Four roof grab handles, rear with coat hooks; holder for the warning vest under the driver's seat; storage compartments in the front door panels with 1.5l bottle holders; storage compartments in the rear door panels with 0.5l bottle holders; ticket holder on the windshield; coat hooks on the B-pillars; storage compartments in the doors with felt lining)
- Tachometer
- Tire mobility kit (tire repair spray incl. compressor)
- Traction control (ASR)
- Transmission: 7-speed dual-clutch transmission (DSG)
- 12V socket in the trunk
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Airbag, head airbags
- Anti-lock braking system (ABS)
- Central locking including remote control integrated into the key and EASY Start
- Diesel particulate filter
- Driving light assistant (Coming Home / Leaving Home function)
- Electrically adjustable and heated exterior mirrors
- Electronic transverse differential lock (XDS+)
- Engine drag torque control (MSR)
- Front center armrest, including storage compartment
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Glasses compartment in the headliner
- Headrests (5) front and rear height adjustable
- Heated rear window
- Heated windshield washer nozzles including 5l washer fluid reservoir
- Immobiliser
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Lane keeping assistant (Lane Assist)
- Lashing eyes in the trunk
- LED fog lights
- LED license plate lights
- Manual headlight range adjustment
- Paint finish: Solid
- Phone: Wireless SmartLink for Apple CarPlay
- Radio accessories: Bluetooth hands-free system
- Radio accessories: SmartLink (Apple CarPlay - Android Auto)
- Radio: Bolero music system with capacitive 10" color display
- Rear center armrest with pass-through option
- Rear parking sensors
- Rear window wiper including windshield washer system
- Removable boot cover
- Roof rails, black
- Seats: Height-adjustable driver and passenger seats (including lumbar support)
- Speed limiter
- Steering wheel: height and reach adjustable
- Storage compartment in the luggage compartment with cargo element
- Third brake light
- Tinted windows
- Tire pressure monitoring
- Wheels: 16" alloy wheels Twister AERO (7J x 16, ET 46 with tires 205/60 R16)



- Upholstery: Cloth

Extra equipment

- Swiveling trailer hitch including trailer stabilization and adapter
- Steering wheel: Heated steering wheel including heated front seats
- Package: Travel (DSG) (Traveller assistance system: - Traffic sign recognition - Predictive and adaptive cruise control (pACC) - Adaptive lane keeping assist - Emergency and traffic jam assist - Capacitive steering wheel with hands-off detection - Adaptive cruise control (ACC) (control range 210 km/h) - Driver fatigue detection - Driving profile selection - Automatically dimming exterior mirror (driver's side))
- Luggage net partition
- Paint finish: Pearl effect
- Package: Columbus infotainment package (Columbus navigation system - Infotainment Online (3-year subscription) - Digital instrument cluster (Virtual Cockpit) - Phonebox - KESSY (Keyless entry and start-stop system))
- 230V socket and USB charging port (230V socket and 2 x USB charging ports in the rear as well as USB charging port in the rearview mirror)
- Sunset (rear window and rear side windows tinted dark)
- Heated windscreen
- 1 set of winter wheels 16 inch alloy Borbet Octavia IV

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Braking system	Brake fluid - No evidence - No deduction
2	Misc.	Inspection / maintenance - No evidence - No deduction
3	Equipment	Tirefit filler - Expired - Replace
4	Door - front left side	Door edge - Scratch(es) - Smart repair
5	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
6	Equipment	Vehicle key - Loose - Loss in value
7	Bonnet	Radiator grille - Broken / torn - Replace
8	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Side panel - rear left side	Side panel - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Documents - Service book (Digitaler Ausdruck)



Repainting

No. Repainting

1 Bonnet, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Bonnet 351 µm |

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.




Damage 3: Equipment: Tirefit filler - Expired - Replace



Damage 4: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 4: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 5: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise




Damage 5: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 6: Equipment: Vehicle key - Loose - Loss in value




Damage 6: Equipment: Vehicle key - Loose - Loss in value




Damage 7: Bonnet: Radiator grille - Broken / torn - Replace




Damage 7: Bonnet: Radiator grille - Broken / torn - Replace




Damage 7: Bonnet: Radiator grille - Broken / torn - Replace



Damage 8: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 8: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 8: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 8: Vehicle glazing: Windscreen - Stone chips - Replace



Repainting 1: Bonnet



Repainting 1: Bonnet