



Expertise

Protocol number: 46376166
Order No. / Reference: 26653128
Inspection date: 6 Jul 2026

Manufacturer: Citroën

Model: C5 Aircross Hybrid 136 ë-DSC6 MAX

VIN: VR7ARHPYEPL061685



Vehicle details

Manufacturer / Type / Model / Equipment

Citroën C5 Aircross Hybrid 136 ë-DSC6 MAX

Vehicle Identification number	VR7ARHPYEPL061685
Mileage (Read)	28,432 km
First registration	11 Apr 2024
Number of holders	1
Next periodical technical inspection	04/2027
(Report not on hand)	

Power / Engine displacement	100 kw / 1,199 ccm
Fuel type / Cylinder	Hybrid Petrol / E / 4
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	SUV

Colour / colour code	Polar-Weiß
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black

readiness to drive	Roadworthy
--------------------	------------



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	-1,000 km
Last service on / at	06/2025 at 16,231 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ733379
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1889 / AHF 00005		
Emission standard	EURO6;WLTP;EA;PI/CI;M, N1, N2	fine dust sticker	
Permitted total weight	2,050 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R19 97W	All-season tyres on Light alloy	Sonstige	5mm / 5mm
2)	205/55 R19 97W	All-season tyres on Light alloy	Sonstige	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Airbag: Driver and passenger side
- Airbag: Front side airbags
- Automatic headlight activation and windscreen wipers with rain sensor, Macis Wash
- Hill start assist
- On-board computer
- Tachometer
- Electric parking brake
- Chassis: CITROËN ADVANCED Comfort suspension
- Electric windows front and rear (with one-touch operation)
- Transmission: 6-speed dual-clutch transmission
- rear window wiper
- Interior mirror automatically dimming
- Keyless system
- Automatic climate control with separate settings for driver/passenger (including Air Quality System (activated carbon filter))
- Paintwork: Bi-tone (roof painted in body color Perla Nera Black Metallic)
- Steering wheel: Steering wheel covered in split leather
- My CITROËN Assist (Emergency Call and Assistance System)
- Fog lights with static cornering lights
- Otto particulate filter
- Package: Parking Package (front and rear parking aid - reversing camera with Top Rear Vision)
- Package: Style package in matte chrome (Airbump with matte chrome surround on the first capsule - matte chrome trim on the front bumper)
- Upholstery: Ambiente Metropolitan Grey (Advanced Comfort Seats - Alcantara/-artificial leather seats in grey / black)
- Tire pressure monitoring system
- Front side windows with laminated glass
- Seat belts: Three-point harnesses on all seats (height adjustable in the front)
- Seats: Driver's seat with lumbar support
- Immobiliser
- Central locking with remote control
- Airbag: Front and rear head airbags (except rear center)
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD) and brake assist
- Electrically adjustable, heated and electrically folding exterior mirrors
- Display: 31-cm/12.3-inch digital instrument cluster
- Third brake light
- Electronic Stability Program (ESP) with Traction Control (ASR)
- Speed controller active and speed limiter
- Rear and side windows tinted darker
- Heated rear window
- Isofix child seat attachments on the front passenger seat and rear seat row
- Height-adjustable boot floor panel
- Front headrests (2)
- Rear headrests (3)
- Paint finish: Metallic Okenite White
- LED headlights with LED daytime running lights
- Engine start/stop button
- Navigation: My Citroën Drive (CITROËN Connect audio system with DAB - Citroën Connect navigation system - 25-cm/10" touchscreen - Integrated European map - Mirror Screen function - Real Time Traffic navigation - Bluetooth hands-free system)
- Package: Safety Package 3 (automatic and dual-clutch transmission) (Active cruise control and limiter with stop and start function for EAT8 - Attention Assist - Traffic sign recognition Plus - High beam assist - Active emergency braking assist (camera & sensor controlled) - Blind spot assist - Coffee break alert - Collision warning - Active lane keeping assist)
- Wheels: Tire repair kit
- Power steering
- Seats: 3 individual seats in the second row (adjustable in length (150 mm) and foldable onto the vehicle floor)
- Seats: Driver's seat/passenger seat adjustable in length, height and tilt

Extra equipment

- Upholstery: Ambiente Hype Black (Advanced Comfort seats - leather - electric driver's seat adjustment with memory function - including ventilated massage function - including seat heating for driver and front passenger as well as rear seat heating - including 2-way adjustable front headrests and footwell lighting - including front and rear floor mats)
- All-weather tires
- Continuous power outlet
- Package: Full Black (Style package in glossy black - 19" alloy wheels in black - roof rails bi-tone black/matte black)
- Rubber floor mats
- Warning marking DIN



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Wheel well extension - Scratch(es) - Replace
2	Wing mirror - left side	Cap - Scratch(es) - Paint
3	Body	Body - Glued / labelled - De-glue / neutralise
4	Misc.	Inspection / maintenance - Due - Perform
5	Rear bumper	Spoiler - Scratch(es) - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Documents




Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Damage 1: Side panel - rear left side: Wheel well extension - Scratch(es)
- Replace



Damage 1: Side panel - rear left side: Wheel well extension - Scratch(es)
- Replace



Damage 2: Wing mirror - left side: Cap - Scratch(es) - Paint



Damage 2: Wing mirror - left side: Cap - Scratch(es) - Paint



Damage 3: Body: Body - Glued / labelled - De-glue / neutralise



Damage 3: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Misc.: Inspection / maintenance - Due - Perform



Damage 5: Rear bumper: Spoiler - Scratch(es) - Replace



Damage 5: Rear bumper: Spoiler - Scratch(es) - Replace