



Expertise

Protocol number: 46543964
Order No. / Reference: 26603030
Inspection date: 14 Jul 2026

Manufacturer: Peugeot

Model: 508 SW Hybrid 225 e-EAT8 Allure

VIN: VR3F4DGZTMY503369



Vehicle details

Manufacturer / Type / Model / Equipment

Peugeot 508 SW Hybrid 225 e-EAT8 Allure

Vehicle Identification number VR3F4DGZTMY503369
Mileage (Read) 84,080 km
First registration 31 May 2021
Number of holders 1
Next periodical technical inspection 06/2026
(Report on hand)

Power / Engine displacement 133 kw / 1,598 ccm
Fuel type / Cylinder Hybr.B/E ext.aufll / 4
Gearbox / Number of gears Automatic / 8
Type of drive Front drive
Type of vehicle Station wagon

Colour / colour code Celebes Blau Metallic
Doors / Seats 5 / 5
Upholstery type Cloth / leather combination
Colour of upholstery Black-Dark grey

Re-import no
readiness to drive Not roadworthy / moveable



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	9,400 km
Last service on / at	08/2025 at 63,510 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FX942399
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	1889 / ABZ 00014		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,290 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98W	Summer tyres on Light alloy	Goodyear	5mm / 5mm
2)	215/55 R17 98W	Summer tyres on Light alloy	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS (Anti-lock Braking System)
- Airbag for driver and front passenger
- Airbag: Curtain airbags front and rear
- Electrically adjustable, heated and folding exterior mirrors
- Illuminated glove compartment
- Turn signals with lane change indicator function
- third brake light
- Aluminum roof rails
- Digital instrument cluster with high-resolution 12.3" screen, adjustable and customizable
- EBV (Electronic Brakeforce Distribution)
- Front parking aid, acoustic and visual
- Electric windows front and rear
- electric parking brake
- Front collision warning
- luggage compartment roller blind
- Transmission: 8-speed automatic transmission EAT8
- Seat belts: 3-point safety belts in all seats
- Heated rear window
- Rear apron with diffuser look in black
- Interior mirror automatically dimming
- Keyless system
- Automatic climate control (2-zone)
- Radiator grille with chrome applications
- Charging cable: Mode 2 charging cable (Type 2, up to 1.8 kW), 6 meters long
- "Merion" 17" alloy wheels
- light sensor
- makeup mirror
- front center armrest
- Multimedia: Mirror Screen
- Navigation system: 3D navigation system NAC
- On-board charger 3.7 kW, 1-phase
- Break warning
- Radio: RCC audio system
- Rain sensor
- Wheels: Tire repair kit (compressor + tire sealant spray)
- Split and automatically folding rear seat backrest (40/60)
- Electric power steering
- Seats: Driver's seat height adjustable
- Lane keeping assist with steering intervention
- Technical Plug-In Hybrid Version
- Immobiliser
- Active Safety Brake Plus
- Airbag: Side airbag
- Active Blind Spot Assist
- Exterior mirrors painted in car color
- Hill start assist
- On-board computer
- Chrome trim strips on the side windows
- Decorative inlays in carbon look
- Dual exhaust with chrome-plated tailpipes
- Tachometer
- Rear parking aid, acoustic and visual
- Electronic Stability Program (ESP)
- High beam assist
- Follow-me-home function (automatic)
- front and rear floor mats
- Cruise control system with speed limiter
- Cup holder in the center console
- Halogen headlights
- Rear window and side windows in the second row are more heavily tinted.
- Map pockets on the front seatbacks
- Child safety lock at the rear
- Height-adjustable headrests
- Paint finish: Celebes Blue
- LED ceiling lighting at the front
- LED daytime running lights
- Steering wheel: Small multifunction steering wheel, flattened at the top and bottom.
- Rear center armrest with pass-through flap
- Multifunctional touchscreen
- Fatigue warning
- Emergency brake assist
- Particle filter: OPF (Otto particulate filter)
- Upholstery: Fabric/faux leather
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system
- Reversing camera with 180° surround view
- paddle shifters on the steering wheel
- Seats: Passenger seat height adjustable
- Seats: Electric lumbar support
- Stop&Start system
- Traffic sign recognition
- Central locking can be activated from inside using a remote control.



Extra equipment

- Mechanically swiveling towbar with ball head
- luggage compartment partition net
- Package: Full LED package (Full LED headlights with headlight range control - Full LED taillights with 3D effect - LED turn signals with static cornering lights)
- Adaptive Cruise Control (ACC) with Stop & Go function (including lane positioning assistant)
- Warning triangle

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Instrument panel	Indicator light (Reifendruck) - on - Perform diagnosis
3	Roof	Roof - dent(s) - Smooth repair work
4	Rear bumper	Rear bumper (Lacknebel+kratzer) - Scratched - Smart repair
5	Misc.	Main inspection - Due - Perform
6	Equipment	charging cable (nicht für Haushaltssteckdosen (Schuko) geeignet) - Differs from the original configuration - Replace
7	Sill - right side	Sill - Dent / paintcoat damage - Repair and paint
8	Front bumper	Front bumper - Scratched - Paint
9	Door - rear right side	Door - Scratched - Paint
10	Side panel - rear right side	Side panel - Scratch(es) - Paint
11	Door - front left side	Door - Dent / paintcoat damage - Repair and paint
12	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 10 Oct 2025	3.549,16 €
2	Front, Provided by user / customer, from 30 Dec 2021	7.462,23 €

Repainting

No.	Repainting
1	Mudguard - left side, Mudguard - right side, Door - rear left side



Paint coat thickness measurement

Mudguard - left side	264 µm	Mudguard - right side	146 µm
Door - rear left side	163 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Wartungshistorie gemäß Auftraggeber Informationen.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.





Figure 34: Misc.




Figure 35: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace




Damage 2: Instrument panel: Indicator light (Reifendruck) - on - Perform diagnosis



Damage 3: Roof: Roof - dent(s) - Smooth repair work




Damage 3: Roof: Roof - dent(s) - Smooth repair work




Damage 4: Rear bumper: Rear bumper (Lacknebel+kratzer) - Scratched - Smart repair



Damage 4: Rear bumper: Rear bumper (Lacknebel+kratzer) - Scratched - Smart repair



Damage 4: Rear bumper: Rear bumper (Lacknebel+kratzer) - Scratched - Smart repair



Damage 5: Misc.: Main inspection - Due - Perform



Damage 6: Equipment: charging cable (nicht für Haushaltssteckdosen (Schuko) geeignet) - Differs from the original configuration - Replace



Damage 7: Sill - right side: Sill - Dent / paintcoat damage - Repair and paint



Damage 7: Sill - right side: Sill - Dent / paintcoat damage - Repair and paint




Damage 7: Sill - right side: Sill - Dent / paintcoat damage - Repair and paint




Damage 7: Sill - right side: Sill - Dent / paintcoat damage - Repair and paint



Damage 8: Front bumper: Front bumper - Scratched - Paint



Damage 8: Front bumper: Front bumper - Scratched - Paint



Damage 8: Front bumper: Front bumper - Scratched - Paint



Damage 8: Front bumper: Front bumper - Scratched - Paint




Damage 9: Door - rear right side: Door - Scratched - Paint



Damage 9: Door - rear right side: Door - Scratched - Paint




Damage 9: Door - rear right side: Door - Scratched - Paint



Damage 10: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 10: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 10: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 10: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 11: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 11: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Repainting 1: Mudguard - left side, Mudguard - right side, Door - rear left side



Repainting 1: Mudguard - left side, Mudguard - right side, Door - rear left side



Repainting 1: Mudguard - left side, Mudguard - right side, Door - rear left side



Repainting 1: Mudguard - left side, Mudguard - right side, Door - rear left side



Repainting 1: Mudguard - left side, Mudguard - right side, Door - rear left side



Repainting 1: Mudguard - left side, Mudguard - right side, Door - rear left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VR3F4DGZTMY503369

Hersteller / Modell: PEUGEOT PEUGEOT 508 SW Hybrid e-EAT8 Allure

Datum	KM-Stand	Beschreibung
26.08.2025	63.510	Bremsflüssigkeit; Bremsflüssigkeit ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
16.04.2025	59.700	Systemtest/Eigendiagnose
06.06.2024	57.357	AU; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
11.09.2023	47.940	Bremsflüssigkeit; Bremsflüssigkeit ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
23.08.2022	41.055	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
22.12.2021	21.836	Bremsklötze hinten; Bremsscheiben + Klötze v; Bremsscheiben hinten