



Expertise

Protocol number: 46362133
Order No. / Reference: 26201312
Inspection date: 7 Jul 2026

Manufacturer: CUPRA

Model: Born 150kW/58kWh

VIN: VSSZZK11RP018419



Vehicle details

Manufacturer / Type / Model / Equipment

CUPRA Born 150kW/58kWh

Vehicle Identification number VSSZZK11RP018419

Mileage (Read) 43,955 km

First registration 2 Apr 2024

Number of holders 1

Next periodical technical inspection 04/2027
(Report not on hand)

Power / Engine displacement 70 kw / 0 ccm

Fuel type / Cylinder Electric / 0

Gearbox / Number of gears Direct drive / 1

Type of drive Rear drive

Type of vehicle Saloon car

Colour / colour code Vapor Grey

Doors / Seats 5 / 5

Upholstery type Cloth

Colour of upholstery Black-Grey



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	-100 Tag(e)
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY930848
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	7593 / ASO 00024		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,280 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R18 99V	All-season tyres on Light alloy	Kumho	5mm / 5mm
2)	215/55 R18 99V	All-season tyres on Light alloy	Kumho	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • Airbag: Airbag for driver and front passenger • Airbag: Head airbag system, front and rear • Exterior mirrors: aspherical on driver's side, convex on passenger's side • third brake light • CCS charging socket • CUPRA e-Sound • CUPRA side skirts in Liquid Grey • decorative elements • Electronic Stability Control (ESC) • Luggage compartment lighting • Speed limiter • rear window wiper • Rear bumper and diffuser in body color • High-voltage battery warranty 8 years or maximum 160,000 km, with 70% Abattery power • Keyless Go (engine start/stop button) • Air conditioning: Climatronic with electronic temperature control • Paint finish: Solid • Steering wheel: CUPRA Supersport multifunction steering wheel in leather • Center console with integrated storage compartment and cup holders • Progressive steering • Rain sensor • Wheels: CYCLONE 7.5J x 18" alloy wheels • Seats: 3 rear seats, rear seat backrest asymmetrically split and foldable • Sun visors with illuminated makeup mirror • Lane departure warning system • Front bumper in body color • Front Assist area monitoring system with City Emergency Braking function | <ul style="list-style-type: none"> • Airbag: Passenger airbag deactivation • Ambient lighting in the front door panel • Electrically adjustable, folding and heated exterior mirrors • Exterior mirror housing in Liquid Grey • C-pillar with CUPRA design element • CUPRA Drive Profile • CUPRA lettering on tailgate • Black headliner • Electronic parking brake including auto-hold function • Electric window regulator with anti-pinch protection and one-touch function • Transmission: 1-speed automatic • Rear spoiler in car color • Manufacturer's warranty: 5 years or up to 150,000 km • Interior mirror automatically dimming • ISOFIX child seat restraint system, in the 2nd row of seats left and right as well as on the front passenger seat • Headrests, 2 front • Headrests, 3 rear • Mode 3 Type 2 charging cable, 16 A • Lights: Full headlights • front center armrest • Fatigue detection • Emergency call service • Radio: Radio, navigation and multimedia systems • Tire pressure monitoring system • Seat belts - front and rear • Seats: CUPRA sports bucket seats in the front • Seats: Driver's seat with height adjustment • Sport pedals in aluminum look • 12V socket in the luggage compartment • Ultrasonic parking aid front and rear • Electronic immobilizer • thermal insulation glazing |
|--|---|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Misc.	Inspection / maintenance - Due - Perform

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Door - rear left side	Door - Scratch(es) - No deduction
4	Door - rear left side	Strip - outer - Scratch(es) - No deduction
5	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Damage 2: Misc.: Inspection / maintenance - Due - Perform



Wear and tear 3: Door - rear left side: Door - Scratch(es) - No deduction



Wear and tear 3: Door - rear left side: Door - Scratch(es) - No deduction