



Expertise

Protocol number: 46674065
Order No. / Reference: 26656762
Inspection date: 23 Jul 2026

Manufacturer: Ford	Model: Transit Custom Kombi 300 L1H1 LKW VA Trend
VIN: WF0ZXXTTGZNP05181	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Transit Custom Kombi 300 L1H1 LKW VA Trend	
Vehicle Identification number	WF0ZXXTTGZNP05181
Mileage (Read)	153,399 km
First registration	10 Oct 2022
Number of holders	1
Next periodical technical inspection	10/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frost-Weiß
Doors / Seats	4 / 6
Upholstery type	Cloth
Colour of upholstery	Black
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	7,000 km
Last service on / at	10/2025 at 120,156 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP438992
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BMU 08043		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	3,000 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R15 104T	Summer tyres on Steel rim with wheel cover	Goodyear	5mm / 5mm
2)	215/65 R15 104T	Summer tyres on Steel rim with wheel cover	Continental	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R15 104T	Winter tyres on Steel	Semperit	4mm / 4mm
2)	215/65 R15 104T	Winter tyres on Steel	Semperit	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R15 104T C	Summer tyres on Steel	Goodyear	9 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, flat
- Tachometer
- Electronic Stability Program (ESP) with Traction Control System (TCS)
- Ford Easy Fuel
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Transmission: 6-speed transmission
- Lockable glove compartment with lid
- Front air conditioning
- Paint finish: Solid color paint
- Steering column, adjustable in height and reach
- Package: Style-Color Package
- Particulate filter: diesel particulate filter
- Wheels/Tires: Spare wheel, steel wheel
- Headlights: Halogen projector headlights
- Sliding door: Sliding door, right
- Mud flaps front and rear
- Half-height side wall cladding
- Seat belts
- Seats: Seat package 13 - (Custom DOKA Trend)
- Power outlet: 12-volt connection
- Immobiliser
- Central locking with remote control
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer
- Headliner in driver's cab
- Third brake light
- Windows, 2nd row: Side windows fixed, right and left
- Front electric windows
- FordPass Connect
- Generator, 240 A
- Cruise control including imitation leather steering wheel
- Grab handle on the B-pillar of the passenger side
- Interior lighting with delay circuit
- Fuel tank 70 l
- Cargo area lighting with activatable switch-off delay
- Emergency brake assist including emergency brake light
- Front and rear parking pilot system including fog lights
- Wheel trims
- Wheels: Steel wheels 6.5 J x 15 with 215/65 R 15 tires
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Seats: 2nd row, 3-seater bench
- Start-stop system
- Lashing eyes 4
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric

Extra equipment

- Airbag (passenger side)
- BOTT: DEK006H0003928-02
- Rear swing door without window (without interior mirror)
- Radio: Audio system 25: Ford audio system including Ford SYNC 3 with AppLink, DAB/DAB+, navigation (Radio (FM/AM) 8" touchscreen multifunction display, FordPass Connect integrated control panel and audio remote control, Ford SYNC 3 with touchscreen (hands-free system with voice control, SMS readout/sending function, Bluetooth, Emergency Assistance...), AppLink (advanced voice control, privacy mode, support for Android Auto and Apple CarPlay, capacitive touchscreens...), lane guidance, adaptive cruise control, lane keeping assist, traffic sign recognition, Park Pilot front/rear)
- Towing device (fixed, 13-pin socket - incl. trailer stability control (TSC))
- Package: Visibility Package II (Trend) (Heated windscreen - Electrically folding exterior mirrors - Adjustable instrument lighting - Windscreen wipers with rain sensor - Headlight assistant with day/night sensor)
- Tire Pressure Monitoring System (TPMS)
- Reversing camera (reversing camera with image transmission of the rear driving path in the multifunction display and coupling aid)
- Programmable auxiliary heater (fuel-operated auxiliary heater including 2 batteries)
- Blind spot assist including cross traffic alert and trailer function (electrically adjustable and heated exterior mirrors, also electrically foldable)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - rear left side - Scratch(es) - Replace
2	Wheel / tyres	Wheel cover - front right side - Scratch(es) - Replace
3	Electronic systems	Parking assistance - on - Perform diagnosis
4	Door - front left side	Door - Scratched - Smart repair
5	Boot lid / rear door	Boot lid - Corrosion - Smart repair
6	Trim / covers	Boot lid - interior trim - Broken / torn - Replace
7	Roof	Roof - Corrosion - Paint

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Wheel arch - dent(s) - No deduction
2	Side panel - rear left side	Wheel arch - dent(s) - No deduction
3	Documents	Log book (Mappe) - Missing - Replace
4	2nd wheel set	2 tyres (WR) - Worn - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, Provided by user / customer, from 10 Mar 2023	3.392,09 €

Repainting

No.	Repainting
1	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side	206 µm
------------------------------	--------



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Wartungshistorie gemäß Auftraggeber Informationen.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN




Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Damage 1: Wheel / tyres: Wheel cover - rear left side - Scratch(es) - Replace



Damage 1: Wheel / tyres: Wheel cover - rear left side - Scratch(es) - Replace



Damage 2: Wheel / tyres: Wheel cover - front right side - Scratch(es) - Replace



Damage 2: Wheel / tyres: Wheel cover - front right side - Scratch(es) - Replace




Damage 3: Electronic systems: Parking assistance - on - Perform diagnosis



Damage 4: Door - front left side: Door - Scratched - Smart repair



Damage 4: Door - front left side: Door - Scratched - Smart repair



Damage 5: Boot lid / rear door: Boot lid - Corrosion - Smart repair



Damage 5: Boot lid / rear door: Boot lid - Corrosion - Smart repair



Damage 6: Trim / covers: Boot lid - interior trim - Broken / torn - Replace



Damage 6: Trim / covers: Boot lid - interior trim - Broken / torn - Replace



Damage 7: Roof: Roof - Corrosion - Paint



Damage 7: Roof: Roof - Corrosion - Paint



Damage 7: Roof: Roof - Corrosion - Paint



Wear and tear 1: Side panel - rear right side: Wheel arch - dent(s) - No deduction



Wear and tear 1: Side panel - rear right side: Wheel arch - dent(s) - No deduction




Wear and tear 2: Side panel - rear left side: Wheel arch - dent(s) - No deduction



Wear and tear 2: Side panel - rear left side: Wheel arch - dent(s) - No deduction



Wear and tear 4: 2nd wheel set: 2 tyres (WR) - Worn - No deduction



Wear and tear 4: 2nd wheel set: 2 tyres (WR) - Worn - No deduction



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side



Side panel - rear right side: 206 μm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0ZXXTTGZNP05181

Hersteller / Modell: FORD FORD Transit Custom 300 L1H1 LKW VA Trend

Datum	KM-Stand	Beschreibung
29.04.2026	146.360	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Systemtest/Eigendiagnose
17.04.2026	145.185	Batterie ern; Systemtest/Eigendiagnose
15.10.2025	120.156	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
14.07.2025	108.375	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
15.01.2025	83.264	Bremsflüssigkeit; Bremsflüssigkeit ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
18.10.2024	71.693	HU + AU
24.06.2024	54.131	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten
27.02.2024	41.339	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst