



Expertise

Protocol number: 46595320
Order No. / Reference: 26546944
Inspection date: 15 Jul 2026

Manufacturer: Ford

Model: e-Transit 350 L3H3 Lkw HA Basis

VIN: WF0EXXTTRBPL59215



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford e-Transit 350 L3H3 Lkw HA Basis	
Vehicle Identification number	WF0EXXTTRBPL59215
Mileage (Read)	55,217 km
First registration	31 Jul 2023
Number of holders	1
Fuel type	Electric
Power	100 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	
Key is / should be	3 / 3	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT924614
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BWL 00063		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 121R	All-season tyres on Steel rim with wheel cover	Barum	7mm / 7mm
2)	235/65 R16 121R	All-season tyres on Steel rim with wheel cover	Barum	8mm / 8mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Assembly Express Line Package

- Single airline points sliding door / B-pillar incl. Mo

Standard equipment

- 1 battery
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated (with integrated turn signals)
- Battery: Battery life, programming of battery life to 10 minutes
- On-board computer (with fuel consumption and mileage information (e.g. remaining range) as well as outside temperature display and Ford ECO mode)
- Double-leaf rear door with 180° opening angle (without window)
- Front electric windows (with quickdown/up function for driver's side)
- Heated windshield
- generator
- Transmission: 1-speed direct drive
- Interior lighting with delay circuit
- Paint finish: Solid color paint
- Charging cable for public charging station (Type 2) (8 m "Mennekes" charging cable (32 Amp) (Mode 3 / Type 2))
- Cargo area lighting
- Steering column, adjustable in height and reach
- MyKey key system (individually programmable secondary key)
- Wheels: Wheel hub covers
- Wheels: Tire repair kit
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Sliding door: Sliding door, right
- Rear mud flaps
- Power steering
- Seats: Seat Package 9 (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated tray in the double passenger seat (foldable) - Heated driver's seat - Heated passenger seat - Interior armrest for driver - Manually adjustable lumbar support in driver's seat - BASIC seat cover: fabric)
- Front overhead storage compartment
- Increased axle load (front to 1850 kg)
- Anti-lock braking system (ABS) with electronic brake-force distribution (EBD) (Electronic safety and stability program (ESP) with traction control (TCS) - Hill start assist - Crosswind assist - Safety brake assist - Rollover protection - Emergency brake support including emergency brake light - additionally with trailer stabilization only in conjunction with trailer hitch (extra charge))
- roof, high
- Tachometer
- Third brake light
- Electronic parking brake
- Ford Power Start function (keyless start)
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Glove compartment with lid
- Automatic climate control (front air conditioning - Ford audio system with 12" multifunction display and Ford SYNC 4 - Radio, DAB/DAB+ - FordPass Connect including live traffic information, Wi-Fi hotspot - Steering wheel audio controls - Bluetooth, USB port, hands-free system - Emergency call assistant - AppLink, supports Android Auto and Apple CarPlay - Touchscreen - Integration of storage media (e.g., USB sticks or MP3 players) - Voice control of various telephony functions and music playback - Extended voice control)
- Headlight low beam: Halogen headlights with daytime running lights
- Side protection strips
- Seat belts (front seat belt tensioners and force limiters - warning system for unfastened driver's seat belt)
- Rear bumper with integrated step
- front bumper
- Partition wall (plastic) at the height of the B-pillar
- Lashing eyes
- Immobiliser
- Heat-insulating glazing, lightly tinted
- Central locking with remote control (2 keys, one of which has a remote control)

Extra equipment

- Airbag (passenger side)
- Double-wing rear doors with a 256° opening angle, (without windows) (without rear windows, with holding magnets)
- Exterior mirrors, electrically adjustable, heated and folding (with integrated turn signals)
- LED lights in the cargo area
- Package: Technology Package 6 (Front and rear parking sensors - Fog lights - Ford audio system with 12" multifunction display and Ford SYNC4 - Cruise control - Rearview camera with image transmission of the driving path behind in the multifunction display [additionally with coupling aid in conjunction with trailer hitch (extra charge)] - LED downlight)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Missing - Replace
2	Boot lid / rear door	Rear door - left side - dent(s) - Smooth repair work
3	Front bumper	Front bumper - Scratch(es) - Loss in value
4	Seat - front	Seat cover - right side - Holes - Smart repair
5	Body	Body - Glued / labelled - De-glue / neutralise
6	Door - front left side	Door (Zusätzlich Blende Kratzer) - Dent / paintcoat damage - Repair and paint
7	Side panel - rear left side	Side panel (Zusätzlich Blende Kratzer) - Deformed - repair according to calculation
8	Roof	Roof (beschädigt) - Corrosion - repair according to calculation

Wear and tear

No.	Component group	Description
1	Sill - left side	Sill - Scratch(es) - No deduction
2	Sliding door, right	Sliding door - dent(s) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Side panel - rear right side	Wheel well extension - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Roof - Stub aerial

Equipment - Tirefit complete

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Professionally repaired	
2	Side right, Professionally repaired	

Repainting

No. Repainting

- Side panel - rear left side, Side panel - rear right side, Door - rear right side, Professionally carried out



Paint coat thickness measurement

Side panel - rear left side	173 µm	Side panel - rear right side	2,920 µm
Door - rear right side	355 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Damage 2: Boot lid / rear door: Rear door - left side - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Rear door - left side - dent(s) - Smooth repair work



Damage 3: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 3: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 3: Front bumper: Front bumper - Scratch(es) - Loss in value




Damage 3: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 3: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 3: Front bumper: Front bumper - Scratch(es) - Loss in value



Damage 4: Seat - front: Seat cover - right side - Holes - Smart repair



Damage 4: Seat - front: Seat cover - right side - Holes - Smart repair



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 6: Door - front left side: Door (Zusätzlich Blende Kratzer) - Dent / paintcoat damage - Repair and paint



Damage 6: Door - front left side: Door (Zusätzlich Blende Kratzer) - Dent / paintcoat damage - Repair and paint



Damage 6: Door - front left side: Door (Zusätzlich Blende Kratzer) - Dent / paintcoat damage - Repair and paint




Damage 6: Door - front left side: Door (Zusätzlich Blende Kratzer) - Dent / paintcoat damage - Repair and paint



Damage 6: Door - front left side: Door (Zusätzlich Blende Kratzer) - Dent / paintcoat damage - Repair and paint



Damage 6: Door - front left side: Door (Zusätzlich Blende Kratzer) - Dent / paintcoat damage - Repair and paint



Damage 6: Door - front left side: Door (Zusätzlich Blende Kratzer) - Dent / paintcoat damage - Repair and paint



Damage 6: Door - front left side: Door (Zusätzlich Blende Kratzer) - Dent / paintcoat damage - Repair and paint



Damage 6: Door - front left side: Door (Zusätzlich Blende Kratzer) - Dent / paintcoat damage - Repair and paint




Damage 7: Side panel - rear left side: Side panel (Zusätzlich Blende Kratzer) - Deformed - repair according to calculation



Damage 7: Side panel - rear left side: Side panel (Zusätzlich Blende Kratzer) - Deformed - repair according to calculation



Damage 7: Side panel - rear left side: Side panel (Zusätzlich Blende Kratzer) - Deformed - repair according to calculation



Damage 7: Side panel - rear left side: Side panel (Zusätzlich Blende Kratzer) - Deformed - repair according to calculation




Damage 7: Side panel - rear left side: Side panel (Zusätzlich Blende Kratzer) - Deformed - repair according to calculation



Damage 7: Side panel - rear left side: Side panel (Zusätzlich Blende Kratzer) - Deformed - repair according to calculation



Damage 7: Side panel - rear left side: Side panel (Zusätzlich Blende Kratzer) - Deformed - repair according to calculation



Damage 7: Side panel - rear left side: Side panel (Zusätzlich Blende Kratzer) - Deformed - repair according to calculation



Damage 7: Side panel - rear left side: Side panel (Zusätzlich Blende Kratzer) - Deformed - repair according to calculation



Damage 8: Roof: Roof (beschädigt) - Corrosion - repair according to calculation



Damage 8: Roof: Roof (beschädigt) - Corrosion - repair according to calculation



Damage 8: Roof: Roof (beschädigt) - Corrosion - repair according to calculation



Damage 8: Roof: Roof (beschädigt) - Corrosion - repair according to calculation



Damage 8: Roof: Roof (beschädigt) - Corrosion - repair according to calculation



Damage 8: Roof: Roof (beschädigt) - Corrosion - repair according to calculation



Missing part 1: Roof: Stub aerial - Missing - Replace




Missing part 2: Equipment: Tirefit complete - Missing - Replace



Repainting 1: Side panel - rear left side, Side panel - rear right side,
Door - rear right side



Repainting 1: Side panel - rear left side, Side panel - rear right side,
Door - rear right side




Repainting 1: Side panel - rear left side, Side panel - rear right side,
Door - rear right side



Repainting 1: Side panel - rear left side, Side panel - rear right side,
Door - rear right side



Repainting 1: Side panel - rear left side, Side panel - rear right side,
Door - rear right side



Repainting 1: Side panel - rear left side, Side panel - rear right side,
Door - rear right side