


2-FHA-993

2-FHA-993 · ST Line 1.0i EcoBoost 125pk M6 · 6 August 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FHA-993	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF02XXERK2RA32640
Model	Puma	Cylinder Capacity	999 ^{cm3}
Model Versions	ST Line 1.0i EcoBoost 125pk M6	Transmission Type	Handmatig geschakelde transmissie
		First Admission	07-05-2024
Body Type	5 door hatchback	Odometer	77.360 ^{Km}
Color	Black	Numer Of Keys	2
Paint Type	Metallic	Interior	Black
Production Year	2024	Number Headrests	5
KW	92		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Navigation system

Rear parking sensors

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel – Heated

Windscreen – Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	1 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Left	5 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Front Right	1 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Right	5 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	None					

Damages



Damage Part
Fender – Rear Right



Damage Type
Dent(s)



Repair Type
Panelbeating & Spray

Acceptable
No



Damage Part
Skirt – Right



Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Skirt – Right



Damage Type
Missing



Notes
Afdichtrubber

Repair Type
Replace

Acceptable
No



Damage Part
Alloy – Right Front

Damage Type
Damaged

Repair Type
Rim repair

Acceptable
No



Damage Part
spoiler FB

Damage Type
Small scratch(es)

Repair Type
Spotrepair

Acceptable
No




Damage Part
Frontdoor – Left

Damage Type
Door-edge chipped

Repair Type
Acceptable

Acceptable
Yes




Damage Part	Damage Type	Repair Type	Acceptable
Rear seat	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Skirt - Left	Missing	Afdichtrubber	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Windscreen - Rear	Missing	Ruitenwisserkapje	Replace	No

