



Expertise

Protocol number: 46500609
Order No. / Reference: 26576673
Inspection date: 10 Jul 2026

Manufacturer: Citroën

Model: Berlingo M BlueHDi 130 FEEL PACK

VIN: VR7ECYHT2NN551430



Vehicle details	
Manufacturer / Type / Model / Equipment	
Citroën Berlingo M BlueHDi 130 FEEL PACK	
Vehicle Identification number	VR7ECYHT2NN551430
Mileage (Read)	75,714 km
First registration	9 Jan 2023
Number of holders	1
Power / Engine displacement	75 kw / 1,499 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Polar-Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Beige
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	7 Monat(e)
Last service on / at	01/2026 at 69,531 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC866654
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / AAR 01307		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,120 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 95V	Summer tyres on Light alloy	Michelin	3mm / 3mm
2)	205/55 R17 95V	Summer tyres on Light alloy	Michelin	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 95H	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	205/55 R17 95H	Winter tyres on Light alloy	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
Tirefit		Expiration date 06/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS & ESC
- Exterior mirrors (2) electrically adjustable, heated, folding
- Hill start assist
- On-board computer
- Coffee Break Alarm
- Roof rails
- Diesel Particulate Filter (DPF)
- Rear parking aid (acoustic and visual)
- Luggage cover
- Rear window can be opened separately and is more heavily tinted (rear window can be opened separately, more heavily tinted - side windows in rows 2 and 3 are more heavily tinted)
- Headrests (5)
- Steering wheel: Multifunction and leather steering wheel
- Package: White color package (exterior mirror housings painted in body color - fog lights with white surround)
- Package: Safety Package Plus (Traffic sign recognition for speed limits and recommendations - High beam assist - Attention system)
- Electric parking brake
- Upholstery: Fabric "Mica Green", grey/green
- Tire pressure monitoring system
- Tire repair kit with puncture spray
- Wheels: 16-inch steel rims with "Twirl-Black Center" wheel covers and summer tires (with 205/60 R 16 tires)
- Seats: 3 individual seats in row 2 with Isofix, foldable (12-volt connection - cup holders)
- Seats: Driver's seat height adjustable with armrest (manual lumbar support)
- Power outlet: Additional 12V socket in the trunk
- Doors: Manual sliding doors right and left with retractable side windows in the sliding doors (Manual sliding doors right and left with retractable side windows in the sliding doors in row 2 and fixed windows in row 3)
- Airbags: Front airbags, head airbags, side airbags (front airbag for driver and front passenger - front and rear head airbags - front side airbags)
- third brake light
- Roof storage (lighting in row 2 and in the cargo area - grab handles in rows 1 and 2)
- Tachometer
- Electric windows front and rear
- Transmission: 6-speed manual transmission
- Rear spoiler lip
- Electrically dimming interior mirror
- Electric child safety lock
- Analog instrument cluster
- Paint finish: Special paint finish Polar White
- Headlight range control
- Package: Safety (Lane Assist - Cruise Control and Speed Limiter - Active Emergency Brake Assist (Active Safety Brake) with Collision Warning)
- Visibility Package (Light sensor - Rain sensor - Magic Wash windscreen wipers with integrated wiper nozzles - Fog lights)
- Radio: Audio system (20-cm/8" touchscreen - Bluetooth - Mirror screen, Apple CarPlay and Android Auto - DAB - USB port)
- Side protection strips "Airbump" in black and partially white
- Power steering
- Seats: Front passenger seat foldable with armrests (folding table behind the seats of row 1)
- Sunshades with lighting
- Start&Stop system
- LED daytime running lights
- Doors unlock automatically in case of an accident.
- Immobiliser
- Central locking with remote control

Extra equipment

- Luggage divider net
- Automatic climate control (2-zone)
- Package: XTR package (exterior mirror caps and roof rails painted in black - front and rear underbody bumpers painted in body color - Airbumps partially orange - XTR logo - "Line Green" ambient lighting - Orange color package (fog lights with orange surrounds) - 17-inch Spin alloy wheels)
- Keyless system (keyless start and access system)
- Package: City Package 2 (Front and rear parking aid with acoustic sensors and 180° reversing camera - 20-cm/8-inch touchscreen - Bluetooth - Mirror Screen, Apple CarPlay and Android Auto - DAB - USB port - Blind Spot Assist)
- Seats: Heated front seats



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - rear left side	Brightware - lower - Scratch(es) - Loss in value
2	Trim / covers	Carpet - rear left side (Kaugummi) - Soiled - Clean
3	Wing mirror - right side	Cap - Scratch(es) - Smart repair
4	Interior	Interior - Scratch(es) - Loss in value
5	Sliding door - left side	Sliding door with glass panel - dent(s) - Smart repair
6	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
7	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
8	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Boot lid / rear door	Boot lid - dent(s) - No deduction
2	Sliding door, right	Sliding door with glass panel - dent(s) - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	Door - front left side	Door (Polieren) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Documents - Log book

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, Provided by user / customer, from 17 Oct 2025	1.433,63 €
2	Side right, Provided by user / customer, from 28 Nov 2024	2.687,72 €

Paint coat thickness measurement

Boot lid / rear door	24 µm	Side panel - rear right side	27 µm
----------------------	-------	------------------------------	-------



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Damage 1: Door - rear left side: Brightware - lower - Scratch(es) - Loss in value



Damage 1: Door - rear left side: Brightware - lower - Scratch(es) - Loss in value



Damage 2: Trim / covers: Carpet - rear left side (Kaugummi) - Soiled - Clean



Damage 2: Trim / covers: Carpet - rear left side (Kaugummi) - Soiled - Clean



Damage 3: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 3: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 4: Interior: Interior - Scratch(es) - Loss in value



Damage 4: Interior: Interior - Scratch(es) - Loss in value



Damage 4: Interior: Interior - Scratch(es) - Loss in value



Damage 4: Interior: Interior - Scratch(es) - Loss in value




Damage 4: Interior: Interior - Scratch(es) - Loss in value



Damage 4: Interior: Interior - Scratch(es) - Loss in value




Damage 4: Interior: Interior - Scratch(es) - Loss in value




Damage 4: Interior: Interior - Scratch(es) - Loss in value




Damage 5: Sliding door - left side: Sliding door with glass panel - dent(s) - Smart repair




Damage 5: Sliding door - left side: Sliding door with glass panel - dent(s) - Smart repair




Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 8: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 8: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 8: Vehicle glazing: Windscreen - Stone chips - Replace



Wear and tear 4: Door - front left side: Door (Polieren) - Scratch(es) - No deduction



Wear and tear 4: Door - front left side: Door (Polieren) - Scratch(es) - No deduction



Previous damage 1: Rear, Side right



Previous damage 1: Rear, Side right



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VR7ECYHT2NN551430

Hersteller / Modell: CITROEN CITROEN Berlingo M BlueHDi 100 FEEL PACK

Datum	KM-Stand	Beschreibung
14.01.2026	69.531	HU + AU; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Systemtest/ Eigendiagnose; Wartung Sonstiges
31.07.2025	56.981	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
04.03.2025	43.723	Bremsflüssigkeit ern; Motoröl b. Wartung; Regelwartungsdienst
29.01.2024	18.790	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges