



Expertise

Protocol number: 46604445
Order No. / Reference: 26670654
Inspection date: 20 Jul 2026

Manufacturer: CUPRA

Model: Born 170kW/77kWh

VIN: VSSZZK13PP026681



Vehicle details

Manufacturer / Type / Model / Equipment

CUPRA Born 170kW/77kWh

Vehicle Identification number VSSZZK13PP026681

Mileage (Read) 31,579 km

First registration 6 Apr 2023

Number of holders 1

Next periodical technical inspection 04/2028
(Report on hand)

Fuel type Electric

Power 70 kW

Gearbox / Number of gears Direct drive / 1

Type of drive Rear drive

Type of vehicle Saloon car

Colour / colour code Vapor Grey

Doors / Seats 5 / 4

Upholstery type Cloth

Colour of upholstery Black-Grey



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	283 km
Last service on / at	04/2025 at 22,649 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ499126
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	7593 / ASN 00019		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	2,320 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R19 93T	Summer tires (with run-flat tires) on Light alloy	Continental	5mm / 5mm
2)	215/50 R19 93T	Summer tires (with run-flat tires) on Light alloy	Continental	4mm / 4mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R19 93T	Winter tires (with run-flat tires) on Light alloy	Pirelli	6mm / 6mm
2)	215/50 R19 93T	Winter tires (with run-flat tires) on Light alloy	Pirelli	7mm / 7mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Airbag for driver and front passenger
- Airbag: Head airbag system, front and rear
- Exterior mirrors: aspherical on driver's side, convex on passenger's side
- Battery warranty 8 years, maximum 160,000 km
- C-pillar with CUPRA design element
- CUPRA Drive Profile
- CUPRA lettering on tailgate
- Black headliner
- Electronic parking brake including auto-hold function
- Electric window regulator with anti-pinch protection and one-touch function
- Transmission: 1-speed automatic
- rear window wiper
- Rear bumper and diffuser in body color
- ISOFIX child seat restraint system, in the 2nd row of seats left and right as well as on the front passenger seat
- Headrests, 2 front
- Paint finish: Solid
- Steering wheel: CUPRA Supersport multifunction steering wheel in leather with CUPRA mode selector
- Center console with integrated storage compartment and cup holders
- Progressive steering
- Rain sensor
- Seat belts - front and rear
- Seats: CUPRA sports bucket seats in the front
- Seats: Driver's seat with height adjustment
- Sport pedals in aluminum look
- 12V socket in the luggage compartment
- Ultrasonic parking aid front and rear
- Electronic immobilizer
- thermal insulation glazing
- Airbag: Passenger airbag deactivation
- Ambient lighting in the front door panel
- Electrically adjustable, folding and heated exterior mirrors
- Exterior mirror housing in Liquid Grey
- third brake light
- CCS charging socket
- CUPRA e-Sound
- CUPRA side skirts in Liquid Grey
- decorative elements
- Electronic Stability Control (ESC)
- Luggage compartment lighting
- Speed limiter
- Heat pump
- Rear spoiler in car color
- Interior mirror automatically dimming
- Keyless Go (engine start/stop button)
- Air conditioning: Climatronic with electronic temperature control
- Mode 3 Type 2 charging cable, 16 A
- Lights: Full headlights
- front center armrest
- Fatigue detection
- Emergency call service
- Radio: Radio, navigation and multimedia systems
- Tire pressure monitoring system
- Seats: 2 rear seats, rear seat backrest asymmetrically split and foldable, with center armrest
- Sun visors with illuminated makeup mirror
- Lane departure warning system
- Front bumper in body color
- Front Assist area monitoring system with City Emergency Braking function



Extra equipment

- AR Head-up Display (Augmented Reality Head-up Display projects driving data into the driver's field of vision)
- Chassis: Dynamic Chassis Control (Adaptive Chassis Control DCC)
- Package: Cargo Pack (Power cable for household socket (charging cable Mode 2, Type 2 / 10A) - Variable luggage compartment floor)
- Package: Protect Pack (anti-theft alarm system including interior monitoring, backup horn, tow-away protection and safe locking - Pre Crash Assist)
- Package: Tech L Pack (Illuminated exterior door handle recesses at the front - Car2X function - Intelligent Park Assist (IPA) - Kessy Advanced, keyless locking and starting system - Wireless Charger)
- Wheels: TYPHOON 7.5J x 19" alloy wheels, black/copper, diamond-cut finish (tires 215/50 R 19 with self-sealing function)
- Charge 32A (Charging cable Mode 3, Type 2 / 32A (Enables single-phase charging with up to 7.2 kW))
- Package: Below Zero Pack (Heated front seats - Heated front windshield washer nozzles)
- Package: Pilot M+ Pack (Adaptive Cruise Control ACC with predictive speed control - CUPRA CONNECT PLUS - prepared for activation of the Online Infotainment service package - High Beam Assist - Navigation system with 12" color touchscreen - Rear Traffic Alert (RTA) - Side Assist incl. Blind Spot Assist - Rearview camera - Traffic sign recognition)
- Radio accessories: Beats Audio sound system (9 speakers, digital multi-channel amplifier, subwoofer, 395 watts total power)
- Tool kit in conjunction with 18-20" summer tires / 19" all-season tires (wheel wrench, towing eye, adapter for the anti-theft wheel bolt, hook for removing the wheel covers, clip for wheel bolt caps)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Fahrzeugmodellbezeichnung laut Rechnung: "CUPRA Born 170kW/77kWh".
- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VSSZZZK13PP026681

Hersteller / Modell: SEAT SEAT Born 170kW/77kWh

Datum	KM-Stand	Beschreibung
29.04.2025	22.649	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst