



Expertise

Protocol number: 46630590
Order No. / Reference: 26801840
Inspection date: 20 Jul 2026

Manufacturer: Skoda
VIN: TMBJH9NP6N7007508

Model: Superb Combi 2.0 TDI DSG Ambition



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Superb Combi 2.0 TDI DSG Ambition	
Vehicle Identification number	TMBJH9NP6N7007508
Mileage (Read)	176,304 km
First registration	17 Feb 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Brillant-Silber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	6,300 km
Last service on / at	12/2025 at 152,990 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GD078723
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	With complaint
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8004 / APL 01355		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,196 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/45 R18 98Y	Summer tyres on Light alloy	Falken	4mm / 4mm
2)	235/45 R18 98Y	Summer tyres on Light alloy	Continental	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Closed storage compartments behind the wheel arches in the trunk, including cargo elements
- Airbag, driver and switchable passenger airbag
- Airbag, driver's knee airbag
- Airbag, head airbags
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Electrically adjustable and heated exterior mirrors
- Exterior mirrors and door handles in body color
- Electrically folding exterior mirrors (with boarding lights - interior and exterior mirrors with automatic dimming)
- Hydraulic brake assist (HBA)
- Roof rails, black
- Diesel particulate filter and SCR catalyst
- Tachometer
- Easy Start (start-stop button instead of ignition lock)
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor (tunnel light, coming and leaving home function)
- Front radar assist including city emergency braking function (The front radar assist warns of impending collisions and initiates braking to reduce the force of an unavoidable impact. The front radar assist continuously monitors the distance to the vehicle ahead using a radar sensor integrated into the radiator grille.)
- ISOFIX preparation on the outer rear seats, including top tether
- Boot cover, roll-up and removable, semi-automatic
- Front and rear headrests are height-adjustable.
- LED low beam
- LED taillights
- Steering wheel: height and reach adjustable
- Reading lights at the front and rear of the headliner
- Rear center armrest with cup holders and pass-through option
- Multi-collision brake
- Rear parking sensors
- Radio: Bolero infotainment system (capacitive 8" touch display in glass design - Wireless Smartlink (Apple CarPlay, Android Auto))
- Radio accessories: USB ports at the front (Type-C) and USB charging port (Type-A) in the center armrest
- Tire pressure monitoring
- Heated windshield washer nozzles
- Superb safety belts (Height-adjustable three-point front seat belts with belt tensioners - Three three-point rear seat belts - Belt fastening indicator for all seats)
- Storage compartments (ticket holder on the windshield, 4 roof grab handles, rear with coat hooks, coat hooks on the B-pillar, holder for the warning vests in the front doors, glasses compartment in the headliner, storage compartments in the door panels (front and rear) with 1.5l bottle holders, cup holder in the front center console with easy-open bottle opening, storage pockets on the front seat backrests, storage compartments behind the wheel arches in the trunk including cargo elements, illuminated trunk)
- Illuminated glove compartment
- Hill start assist
- Grey headliner
- Decorative inlay silver brushed
- Digital instrument cluster (Virtual Cockpit) 10.2"
- Third brake light
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control system (cruise control) including speed limiter
- Transmission: 7-speed dual-clutch transmission (DSG)
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- Child safety lock for rear doors & windows, electric
- Air Care Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger, including odor and allergen filter and air-conditioned glove compartment)
- Steering wheel: 2-spoke leather steering wheel with multifunction buttons (including gearshift and handbrake levers in leather)
- Front center armrest with storage compartment
- Engine drag torque control (MSR)
- LED fog lights with integrated cornering lights
- Upholstery: Cloth
- Radio accessories: Digital radio reception DAB+
- Radio accessories: In-car communication
- Radio accessories: SmartLink+ (Apple CarPlay - Android Auto - MirrorLink - SmartGate)
- Radio accessories: Wireless SmartLink for Apple CarPlay
- Tire mobility kit (tire repair spray incl. compressor)
- Electromechanical power steering
- Seats: Adjustable lumbar support in the front seats
- Seats: Height-adjustable front seats
- Seats: Rear seat backrest split 60:40, foldable
- Sun visor on driver and passenger side with illuminated make-up mirror
- Start/stop system including brake energy recuperation
- 12V socket in the trunk
- 12V socket in the center console, front and rear
- Telephone: Convenient hands-free phone system with Bluetooth (without connection to an external antenna)



- SKODA Care Connect (SOS emergency call function (Emergency Call incl. automatic activation in the event of an accident with airbag deployment), Mobility service (connection for rapid assistance in case of breakdown), Information service (connection to the hotline for all questions relating to vehicle functions), Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level)
- Lashing eyes in the trunk
- Central locking with remote control

- Chrome-plated elements (on air vents, light switches, music or navigation systems, air conditioning)
- Immobiliser

Extra equipment

- Adaptive Cruise Control (ACC)
- Swiveling trailer hitch including trailer stabilization
- Chassis: Sport chassis (15 mm lowering)
- Paint finish: Metallic
- Package: Business Amundsen (DSG) (Amundsen navigation system - voice control - Wi-Fi hotspot - Wireless Smartlink for Apple CarPlay - 8" capacitive touchscreen in glass design - Phonebox - Traveller assistance system (traffic sign recognition, predictive lane keeping assist pACC, adaptive lane keeping assist, emergency and traffic jam assist, capacitive steering wheel with hands-off detection) - 230 V socket and 3 USB ports, tablet holder - Sunset - Infotainment Online (3-year subscription))
- Airbag, proactive occupant protection including rear side airbags
- High beam assist
- Steering wheel: Heated steering wheel (2 spokes) (with paddle shifters)
- Wheels: 18" Zenith alloy wheels (8J x 18" ET 44 with 235/45 R18 tires)
- Reversing camera with washer nozzle
- Seats: Heated front seats
- Lane keeping assist, lane change assist, parking assist
- Folding front passenger seat backrest
- Traffic sign recognition

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed, problem has been detected This is due to the following reason.: Riementrieb Quietscht
readiness to drive	The vehicle was roadworthy at the time of inspection.



Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (2. Wartung überzogen)
2	Trim / covers	Floor mats (VL) - Holes - Replace
3	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Loss in value
4	Door - rear right side	Door - Dent / paintcoat damage - Smart repair
5	Door - front right side	Door (Blende unten) - Scratch(es) - Smart repair
6	Trim / covers	Door trim - rear left side - Scratch(es) - Smart repair
7	Trim / covers	A-pillar - trim - interior, left side - Scratch(es) - Replace
8	Engine	Belt drive (Quietscht) - Functional / admissibility - Perform diagnosis
9	Body	Body - Damage by hail - Repair
10	Side panel - rear right side	Side panel (Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint
11	Bonnet	Bonnet (Lackstift) - Paint defect - Paint
12	Roof	Roof (+ Kratzer) - Corrosion - Paint

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - dent(s) - No deduction
2	Roof	Roof rail - right side - dent(s) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Boot lid / rear door	Boot lid - Scratch(es) - No deduction
5	Body	B-pillar - left side - dent(s) - No deduction
6	Body	B-pillar - right side - Dent / paintcoat damage - No deduction
7	Trim / covers	Roof lining - Soiled - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Tirefit filler

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 9 Jan 2024	3.751,80 €
2	Side right, Provided by user / customer, from 9 Apr 2024	7.381,20 €

Repainting

No. Repainting

- Mudguard - right side, Bonnet, Door - rear right side, Door - front right side, Professionally carried out, Invoice of repair done Non-existent
- Side panel - rear right side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - right side	167 µm	Bonnet	199 µm
Side panel - rear right side	1,500 µm	Door - rear right side	280 µm
Door - front right side	265 µm		



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Damage 2: Trim / covers: Floor mats (VL) - Holes - Replace



Damage 3: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Smart repair




Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Smart repair



Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Smart repair




Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Smart repair




Damage 5: Door - front right side: Door (Blende unten) - Scratch(es) - Smart repair




Damage 5: Door - front right side: Door (Blende unten) - Scratch(es) - Smart repair



Damage 6: Trim / covers: Door trim - rear left side - Scratch(es) - Smart repair



Damage 6: Trim / covers: Door trim - rear left side - Scratch(es) - Smart repair




Damage 7: Trim / covers: A-pillar - trim - interior, left side - Scratch(es) - Replace



Damage 7: Trim / covers: A-pillar - trim - interior, left side - Scratch(es) - Replace



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair




Damage 9: Body: Body - Damage by hail - Repair




Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair



Damage 9: Body: Body - Damage by hail - Repair




Damage 9: Body: Body - Damage by hail - Repair




Damage 10: Side panel - rear right side: Side panel (Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint



Damage 10: Side panel - rear right side: Side panel (Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint




Damage 10: Side panel - rear right side: Side panel (Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint




Damage 10: Side panel - rear right side: Side panel (Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint



Damage 10: Side panel - rear right side: Side panel (Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint



Damage 10: Side panel - rear right side: Side panel (Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint




Damage 11: Bonnet: Bonnet (Lackstift) - Paint defect - Paint




Damage 11: Bonnet: Bonnet (Lackstift) - Paint defect - Paint



Damage 11: Bonnet: Bonnet (Lackstift) - Paint defect - Paint



Damage 11: Bonnet: Bonnet (Lackstift) - Paint defect - Paint



Damage 12: Roof: Roof (+ Kratzer) - Corrosion - Paint



Damage 12: Roof: Roof (+ Kratzer) - Corrosion - Paint



Damage 12: Roof: Roof (+ Kratzer) - Corrosion - Paint



Repainting 1: Mudguard - right side, Bonnet, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Bonnet, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Bonnet, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Bonnet, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Bonnet, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Bonnet, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Bonnet, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Bonnet, Door - rear right side, Door - front right side



Repainting 2: Side panel - rear right side



Repainting 2: Side panel - rear right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBJH9NP6N7007508
Hersteller / Modell: SKODA SKODA Superb Combi 2.0 TDI DSG Ambition

Datum	KM-Stand	Beschreibung
09.12.2025	152.990	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
10.10.2025	145.909	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Wartung Sonstiges
19.08.2025	136.988	Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges
19.03.2025	119.849	Bremse Sonstiges; Bremsklötze vorne; Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
13.02.2025	115.091	HU + AU
11.11.2024	95.258	Batterie ern; Keilrippenriemen; Lichtmaschine ern/inst; Reparatur Sonstiges; Systemtest/Eigendiagnose
29.07.2024	90.547	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
30.04.2024	82.839	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
13.09.2023	61.861	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
27.09.2022	30.770	Motoröl b. Wartung; Regelwartungsdienst