



Expertise

Protocol number: 46517006  
Order No. / Reference: 26535403  
Inspection date: 8 Jul 2026

Manufacturer: Mercedes-Benz

Model: E 220 d T 9G-TRONIC Avantgarde

VIN: W1KZH0EB7PB144630



| Vehicle details                              |                             |
|----------------------------------------------|-----------------------------|
| Manufacturer / Type / Model / Equipment      |                             |
| Mercedes-Benz E 220 d T 9G-TRONIC Avantgarde |                             |
| Vehicle Identification number                | W1KZH0EB7PB144630           |
| Mileage (Read)                               | 157,687 km                  |
| First registration                           | 2 May 2023                  |
| Number of holders                            | 1                           |
| Power / Engine displacement                  | 147 kw / 1,993 ccm          |
| Fuel type / Cylinder                         | Hybrid Diesel / E / 4       |
| Gearbox / Number of gears                    | Automatic / 9               |
| Type of drive                                | Rear drive                  |
| Type of vehicle                              | Station wagon               |
| Colour / colour code                         | Schwarz                     |
| Doors / Seats                                | 5 / 5                       |
| Upholstery type                              | Cloth / leather combination |
| Colour of upholstery                         | Black                       |



## Vehicle details

|                                                  |                              |                                |                                                            |
|--------------------------------------------------|------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete     | <b>Next maintenance in</b>     | 217 Tag(e)                                                 |
| <b>Last service on / at</b>                      | 09/2025 at 122,845 km        |                                |                                                            |
| <b>Key is / should be</b>                        | 3 / 2                        | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                              | <b>Letter No.</b>              | GS700142                                                   |
| <b>Previous damage / Accident</b>                | None detectable              | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient                   | <b>Lifting equipment / pit</b> | No                                                         |
| <b>Test drive</b>                                | Not performed                | <b>Engine function test</b>    | Performed                                                  |
| <b>Manufacturer key number/ type code number</b> | 2222 / BEG 00109             |                                |                                                            |
| <b>Emission standard</b>                         | EURO6;WLTP;AP;PI/CI; M, N1 I | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,525 kg                     | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 225/55 R17 97Y | Summer tyres on Light alloy | Pirelli      | 5mm / 5mm   |
| 2) | 225/55 R17 97Y | Summer tyres on Light alloy | Pirelli      | 4mm / 4mm   |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

## Equipment

### Standard equipment

- ADAPTIVE BRAKE with hill start assist, pre-filling and drying braking in wet conditions
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Premium ambient lighting with 64 colors and 3 color zones
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Attention Assist
- Basic services
- On-board computer
- Diesel particulate filter
- Third brake light
- EASY-PACK cargo cover including EASY-PACK safety net
- Electronic Stability Program (ESP)
- Chassis: Air suspension on the rear axle with level control
- Electric window regulator with comfort operation and anti-pinch protection, 4-way
- Heated rear window with timer
- Interior headliner in nevagrau fabric
- THERMATIC automatic climate control
- Paint finish: Solid
- LED High Performance Headlights
- Steering wheel: Multifunction steering wheel in Nappa leather in a 3-spoke design
- Mercedes-Benz emergency call system
- Center console with on-the-fly storage compartment
- Navigation: Hard disk navigation
- Package: Storage
- Package: Seating comfort
- Upholstery: ARTICO leatherette/Norwich fabric
- PRE-SAFE system
- Radio: Extended MBUX functions
- Radio: MBUX multimedia system
- Radio accessories: Digital radio
- Radio accessories: Communication module (LTE) for using Mercedes me connect services
- Tire pressure monitoring system
- Remote Services Plus
- Power steering
- Seats: Rear seat backrests foldable, 40/20/40 split
- Touchpad
- Electronic immobilizer
- Central locking
- AdBlue tank with a capacity of 23.5 liters
- Airbag for driver and front passenger
- Airbag: Kneebag for driver
- Airbag: Windowbags left/right
- AMG sports pedal assembly made of brushed stainless steel with rubber studs
- Foldable armrest for driver and front passenger
- Left and right exterior mirrors, heated and electrically adjustable, painted in body color
- Brake assist, active
- Tachometer
- DYNAMIC SELECT
- EASY-PACK tailgate
- Chassis: AGILITY CONTROL chassis with selective damping system and lowered suspension
- Velour floor mats
- Transmission: 9-speed automatic, 9G-TRONIC
- rear window wiper
- KEYLESS START
- Headrests 5-way adjustable for driver and front passenger, 4-way adjustable, and 2-way adjustable in the rear.
- Steering column mechanically adjustable in height and length
- Center console piano black finish
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: AVANTGARDE Exterior (43.2 cm (17") light-alloy wheels in 5-twin-spoke design, painted high-gloss black and polished with 225/55 R 17 tires on 7.5 J x 17 ET 40 rims - Radiator grille with integrated Mercedes star - Hood with pronounced power domes - Front bumper with chrome trim strip, chrome front splitter - Side skirts and window surrounds in polished aluminum - Side sills painted in body color - Roof rails in polished aluminum - Rear bumper with chrome trim strip - Exhaust system with two tailpipe trims)
- Windscreen wipers with rain sensor
- Seats: i-Size child seat attachment
- Power outlet: 12V socket in the cargo area
- High-visibility vest for drivers
- Green, heat-insulating glass all around
- Decorative elements: aluminum with longitudinal brushing, light finish



## Extra equipment

- Adaptive High Beam Assist (You activate the system with one operation and then benefit from the long beam range.)
- Black fabric headliner
- Package: Business (MBUX High-End Package - Connectivity Package Navigation - Traffic Sign Assist - Smartphone Integration (Apple CarPlay and Android Auto) - Preparation for Digital Key Handover - Widescreen Cockpit - Wireless Charging System for Mobile Devices - MBUX Augmented Reality for Navigation - Heated Seats for Driver and Front Passenger - Parking Package with Rearview Camera - Fuel Tank with 66 Liter Capacity (916) (60l for Diesel Plug-in Hybrids).)
- Package: Parking package with reversing camera (The parking package with reversing camera makes it easier to find and select parking spaces, as well as to park and exit in parallel and perpendicular parking spaces or garages. The active parking assistant steers the vehicle into parking spaces, including speed control and automatic gear changes.)
- Heated windshield washer system (including heated washer fluid reservoir, windshield washer nozzles and washer fluid hoses)
- Seats: Heated seats for driver and front passenger (selectable in three stages - Intelligent and comfortable: The seat heating switches off automatically)
- Towbar with ESP trailer stabilization (fully electrically foldable and retractable)
- Center console wood ash black open pore
- Package: Memory (driver and front passenger seats, steering column and exterior mirrors electrically adjustable and storable - seat longitudinal position and headrest height additionally electrically adjustable - distribution of the heated areas of the seat cushion and seat backrest storable - position of the optional head-up display adjustable and storable - 4-way lumbar support for driver and front passenger - seat cushion depth adjustment with gapless cushion - PRE-SAFE positioning function for the front passenger seat)
- Package: Sun protection package (mechanical sunshade in rear doors left and right - extendable sun visors with make-up mirror for driver and front passenger)
- Package: Mirrors (both exterior mirrors electrically foldable (button in the driver's door control panel) - automatic lowering of the passenger-side mirror glass to parking position when reverse gear is engaged - interior mirror and driver's side exterior mirror automatically dimming continuously - ambient lighting of the exterior mirror to illuminate the entry area)
- TIREFIT with tire inflation compressor
- Type designation removed from trunk lid

## Brief expert findings

|                      |                                                                                                                                                                                                                                               |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)                                                                  |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.                                                                     |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                                                                                         |
| Engine function test | An engine test run was performed.                                                                                                                                                                                                             |

## Value reducing factors

| No. | Component group              | Description                                                                  |
|-----|------------------------------|------------------------------------------------------------------------------|
| 1   | Side panel - rear right side | Mudguard - rear right side - Scratch(es) - Smart repair                      |
| 2   | Door - front left side       | Door - Dent / paintcoat damage - Repair and paint                            |
| 3   | Bonnet                       | Bonnet (Übermäßige Steinschläge) - Stone chips - Paint                       |
| 4   | Front bumper                 | Front bumper - Scratch(es) - Paint                                           |
| 5   | Vehicle glazing              | Windscreen (Mit Rissbildung) - Stone chips - repair according to calculation |
| 6   | Rear bumper                  | Rear bumper - Broken / torn - repair according to calculation                |



## Wear and tear

| No. | Component group         | Description                            |
|-----|-------------------------|----------------------------------------|
| 1   | Door - front right side | Door edge - Scratch(es) - No deduction |
| 2   | Door - rear left side   | Door edge - Scratch(es) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung, Mehrkosten und somit Abweichung der für die Stoßstange ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.



**Figure 1:** Diagonal front (left)



**Figure 2:** Diagonal front (right)



**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



**Figure 31:** Misc.




**Damage 1:** Side panel - rear right side: Mudguard - rear right side - Scratch(es) - Smart repair



**Damage 1:** Side panel - rear right side: Mudguard - rear right side - Scratch(es) - Smart repair



**Damage 2:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 2:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 2:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 3:** Bonnet: Bonnet (Übermäßige Steinschläge) - Stone chips - Paint



**Damage 3:** Bonnet: Bonnet (Übermäßige Steinschläge) - Stone chips - Paint




**Damage 3:** Bonnet: Bonnet (Übermäßige Steinschläge) - Stone chips - Paint



**Damage 3:** Bonnet: Bonnet (Übermäßige Steinschläge) - Stone chips - Paint



**Damage 4:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 4:** Front bumper: Front bumper - Scratch(es) - Paint




**Damage 4:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 5:** Vehicle glazing: Windscreen (Mit Rissbildung) - Stone chips - repair according to calculation



**Damage 5:** Vehicle glazing: Windscreen (Mit Rissbildung) - Stone chips - repair according to calculation



**Damage 6:** Rear bumper: Rear bumper - Broken / torn - repair according to calculation



**Damage 6:** Rear bumper: Rear bumper - Broken / torn - repair according to calculation



**Damage 6:** Rear bumper: Rear bumper - Broken / torn - repair according to calculation



**Wear and tear 1:** Door - front right side: Door edge - Scratch(es) - No deduction



**Wear and tear 1:** Door - front right side: Door edge - Scratch(es) - No deduction



**Wear and tear 2:** Door - rear left side: Door edge - Scratch(es) - No deduction



**Wear and tear 2:** Door - rear left side: Door edge - Scratch(es) - No deduction