



Expertise

Protocol number: 46277296
Order No. / Reference: 26509910
Inspection date: 1 Jul 2026

Manufacturer: Nissan

Model: Leaf 62 kWh e+ N-Connecta

VIN: SJNFAAZE1U0145277



Vehicle details	
Manufacturer / Type / Model / Equipment	
Nissan Leaf 62 kWh e+ N-Connecta	
Vehicle Identification number	SJNFAAZE1U0145277
Mileage (Read)	43,180 km
First registration	22 Dec 2021
Number of holders	1
Power / Engine displacement	90 kw / 0 ccm
Fuel type / Cylinder	Electric / 0
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Blade Silver Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Blue



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	
Key is / should be	4 / 4	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC885313
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2228 / AAJ 00003		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,140 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R17 95V	All-season tyres on Light alloy	Goodyear	5mm / 5mm
2)	215/50 R17 95V	All-season tyres on Light alloy	Goodyear	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Airbag: Driver and passenger side • Airbag: Front side airbags • Anti-lock braking system (ABS) with electronic brake force distribution (EBD) and NISSAN brake assist • Outdoor temperature display • third brake light • Electric windows front and rear • Cruise control system and speed limiter • cup holder • Heated rear window • Intelligent Adaptive Speed and Distance Assist • Intelligent Autonomous Emergency Braking Assistant • Automatic air conditioning • Headrests (5) front and rear • Front charging port Type 2, AC (up to 6.6 kW) • Charging port: Fast charging port at the front (CHAdeMO), direct current up to 50 kW • Charging cable: Mode 3 charging cable Type 2/Type 2 (up to 7.4kW) • Steering wheel: Remote control on the steering wheel • Headlight range control • NISSAN Connect EV navigation system • Electric parking brake • ProPILOT • Radio accessories: Apple CarPlay and Android Auto • Tire pressure monitoring system (TPMS) • Color reversing camera • Rear seat backrest foldable asymmetrically (60:40) • Windscreen wipers with intermittent function front and rear • Seat belts: Three-point seat belts • Seats: Driver's seat height adjustable • 12-volt socket, front • Chrome-look door handles • Glazing: UV-absorbing windshield • Electronic immobilizer | <ul style="list-style-type: none"> • Airbag: Front and rear head airbags • Acoustic pedestrian warning system (AVAS) • Electrically adjustable exterior mirrors in car color • Exterior mirrors with automatic folding function • Hill Start Assist • Electronic Stability Program (ESP) • High Beam Assist • Transmission: Automatic, continuously variable • shark antenna • Interior mirror, automatically dimming • Intelligent AROUND VIEW MONITOR • Intelligent lane keeping assist active • Removable boot cover • Paint finish: Solid • Charging port: Fast charging port at the front (CHAdeMO) compatible with 100kW • Charging cable: EVSE cable (Mode 2 safety system) with household plug (up to 2.3 kW) • Leather steering wheel • Steering column adjustable in height and depth • Light and rain sensor • Fog light • Upholstery: Cloth • Cross-traffic alert • Radio accessories: Roof antenna • Wheels: Light alloy (4) 6.5J x 17" • LED taillights • Windows tinted from the B-pillar back • electric power steering • Seats: Driver and passenger seats manually adjustable • Seats: ISOFIX child seat attachment • Blind spot assist, active • Glazing: Laminated glass windshield • Traffic sign recognition • Central locking including remote control |
|---|--|

Extra equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • 2 additional keys • All-season tyres • Paint finish: Metallic | <ul style="list-style-type: none"> • Wheel lock for 4 alloy wheels • Rubber mats • Registration package including floor mats and first-aid kit |
|---|---|



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Misc.	Inspection / maintenance - No evidence - No deduction
3	Equipment	Tirefit filler - Expired - Replace
4	Body	Body - Glued / labelled - De-glue / neutralise

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Wheel / tyres - Wheel lock

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Damage 3: Equipment: Tirefit filler - Expired - Replace




Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise