



Expertise

Protocol number: 45769336
Order No. / Reference: 26445520
Inspection date: 3 Jun 2026

Manufacturer: Volkswagen

Model: Touareg 3.0 V6 TDI 4Motion DPF Aut. Elegance

VIN: WVGZZZCRZMD016781



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Touareg 3.0 V6 TDI 4Motion DPF Aut. Elegance	
Vehicle Identification number	WVGZZZCRZMD016781
Mileage (Read)	105,274 km
First registration	22 Jan 2021
Number of holders	1
Next periodical technical inspection	04/2028
(Report on hand)	
Power / Engine displacement	170 kw / 2,967 ccm
Fuel type / Cylinder	Diesel / 6
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Siliziumgrau Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Beige-Dark grey



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	9,000 km
Last service on / at	10/2025 at 88,116 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FX402720
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / COB 00001		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,850 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R18 110H	Winter tyres on Light alloy	Bridgestone	6mm / 6mm
2)	235/65 R18 110H	Winter tyres on Light alloy	Bridgestone	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/55 R19 107W	Summer tyres on Light alloy	Bridgestone	6mm / 6mm
2)	255/55 R19 107W	Summer tyres on Light alloy	Bridgestone	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2030		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Airbag for driver and front passenger, with front passenger airbag deactivation
- Electrically folding, adjustable, heated and dimming exterior mirrors
- Diesel particulate filter
- Electronic Stability Program (ESP)
- Driving profile selection
- High beam control "Light Assist"
- Pedestrian protection measures expanded
- luggage compartment cover
- Transmission: 8-speed automatic Tiptronic
- Rear window wiper with intermittent function
- Rear headrests (3)
- LED headlights with LED daytime running lights
- front center armrest
- Multifunction display "Premium"
- Non-smoking version
- Emergency call service
- Wheels: Tire Mobility Set
- Rear seat bench and backrest asymmetrically split, foldable, longitudinally adjustable
- Seat belts: Three-point automatic seat belts
- Lane keeping assistant "Lane Assist"
- Bumpers in body color
- Traffic sign recognition
- Electronic immobilizer
- Airbag, head airbag system including front side airbags
- white ambient lighting
- Outdoor temperature display
- third brake light
- Tachometer
- Automatic headlight control, with LED daytime running lights
- Windscreen made of laminated safety glass, heat and sound insulating
- Cruise control
- Rear window heated
- Air conditioning system "Air Care Climatronic"
- Front headrests
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- Navigation system "Discover Pro"
- Emergency braking assistant "Front Assist"
- Package: Design Package "Elegance"
- LED taillights
- Keyless Start system
- Power steering
- Seats: Front seats with height adjustment
- Start-stop system with brake energy recuperation
- Textile floor mats front and rear
- Prepared for "Guide & Inform" and "Security & Service"
- Central locking including remote control

Extra equipment

- Electrically folding towbar including trailer maneuvering assistant "Trailer Assist"
- Paint finish: Metallic
- Package: Ambient lighting package (multicoloured ambient lighting - illuminated stainless steel door sill trims at the front)
- Package: Leather "Vienna" with ergoComfort front seats (ergoComfort front seats - remote release for rear seat backrest - pneumatically adjustable lumbar support in front - rear center armrest - automatically heated windshield washer nozzles in front - safety-optimized front headrests - seat center panels and inner side bolsters in leather "Vienna" - heated front seats)
- Heated windscreen (laminated safety glass, heat and noise insulating)
- Lighting: IQ.LIGHT - LED matrix headlights (Dynamic Light Assist high beam control for LED matrix headlights - LED matrix headlights with LED daytime running lights - LED taillights with dynamic turn signals - headlight cleaning system)
- Parking assist system "Park Assist" with reversing camera "Rear Assist" (incl. parking aid)
- Wheels: Alloy wheels (4) "Osorno" 8 J x 19 (tires 255/55 R 19)
- Windows: Rear side windows and rear window tinted
- Locking system: Luggage compartment lid with electric opening and closing (luggage compartment cover with electric opening - closing aid for luggage compartment lid)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
2	Rear bumper	Rear bumper - Scratch(es) - Paint

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Comments

Der montierte Radsatz ist nicht Bestandteil der Ausstattung.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.





Figure 33: Misc.



Figure 34: Misc.



Damage 1: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work




Damage 1: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint