

# Skoda Enyaq '21 BEV

## Vehicle information


Make:	<b>Skoda</b>	License:	
Gearbox:	<b>Automatic</b>	Body color:	
Model:	<b>Enyaq '21 BEV</b>	VIN:	<b>TMBJB7NY0MF019639</b>
Fuel type:	<b>Electric</b>	Power:	<b>132 kW</b>
Version:	<b>Enyaq iV60</b>	First registration:	<b>06/05/2021</b>
Mileage:	<b>237384 km</b>	N° of doors:	

## Damage summary

<b>Front</b>	(2)
<b>Interior</b>	(1)
<b>Left</b>	(1)
<b>Rear</b>	(2)

## Commercial pictures





**Options according to the inspector**

Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser	Yes
Radio multimedia	Yes	Telephone equipment	Yes		

**Damages**

--	--	--	--	--	--

**Boot lid covering R**

Scratch(es)  
Smart repair  
Rear




**Bumper R**

Scratch(es)  
Repair and paint (complete)  
Rear



**Bumper trim F**

Deformed / Strained  
Replace  
Front




**Door RL**

Dent(s) and scratch(es)  
Repair and paint (complete)  
Left




**Ignition key**

Worn  
Replace  
Interior



**Windscreen**  
Stone chip(s)  
Replace  
Front



## Tyres

### Front Left

Summer

235/55/19/101/T

Bridgestone

3.3 mm

### Front Right

Summer

235/55/19/101/T

Bridgestone

3.3 mm

### Rear Left

Summer

235/55/19/101/T

Bridgestone

2.8 mm

### Rear Right

Summer

235/55/19/101/T

Bridgestone

2.3 mm

## Checks

Certificate of Conformity	<b>No</b> CO2 Emission	<b>0</b>
Digital maintenance	<b>Yes</b> GPS storage	<b>Yes</b>
GPS storage	<b>HD</b> Luggage cover	<b>Yes</b>
Number head rests	<b>5</b> Number of charging cables (rapid charge)	<b>1</b>
Number of keys total	<b>2</b> Service book	<b>N/A</b>
User's manual	<b>Yes</b>	

### Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.