

# MACDAM

## Ford Mustang '19 BEV


### Vehicle information



Make:	<b>Ford</b>	License:	
Gearbox:	<b>Automatic</b>	Body color:	
Model:	<b>Mustang '19 BEV</b>	VIN:	<b>WF0TK1E70MMA15051</b>
Fuel type:	<b>Electric</b>	Power:	<b>210 kW</b>
Version:	<b>Mustang EV 99kWh RWD Ext.R.</b>	First registration	<b>24/06/2021</b>
Mileage:	<b>130637 km</b>	N° of doors:	

### Damage summary

<b>Front</b>	<b>3</b>
<b>Left</b>	<b>1</b>
<b>Right</b>	<b>4</b>
<b>Roof &amp; others</b>	<b>1</b>

### Commercial pictures





**Batterijcertificaat**  
 Datum van diagnose: 01/07/2026

93,5%

Status van de gezondheid (SOH)\*

**Ford Mustang MACH e Propulsion Extended Range**

VIN : WFOTK1E7OMMA15051  
 Kilometerstand : 130.637 km

\*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie

Meer weten over: [www.get-moba.com](http://www.get-moba.com)

CARA



## Options according to the inspector

Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser	Yes
Radio multimedia	Yes	Rear view camera	Yes	Telephone equipment	Yes

## Damages

### Bonnet

Chemical polution  
Repair and paint (complete)  
Front



### Bumper F

Scratch(es)  
Repair and paint (complete)  
Front



### Door FL

Scratch(es)  
Repair and paint (complete)  
Left



### Door FR

Dent(s)  
Paintless dent repair  
Right



### Door RR

Bad repair  
Repair and paint (complete)  
Right




**Outside rear-view mirror housing R**

Scratch(es)  
Replace and paint  
Right



**Roof**

Chemical polution  
Repair and paint (complete)  
Roof & others



**Windscreen**

Stone chip(s)  
Windscreen repair  
Front



**Wing RR**

Bad repair  
Repair and paint (complete)  
Right



## Tyres

### Front Left

Winter

225/60/18/104/H

Michelin

6.3 mm

### Front Right

Winter

225/60/18/104/H

Michelin

6.2 mm

### Rear Left

Winter

225/60/18/104/H

Michelin

4.9 mm

### Rear Right

Winter

225/60/18/104/H

Michelin

4.2 mm

## Checks

Certificate of Conformity	<b>No</b>	CO2 Emission	<b>0</b>
Digital maintenance	<b>Yes</b>	GPS storage	<b>Yes</b>
GPS storage	<b>HD</b>	Luggage cover	<b>Yes</b>
Number head rests	<b>5</b>	Number of charging cables (rapid charge)	<b>1</b>
Number of keys total	<b>2</b>	Reset to factory settings	<b>Yes, vehicle is reset to factory settings</b>
Service book	<b>N/A</b>	User's manual	<b>Yes</b>

### Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.