



SKODA OCTAVIA COMBI			
Vinnumber:	TMBJJ7NE8L0125699	Versionname:	2.0 CRTDI 110kW GreenTec Ambition
First Registrationdate:	29/01/2020	Fiscalpower:	
Expertise Mileage:	147739	Power Kw:	110
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2102
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	1	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Winter tyres:	205/55/16/91 H		
	Fr.L.	Continental: 4 mm	Fr.R.
	Re.L.	Continental: 4 mm	Re.R.
			Continental: 4 mm
Tyre profile depth FL			4.0
Tyre profile depth FR			4.0
Tyre profile depth RL			4.0
Tyre profile depth RR			4.0
Tyre size FL			205/55 R 16 91 H
Tyre size FR			205/55 R 16 91 H
Tyre size RL			205/55 R 16 91 H
Tyre size RR			205/55 R 16 91 H
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Winter
Tyre type RR			Winter
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			2443,46
Ignition key, Missing, Replace			350,09



Interior, Damaged, Acceptable	0,00
-------------------------------	------



Seat cover FR, Stain, Cleaning	29,16
--------------------------------	-------



Instrument panel, complete, Damaged, Acceptable	0,00
---	------



Seat cover FL, Stain, Cleaning	29,16
--------------------------------	-------



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)	406,19
--	--------



Bumper F, Scratch(es), Repair and paint (complete)	296,58
--	--------



Parking sensor F, Not functioning (well), Replace	148,82
---	--------



Wing RL, Dent(s), Acceptable	0,00
------------------------------	------



Luggage compartment cover, Missing, Replace	196,41
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Tailgate / Boot, Dent(s), Repair and paint (complete)	422,44
---	--------



Rear window, Scratch(es), Replace	0,00
-----------------------------------	------



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)	431,58
---	--------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------



