



Expertise

Protocol number: 46002250  
Order No. / Reference: 26418210  
Inspection date: 16 Jun 2026

Manufacturer: Ford  
VIN: WF0TK1E76NMA51490

Model: Mustang Mach-E



| Vehicle details                         |                                            |
|-----------------------------------------|--------------------------------------------|
| Manufacturer / Type / Model / Equipment |                                            |
| Ford Mustang Mach-E                     |                                            |
| Vehicle Identification number           | WF0TK1E76NMA51490                          |
| Mileage (Read)                          | 90,502 km                                  |
| First registration                      | 6 Dec 2022                                 |
| Number of holders                       | 1                                          |
| Next periodical technical inspection    | 12/2027                                    |
| (Report on hand)                        |                                            |
| Power / Engine displacement             | 100 kw /                                   |
| Fuel type / Cylinder                    | Electric / 0                               |
| Gearbox / Number of gears               | Direct drive / 1                           |
| Type of drive                           | Rear drive                                 |
| Type of vehicle                         | SUV                                        |
| Colour / colour code                    | Lucid Red TC/Red Carpet<br>TC/Rapid Red TC |
| Doors / Seats                           | 5 / 5                                      |
| Upholstery type                         | Artificial leather                         |
| Colour of upholstery                    | Black                                      |
| Vehicle with smoke odor                 | no                                         |



## Vehicle details

|                                                  |                                |                                |                                                            |
|--------------------------------------------------|--------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | Available / incomplete         | <b>Next maintenance in</b>     |                                                            |
| <b>Last service on / at</b>                      | 05/2025 at 61,481 km           |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                          | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                                | <b>Letter No.</b>              | GP494642                                                   |
| <b>Previous damage / Accident</b>                | Detectable                     | <b>Repainting</b>              | Detectable                                                 |
| <b>Inspection conditions</b>                     | sufficient                     | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | Not performed                  | <b>Engine function test</b>    | Performed                                                  |
| <b>Manufacturer key number/ type code number</b> | 8566 / BVE 00010               |                                |                                                            |
| <b>Emission standard</b>                         | 2017/1151;WLTP;reine Elektrofz | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,605 kg                       | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 225/60 R18 104V | Winter tyres on Light alloy | Goodyear     | 6mm / 6mm   |
| 2) | 225/60 R18 104V | Winter tyres on Light alloy | Goodyear     | 6mm / 6mm   |

### Additional tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 225/60 R18 104V | Summer tyres on Light alloy | Continental  | 5mm / 5mm   |
| 2) | 225/60 R18 104V | Summer tyres on Light alloy | Continental  | 5mm / 5mm   |

### Replacement

| Typ | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
|     | Tirefit   | Expiration date 09/2027 |              |             |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



## Equipment

## Standard equipment

- Acoustic Vehicle Alerting System (AVAS)
- Anti-lock braking system (ABS) (with electronic brake force distribution (EBD))
- Exterior mirrors painted in car color
- Tires: 7 J x 18 light alloy wheels (4) in 5-spoke design (with tires 225/60 R 18)
- Tires: Tire repair kit (maximum speed 80 km/h when used)
- Light-colored woven fabric headliner
- Electronic Stability Program (ESP)
- Electric front and rear windows with all-around closing function
- High Beam Assist
- Ford Co-Pilot360 including Ford Intelligent Drive Assist (Intelligent speed limiter with speed limit display - Pre-Collision Assist, Evasive Steering Assist - Blind Spot Assist with Cross Traffic Alert - Lane Keeping Assist - Traffic Jam Assist with Stop&Go function - Intelligent Adaptive Cruise Control (iACC))
- Front trunk with Ford MegaBox
- Heated windshield
- Transmission: 1-speed direct drive (Electronic Shifter (rotary switch for automatic transmission))
- rear window wiper
- Interior decor with grey decorative stitching (for seat upholstery, steering wheel, door interiors, carpet floor mats, center console and instrument panel)
- Intelligent Protection System (IPS) (Front airbag for driver and front passenger - Airbag between driver and front passenger - Knee airbag, driver's side - Head and shoulder airbags front and rear - Side airbags front and rear - 3-point seat belts at all seats, height-adjustable - Seat belt tensioners and force limiters front and outer rear seat row - Warning system for unfastened front seat belts)
- Charging cables: 2 charging cables for charging the high-voltage battery (Mode 3 charging cable (length 6 m) and home charging cable for standard household socket (length 6.7 m))
- Reading lamp at the back
- Media console with two USB ports
- Rear center armrest with two cup holders
- MyKey key system (individually programmable second key)
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Front and rear parking pilot system
- Pollen and dust filter
- Upholstery: Premium Sensico upholstery in leather look in black with grey decorative stitching
- Tire Pressure Monitoring System (TPMS)
- Reversing camera with reversing parking assistant
- Windscreen wipers with rain sensor (sensitivity adjustable)
- Keys: Classic car key and up to 4 digital keys (Phone as a Key) (Keyless Entry - also possible via door code or smartphone via FordPass App, Keyless Start via smartphone via FordPass App, start button or code)
- Towbar preparation kit (ESP trailer stabilization function)
- Electrically adjustable and heated exterior mirrors (with integrated turn signals, ambient lighting and blind spot information system including cross traffic alert) with emergency braking function when reversing out of parking spaces)
- third brake light
- Theft alarm system
- Driver information system with digital instrument panel, 10.2" screen diagonal (25.9 cm) (with range and speed display)
- Electric parking brake with auto hold function
- Ford EcoCoach (shows the efficiency of current driving behavior)
- FordPass Connect including eCall, live traffic information and Wi-Fi hotspot (real-time traffic information - Wi-Fi hotspot - eCall emergency call system: in the event of an accident, an emergency call is triggered and important data is transmitted)
- Flexible luggage compartment cover and luggage compartment lighting
- Heated rear window
- Rear spoiler
- Interior mirror, automatically dimming
- Intelligent Range (Intelligent Range provides a very precise and realistic estimate of battery range)
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Rear headrests (3) height adjustable
- Front headrests are height-adjustable
- LED headlights in projection lens design (automatically height-adjustable, with integrated daytime running lights)
- Steering wheel: Multifunction leather steering wheel, heated (in Sensico synthetic leather)
- Illuminated makeup mirrors in the driver's and passenger's sun visors
- Mustang LED taillights
- Fatigue warning
- One Pedal Drive (Pressing the pedal accelerates the vehicle, releasing it decelerates it. (Engine braking effect) The strength of the deceleration can be influenced by the selected driving mode.)
- Post-Collision Assist
- Radio accessories: Ford SYNC 4 (audio system with digital radio reception DAB/DAB+ (Digital Audio Broadcasting) - navigation system - Bluetooth hands-free system - sound system with 6 speakers - 15.5" touchscreen in center console (39.3 cm screen diagonal))
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Servotronic
- Seats: Front seats, individually and variably heated
- Seats: Comfort seats, front



- Seat: Rear seat backrests, foldable, 60:40 split
- Seats: Driver and front passenger seats, 6-way manually adjustable
- Power outlet: 12-volt connection at the front
- Pocket on the driver's and passenger's seat backrest
- Carpet floor mats front and rear, velour
- Electric door child safety lock
- Traffic sign recognition system
- Immobiliser

- Power outlet: 12-volt connection in the luggage compartment
- Phone: Inductive charging station for mobile devices (according to Qi standard, compatibility depends on the device)
- Lashing eyes in the luggage compartment
- Central locking system with overall locking function

#### Extra equipment

- Paint finish: Metallic
- Package: Technology Package 2 (as Technology Package 1, additionally with: - Panoramic roof - Electrically folding exterior mirrors with Mustang pony projection onto the ground - Premium Sensico upholstery in leather look, perforated, in black with grey decorative stitching - Front seats, 8-way electrically adjustable, with adjustable lumbar support and memory function)

#### Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |

#### Value reducing factors

| No. | Component group       | Description                                                                                             |
|-----|-----------------------|---------------------------------------------------------------------------------------------------------|
| 1   | Rear bumper           | Rear bumper - Scratch(es) - Loss in value                                                               |
| 2   | Sill - right side     | Sill - dent(s) - Smart repair                                                                           |
| 3   | Wheel / tyres         | Alloy rim - rear right side - Scratch(es) - Loss in value                                               |
| 4   | Boot lid / rear door  | Boot lid - Scratch(es) - Smart repair                                                                   |
| 5   | Front bumper          | Spoiler - Scratch(es) - Loss in value                                                                   |
| 6   | Misc.                 | Inspection / maintenance (Intervall alle 12 Monate/16000 km, letzter Eintrag bei 60000) - Due - Perform |
| 7   | Bonnet                | Bonnet (Verätzungen / mit Kratzer) - Paint defect - Paint                                               |
| 8   | Front bumper          | Front bumper (Zierleiste) - Deformed - Replace                                                          |
| 9   | Mudguard - right side | Mudguard - right side - Scratch(es) - Paint                                                             |

#### Wear and tear

| No. | Component group        | Description                             |
|-----|------------------------|-----------------------------------------|
| 1   | Body                   | Body - Scratch(es) - No deduction       |
| 2   | Vehicle glazing        | Windscreen - Stone chips - No deduction |
| 3   | Door - front left side | Door edge - Scratch(es) - No deduction  |
| 4   | Bonnet                 | Bonnet - Stone chips - No deduction     |

The vehicle shows signs of wear and tear commensurate with its age and use.



## Previous damages

| No. | Previous damage                                         | Extent of damage (Net) |
|-----|---------------------------------------------------------|------------------------|
| 1   | Front, Provided by user / customer, from 4 May 2026     | 1.499,59 €             |
| 2   | Underbody, Provided by user / customer, from 4 May 2026 | 4.667,56 €             |

## Repainting

| No. | Repainting                                                                                                       |
|-----|------------------------------------------------------------------------------------------------------------------|
| 1   | Door - rear right side, Door - front right side, Professionally carried out, Invoice of repair done Non-existent |

## Paint coat thickness measurement

|                        |        |                         |        |
|------------------------|--------|-------------------------|--------|
| Door - rear right side | 192 µm | Door - front right side | 221 µm |
|------------------------|--------|-------------------------|--------|

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

Der montierte Winterradsatz ist kein Bestandteil der Ausstattung.

ALPHABET



**Figure 1:** Diagonal front (left)

ALPHABET



**Figure 2:** Diagonal front (right)

ALPHABET



**Figure 3:** Diagonal rear (left)

ALPHABET



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN




Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



**Figure 31:** Misc.



**Figure 32:** Misc.




**Figure 33:** Misc.



**Damage 1:** Rear bumper: Rear bumper - Scratch(es) - Loss in value



**Damage 1:** Rear bumper: Rear bumper - Scratch(es) - Loss in value



**Damage 2:** Sill - right side: Sill - dent(s) - Smart repair



**Damage 2:** Sill - right side: Sill - dent(s) - Smart repair



**Damage 3:** Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value




**Damage 3:** Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



**Damage 4:** Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



**Damage 4:** Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



**Damage 5:** Front bumper: Spoiler - Scratch(es) - Loss in value



**Damage 5:** Front bumper: Spoiler - Scratch(es) - Loss in value



**Damage 5:** Front bumper: Spoiler - Scratch(es) - Loss in value




**Damage 5:** Front bumper: Spoiler - Scratch(es) - Loss in value



**Damage 7:** Bonnet: Bonnet (Verätzungen / mit Kratzer) - Paint defect - Paint



**Damage 7:** Bonnet: Bonnet (Verätzungen / mit Kratzer) - Paint defect - Paint



**Damage 7:** Bonnet: Bonnet (Verätzungen / mit Kratzer) - Paint defect - Paint



**Damage 7:** Bonnet: Bonnet (Verätzungen / mit Kratzer) - Paint defect - Paint




**Damage 8:** Front bumper: Front bumper (Zierleiste) - Deformed - Replace



**Damage 8:** Front bumper: Front bumper (Zierleiste) - Deformed - Replace



**Damage 8:** Front bumper: Front bumper (Zierleiste) - Deformed - Replace



**Damage 8:** Front bumper: Front bumper (Zierleiste) - Deformed - Replace




**Damage 9:** Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



**Damage 9:** Mudguard - right side: Mudguard - right side - Scratch(es) - Paint




**Damage 9:** Mudguard - right side: Mudguard - right side - Scratch(es) - Paint




**Repainting 1:** Door - rear right side, Door - front right side



**Repainting 1:** Door - rear right side, Door - front right side



**Repainting 1:** Door - rear right side, Door - front right side



**Repainting 1:** Door - rear right side, Door - front right side



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0TK1E76NMA51490

Hersteller / Modell: FORD FORD Mustang Mach-E

| Datum      | KM-Stand | Beschreibung                                                |
|------------|----------|-------------------------------------------------------------|
| 16.05.2025 | 61.481   | Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst |