



Expertise

Protocol number: 46565989
Order No. / Reference: 26716555
Inspection date: 13 Jul 2026

Manufacturer: Volkswagen

Model: Caddy Cargo 2.0 TDI BMT

VIN: WV1ZZZSK8PX079554



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Caddy Cargo 2.0 TDI BMT	
Vehicle Identification number	WV1ZZZSK8PX079554
Mileage (Read)	137,587 km
First registration	22 Jun 2023
Number of holders	1
Next periodical technical inspection	06/2027
(Report not on hand)	
Power / Engine displacement	75 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candyweiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Dark grey
Re-import	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	3,700 km
Last service on / at	01/2026 at 113,491 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS571945
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0603 / CMF 00371		
Emission standard	EURO6;WLTP;AQ;PI/CI; N1 II	fine dust sticker	
Permitted total weight	2,220 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R15 99H	Summer tyres on Steel rim with wheel cover	Hankook	4mm / 4mm
2)	205/65 R15 99H	Summer tyres on Steel rim with wheel cover	Hankook	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/50 R17 93V	Winter tyres on Light alloy	Bridgestone	3mm / 3mm
2)	205/50 R17 93V	Winter tyres on Light alloy	Bridgestone	3mm / 3mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/65 R15 99H	Summer tyres on Steel	Hankook	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartments: Glove compartment open
- Airbag, side and head airbags for driver and front passenger
- Exterior mirror housings and door handles in black, sliding door track in silver
- Floor coverings: Carpet in the driver's cab
- third brake light
- Roof rail/roof rack preparation
- Three-point automatic seat belts (with front belt height adjustment and electric belt tensioners)
- Deletion: Without rear window (sheet metal)
- ESP Electronic Stability Program with Brake Assist (incl. Anti-lock Braking System (ABS), Traction Control (ASR), (EDS and MSR))
- Electric windows, front
- Transmission: 6-speed transmission
- Rear wing door (asymmetrically divided) without window cutout
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Steering wheel: Multifunction steering wheel
- Air vents, front, in matte black
- Multifunction display "Plus"
- Multi-collision brake
- Fatigue detection
- Non-smoking version
- eCall emergency call system
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Radio "Composition Audio" with 20.96 cm (8.25 inch) touch color display (2 USB interfaces (Type C) in the center console, front - 4 speakers - mobile phone interface)
- Wheels, tires: Wheel covers
- Wheels/Tires: Tire pressure monitoring system
- Wheels/Tires: Steel wheels 6J x 15, in black
- Gearshift lever in plastic
- Sliding door, on the right in the passenger/cargo area
- Standard side panels in the cargo area
- Speed-sensitive power steering (Servotronic)
- Seats: Height adjustment for left seat, manual
- Sun visors without mirrors, with ticket pocket on the driver's side, plus airbag label on the sun visor
- Start-stop system (with brake energy recuperation)
- Telephone: Mobile phone interface
- Door trim and armrest in plastic
- Lashing points: 6 lashing points for securing cargo
- Warning tone and light for unfastened front seat belts
- Green thermal insulation glazing
- Additional dust protection seal on the outside
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Exterior mirrors: electrically adjustable
- Reinforced battery (70 Ah/ 420 A)
- Operating voltage 12 V
- Brake booster
- Cockpit panel, matte
- Three-phase generator 140 A
- Rear parking assist
- Electronic parking brake including auto-hold function
- Omission: Without additional child seat anchorage
- Automatic headlight control with daytime running lights
- Windows: Laminated glass front pane in heat-insulating glazing
- Cruise control system including speed limiter
- Halogen dual headlights-H7
- Heating and ventilation system in the driver's cab
- Interior lighting in the cargo area (1 light)
- Fuel fill quantity, standard fuel initial fill
- Diesel fuel system
- Headlight range control
- Center console with 2 universal cup holders
- Multifunctional camera
- Multimedia systems: 2 USB ports (Type C) in the center console, front
- Emergency braking assistant "Front Assist" (with pedestrian and cyclist detection)
- Upholstery: Fabric, "Double Grid" design
- "Composition Audio" radio with 20.96 cm (8.25 inch) color touchscreen
- Radio accessories: 4 speakers
- Radio accessories: Digital radio reception DAB+
- Wheels/Tires: 205/65 R 15 99 H XL, optimized for low rolling resistance
- taillights
- Windscreen wiper intermittent control with light sensor
- Keys for locking system: 2 remote control flip keys
- Side indicator lights
- dimmable interior safety mirror
- Seats: Left and right seats in the 1st row (including headrests)
- Lane keeping assistant "Lane Assist"
- Bumper in grey
- Partition wall (tall) without window
- First aid kit, warning triangle and high-visibility vest
- Prepared for "We Connect" and "We Connect Plus"
- Electronic immobilizer
- Central locking with remote control and interior operation



Extra equipment

- Electrically adjustable and heated exterior mirrors
- Window: Fixed side window in the cargo/passenger compartment, front right
- Rear window heating and rear window wiper (heated rear window - rear window wiper/washer system with interval function)
- Fog lights including cornering lights
- Package: Cool & Sound (Refrigerant R1234yf - Safety interior mirror, automatically dimming - Air Care Climatronic air conditioning with 2-zone temperature control and air purification function)
- Wheels/Tires: Spare wheel in driving tire size, steel (spare wheel in driving tire size, steel - on-board tools and jack)
- Floor coverings, rubber floor covering in the cargo area
- Rear wing door (asymmetrically divided) with window cutout
- Navigation system "Discover Media" (25.4 cm (10 inch) touch color display - streaming & internet - 2 USB interfaces (Type C) in the center console, front - glove compartment with lockable, illuminated flap - 4 speakers - mobile phone interface)
- Package: Winter package "Basic" (Seat heating for seats in the driver's cab, left and right, separately adjustable - Washer fluid level indicator with enlarged washer fluid reservoir - Heated windshield washer nozzles at the front)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Vehicle glazing	Rear window - Scratch(es) - Loss in value
2	Body	A-pillar - right side - Scratch(es) - Smart repair
3	Instrument panel	Centre console - front - Scratch(es) - Loss in value
4	Fog lamp	Fog lamp - front left side - Broken / torn - Replace
5	Bonnet	Bonnet - Dent / paintcoat damage - Smart repair
6	Door - front left side	Door - Dent / paintcoat damage - Smart repair

Wear and tear

No.	Component group	Description
1	Sill - left side	Sill - Scratch(es) - No deduction
2	2nd wheel set	Tyres - complete set - Worn - No deduction
3	Sliding door, right	Sliding door - dent(s) - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Vehicle jack



Repainting

No. Repainting

- 1 Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
- 2 Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - rear right side	179 µm	Door - front right side	199 µm
------------------------	--------	-------------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view




Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Damage 1: Vehicle glazing: Rear window - Scratch(es) - Loss in value



Damage 1: Vehicle glazing: Rear window - Scratch(es) - Loss in value



Damage 1: Vehicle glazing: Rear window - Scratch(es) - Loss in value



Damage 2: Body: A-pillar - right side - Scratch(es) - Smart repair



Damage 2: Body: A-pillar - right side - Scratch(es) - Smart repair



Damage 3: Instrument panel: Centre console - front - Scratch(es) - Loss in value



Damage 4: Fog lamp: Fog lamp - front left side - Broken / torn - Replace



Damage 4: Fog lamp: Fog lamp - front left side - Broken / torn - Replace



Damage 5: Bonnet: Bonnet - Dent / paintcoat damage - Smart repair



Damage 5: Bonnet: Bonnet - Dent / paintcoat damage - Smart repair



Damage 5: Bonnet: Bonnet - Dent / paintcoat damage - Smart repair



Damage 6: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 6: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 6: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Repainting 1: Door - rear right side



Repainting 1: Door - rear right side



Repainting 2: Door - front right side



Repainting 2: Door - front right side