



Expertise

Protocol number: 46595469
Order No. / Reference: 26741758
Inspection date: 14 Jul 2026

Manufacturer: Volkswagen
VIN: WVGZZAAZMD000341

Model: up!



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen up!	
Vehicle Identification number	WVGZZAAZMD000341
Mileage (Read)	94,566 km
First registration	4 May 2021
Number of holders	1
Fuel type	Petrol
Engine displacement / Cylinder	999 ccm / 3
Power	48 kW
Gearbox / Number of gears	Manual / 5
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Deep Black Perleffekt
Doors / Seats	5 / 4
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	8,700 km
Last service on / at	01/2026 at 88,201 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA649588
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / CMX 00004		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,330 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	165/70 R14 81T	All-season tyres on Steel rim with wheel cover	Fulda	6mm / 6mm
2)	165/70 R14 81T	All-season tyres on Steel rim with wheel cover	Fulda	7mm / 7mm

Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger (with passenger airbag deactivation)
- Exterior mirrors adjustable from inside
- Turn signals integrated into the side exterior mirrors
- third brake light
- Headliner in light grey
- Tachometer
- Electronic Stability Program (including hill start assist, ABS with brake assist, ASR, EBV and MSR)
- luggage compartment cover
- Luggage compartment floor adjustable to 2 heights and removable
- Glove compartment with flap
- rear window wiper
- Front headrests (integrated into the seat)
- Steering column with height adjustment
- Multifunction display "Plus" (with display of, among other things: - Outside temperature - Speed warning - Average consumption - Comfort - Average speed - Current consumption - Trip distance - Range - Driving time - Service - Gear recommendation (applies to vehicles with manual transmission and dual-clutch transmission DSG) - Time - Digital speedometer - Language - Digital oil temperature display - Auxiliary heater - Lights & visibility - Winter tires)
- Wheels: Tire Mobility Set (12-volt compressor and tire sealant)
- Rear bench seat, undivided, 2-seater, backrest asymmetrically split and foldable
- Seats: Driver's seat with height adjustment
- Start-stop system (with brake energy recuperation)
- Telephone interface
- Chrome interior door handle
- USB interface
- First aid kit, warning triangle and high-visibility vest
- Warning tone and light for unfastened seat belts front and rear
- Electronic immobilizer
- Central locking (without safe locking with remote control, 2 remote keys)
- Airbag, head airbag system including front side airbags (for front and rear passengers)
- Exterior mirror housings and door handles in body color
- Vehicle tool kit
- Internally ventilated brake discs
- Dash pad "black cube"
- Chrome trim around the left and right air vents (as well as the controls for the radio and air conditioning)
- Electric front windows
- Luggage compartment lighting
- Transmission: 5-speed manual transmission
- Handbrake lever handle in plastic
- Heated rear window
- Rear headrests (2) (lowerable)
- LED daytime running lights
- Makeup mirror in the passenger-side sun visor
- Upholstery: Cloth
- Radio "Composition Phone" (screen diagonal 12.7 cm - FM radio reception - MP3 - AUX-IN multimedia jack - Apple compatibility for USB interface - telephone interface - Bluetooth audio - hands-free system)
- Radio accessories: 2 speakers
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system (passive)
- Wheels: 4 steel wheels 5 J x 14 (wheel covers with Volkswagen logo in aluminum - tires 175/65 R 14 optimized for rolling resistance)
- electromechanical power steering
- Seats: Easy-Entry entry aid (on driver's side with memory function)
- 12V socket
- Phone accessory: maps + more dock (The flexible 3-arm holder for smartphones up to 14 cm (5.5 inches) in size is attached to the instrument panel above the radio via a clip and can be removed. A USB interface for charging and data transfer is integrated into the "maps + more dock")
- We Connect Go
- Green heat-insulating glazing (sides and rear)

Extra equipment

- Version with 4 doors including height-adjustable front seats (rear side windows can be opened - front seats with height adjustment)
- Wheels: 4 all-season tires 165/70 R 14
- Textile floor mats front and rear (with individual installation)
- "Climatronic" air conditioning system (allergen filter)
- Paint finish: Pearl effect
- Package: Winter package (electrically adjustable and heated exterior mirrors - aspherical exterior mirror on driver's side - fog lights and cornering lights - heated front seats)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door - dent(s) - Smooth repair work
2	Roof	Roof - dent(s) - Smooth repair work
3	Interior	Interior (Muffig) - Missing - Ozone treatment
4	Mudguard - right side	Mudguard - right side - Scratch(es) - Paint
5	Door - front right side	Door - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Mudguard - left side	Mudguard - left side - dent(s) - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Door - front left side	Door edge - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Damage 1: Door - front right side: Door - dent(s) - Smooth repair work



Damage 1: Door - front right side: Door - dent(s) - Smooth repair work



Damage 1: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Roof: Roof - dent(s) - Smooth repair work



Damage 2: Roof: Roof - dent(s) - Smooth repair work




Damage 2: Roof: Roof - dent(s) - Smooth repair work



Damage 4: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint




Damage 4: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage 4: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage 5: Door - front right side: Door - Scratch(es) - Paint



Damage 5: Door - front right side: Door - Scratch(es) - Paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVVZZZAAZMD000341

Hersteller / Modell: VOLKSWAGEN VW up!

Datum	KM-Stand	Beschreibung
14.01.2026	88.201	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges