



Expertise

Protocol number: 46621031
Order No. / Reference: 26617324
Inspection date: 21 Jul 2026

Manufacturer: Mercedes-Benz

Model: Vito 110 CDI Mixto Kompakt HA

VIN: W1V44770114119784



Vehicle details

Manufacturer / Type / Model / Equipment

Mercedes-Benz Vito 110 CDI Mixto Kompakt HA

Vehicle Identification number W1V44770114119784
Mileage (Read) 56,485 km
First registration 9 Jun 2022
Number of holders 1
Next periodical technical inspection 06/2026
(Report on hand)

Fuel type Diesel
Engine displacement / Cylinder 1,950 ccm / 4
Power 75 kW
Gearbox / Number of gears Manual / 6
Type of drive Rear drive
Type of vehicle Van

Colour / colour code Verkehrsblau
Doors / Seats 4 / 6
Upholstery type Cloth
Colour of upholstery Black

Re-import no
readiness to drive Roadworthy



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	-32 Tag(e)
Last service on / at	06/2024 at 29,257 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM178002
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2222 / BDX 00589		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,800 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 107H	All-season tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm
2)	225/55 R17 107H	All-season tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS, ESP, ASR, EBV, BAS
- Passenger side airbag
- ATTENTION ASSIST
- Outdoor temperature display
- Fixing points in the roof frame
- third brake light
- Front cupholder
- Diesel particulate filter and SCR
- Chassis: Standard chassis Plus
- Front left window fixed in SW/ cargo area sliding door
- Electric windows, driver/passenger
- Generator management
- Seatbelt warning device for driver and front passenger seat
- Lockable glove box
- HOLD function
- Interior lights in the rear
- Interior trim of cargo area, side
- Instrument cluster
- Headrests (2), front
- Mercedes-Benz emergency call system
- Breakdown management
- Tires: Premium protection tires (3 years)
- Headlights: halogen technology
- Crosswind Assist
- Start-stop function
- Cruise control
- Pre-installation for Remote Services Plus
- Windshield washer fluid level warning light
- Immobiliser

Extra equipment

- Upgrading/downgrading (upgrading to 3.05 t GVW)
- Driving light assistant (automatically switching on driving lights)
- Window front left fixed in SW/ sliding door (in conjunction with thermal glass)
- Fleet Comfort Package Z7K
- semi-automatic air conditioning system controlled by TEMPATIC
- Steering wheel adjustable for tilt and height
- Radio/Navigation: Multimedia DAB Digital Radio and Navigation System Audio 40 (7-inch LCD touchscreen - Apple CarPlay and Android Auto - Bluetooth 3.0 - Hands-free system - 2-way front speakers)
- Seats: 3-seater bench, 1st row
- Seats: Comfort driver's seat

- Screw-in towing eye front/rear
- Driver's side airbag
- Exterior mirrors, manually adjustable (2)
- Battery: fleece battery 12 V / 92 Ah
- Hill start assist
- Brake lights, adaptive
- Standard roof lining, pillars B to D
- Electronic tachometer
- HVO-capable vehicle
- Front right window fixed in SW/ cargo area sliding door
- Generator 14 V / 250 A
- Transmission: 6-speed manual
- Seatbelt warning device for driver's seat
- Boot lid
- Wooden floor (cargo area)
- Interior mirror
- Child safety locks on doors in the passenger compartment
- Communication module (LTE) for digital services
- Headlight range control
- Package: BlueEFFICIENCY
- Upholstery: Caluma fabric, black
- Wheels: Steel rims 6.5 J x 17
- Sliding door on the right, cargo/passenger compartment
- electromechanical power steering
- 12V socket
- Doors: active locking mechanism for sliding doors
- Warm air duct to the passenger compartment
- ASSYST maintenance interval indicator
- Central locking with radio remote control

- Overhead control unit Comfort in conjunction with air conditioning and driving light assistant
- Window in tailgate (with wiper/washer system)
- Front right window fixed in SW/ sliding door (in conjunction with thermal glazing)
- Rear camera not foldable
- Large fuel tank, approx. 70 liters
- Paint finish: Traffic blue
- Multifunctional steering wheel
- Rain sensor
- Tires: 225/55R17
- Tires: All-season tires
- High-resolution reversing camera with guide lines
- Seats: Passenger seat, two-seater
- Auxiliary heater, electric



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door edge - Scratch(es) - Smart repair
2	Misc.	Main inspection - Expired - Replace
3	Misc.	Inspection / maintenance - Due - Replace
4	Seat - front	Seat cover - left side - Broken / torn - Replace

Accident damages

No.	Accident
1	Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.



ALPHABET

Figure 1: Diagonal front (left)



ALPHABET

Figure 2: Diagonal front (right)



ALPHABET

Figure 3: Diagonal rear (left)



ALPHABET

Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.






Figure 27: Misc.




Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 2: Misc.: Main inspection - Expired - Replace



Damage 3: Misc.: Inspection / maintenance - Due - Replace




Damage 4: Seat - front: Seat cover - left side - Broken / torn - Replace




Damage 4: Seat - front: Seat cover - left side - Broken / torn - Replace



Accident 1: Side right




Accident 1: Side right




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1V44770114119784

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ Vito 110 CDI Mixto
Kompakt HA

Datum	KM-Stand	Beschreibung
19.06.2024	29.257	AU; Regelwartungsdienst