



Expertise

Protocol number: 46278560
Order No. / Reference: 26650722
Inspection date: 2 Jul 2026

Manufacturer: Ford

Model: Transit 330 L3H2 VA Trend

VIN: WF0KXXTTRKMD39101



Vehicle details

Manufacturer / Type / Model / Equipment

Ford Transit 330 L3H2 VA Trend

Vehicle Identification number WF0KXXTTRKMD39101

Mileage (Read) 204,481 km

First registration 7 Apr 2022

Number of holders 1

Next periodical technical inspection 06/2028
(Report on hand)

Power / Engine displacement 77 kw / 1,995 ccm

Fuel type / Cylinder Diesel / 4

Gearbox / Number of gears Manual / 6

Type of drive Front drive

Type of vehicle Van

Colour / colour code Frozen White

Doors / Seats 4 / 8

Upholstery type Cloth

Colour of upholstery Black

Vehicle with smoke odor no



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	15,000 km
Last service on / at	08/2025 at 188,907 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GH388284
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BNP 00452		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	3,365 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Summer tyres on Steel rim with wheel cover	Continental	4mm / 4mm
2)	235/65 R16 115R	Summer tyres on Steel rim with wheel cover	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	235/65 R16 115R C	Summer tyres on Steel	Continental	4 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Rubberized floor (in driver's cab and passenger compartment)
- roof, middle
- Double-leaf rear door with 180° opening angle (with window)
- Electronic Stability Program (ESP) with Traction Control (TSC)
- Lane Assist additionally with Lane Keeping Assist
- Windows, 2nd row: Side windows fixed, right and left
- Ford Easy Fuel
- Generator, high-performance version
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Paint finish: Solid color paint
- Steering column, adjustable in height and reach
- Fog light
- Emergency call assistant
- Front and rear parking pilot system
- Particulate filter: diesel particulate filter
- Wheels: Wheel trims
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Windscreen wipers with rain sensor
- Headlights with headlight assistant and day/night sensor
- Headlight low beam halogen headlights with daytime running lights
- Side protection strips
- Power steering
- Seats: Rear seat package 4 (3-seater bench narrow in 2nd row, removable, with three height-adjustable headrests, 3-point safety belts, with one ISOFIX mount - 3-seater bench wide in 3rd row)
- Immobiliser
- Central locking with remote control
- Second key, foldable, with remote control
- Driver and passenger side airbags
- Exterior mirrors, electrically adjustable and heated
- Battery: Battery life, programming of battery life to 10 minutes
- On-board computer
- Complete headliner
- Tachometer
- Third brake light
- Passenger compartment lighting with delay function
- Lane Keeping Assist (Lane Keeping Assist and Driver Alert including High Beam Assist)
- Front electric windows
- Heated windshield
- Cruise control
- Lockable glove compartment with lid
- Fuel tank 70 l
- Steering wheel: Faux leather steering wheel
- MyKey key system
- Emergency brake assist active (camera-based)
- Package: Technology Package 9 (Heated windscreen - Rain-sensing wipers - Front and rear parking sensors - Active emergency braking assist (camera-based) - Lane Keeping Assist with Driver Alert and High Beam Assist; additionally with Lane Departure Warning - Automatic Headlights with Day/Night Sensor - Cruise Control - Fog Lights - Ford Audio System 4" Multifunction Display)
- Sliding door: Sliding door, right
- Rear mud flaps
- Low side paneling
- Seat belts
- Start-stop system
- Rear bumper with integrated step
- front bumper
- Bumper center section partially painted in body color
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric
- Overhead storage compartment at the front, horizontal

Extra equipment

- Heat-insulating glazing, medium tint level of the side windows from the B-pillar back
- Package: Climate Package 3 ABKAD
- Package: Visible Package I ABSAH
- Seats in the passenger compartment: Seat backrests adjustable for tilt
- Wheels/Tires: Spare wheel, steel wheel
- Headlight dipped beam: with static cornering light (supplement to headlight dipped beam)
- Seats: Seat package 12 (driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - single passenger seat, 2-way adjustable (forward/backward, backrest) - height-adjustable headrests - interior armrest for driver - manual lumbar support (driver's seat) - Trend seat cover: fabric)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Side panel - dent(s) - Smart repair
2	Sliding door, right	Trim washable - lower - Broken / torn - Replace
3	Side panel - rear right side	Protection strip (hinten) - Scratched - Replace
4	Side panel - rear left side	Interior trim - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Protection strip (inkl. Radlauf) - Scratch(es) - No deduction
2	Rear bumper	Bumper - rear right side - Scratch(es) - No deduction
3	Boot lid / rear door	Rear door - left side - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Documents - Owner's manual

Repainting

No. Repainting

1 Boot lid / rear door, Side panel - rear right side, Professionally carried out

Paint coat thickness measurement

Boot lid / rear door	165 µm	Side panel - rear right side	194 µm
----------------------	--------	------------------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Damage 1: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 1: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 2: Sliding door, right: Trim washable - lower - Broken / torn - Replace



Damage 2: Sliding door, right: Trim washable - lower - Broken / torn - Replace




Damage 3: Side panel - rear right side: Protection strip (hinten) - Scratched - Replace



Damage 3: Side panel - rear right side: Protection strip (hinten) - Scratched - Replace



Damage 3: Side panel - rear right side: Protection strip (hinten) - Scratched - Replace



Damage 4: Side panel - rear left side: Interior trim - Broken / torn - Replace



Damage 4: Side panel - rear left side: Interior trim - Broken / torn - Replace



Boot lid / rear door: 165 µm



Side panel - rear right side: 194 µm