

Vehicle details

VIN	W1K118684 1N186462	Registration date	01/01/1900	Exterior Color	Unknown
Brand	MERCEDES	Licence Plate	2CSN438	Odometer	109 588 km
Model	CLA				

Inspection Details

Arrival Date	30/07/2026	Inspection ID	7099186	Inspection date	07/08/2026
Assign Date	30/07/2026	Fleet owner	LIZY Belgique	Inspection loc.	Parc Lizy



Generic equipment

Automated air-conditioning	✓
Rain and light sensor	✓
GPS system	✓
Front radars	✓
Alloy wheel rims	✓
Reversing camera	✓

Removable element

Spare wheel kit	✓
Emergency compressor kit	✓
Triangle	✓
Safety vest	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Fire extinguisher	✓

Technical Document

Service manual holder	✓
User manual	✓
First aid kit	✓
Adapter USB	✓
Spare key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres

Uniroyal 205/60/16 H All seasons 7.0 mm		Uniroyal 205/60/16 H All seasons 7.0 mm	
Uniroyal 205/60/16 H All seasons 7.0 mm		Uniroyal 205/60/16 H All seasons 7.0 mm	

Damages

1		Part	Bumper	Repair Time	-	Part Cost	-
		Position	Front	Repair Cost	-	Gross Cost	153.00€
		Damages	Scratched	Paint Time	1.80	Depreciation %	-
		Severity	-	Paint cost	153.00€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	153.00€
2		Part	Windscreen with rain sensor	Repair Time	2.00	Part Cost	689.09€
		Position	Front	Repair Cost	150.00€	Gross Cost	839.09€
		Damages	Stone impact	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	839.09€

DEKRA Automotive Solutions

3		Part	Fabric seat	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	68.00€
		Damages	Perforated	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	68.00€	Net Cost	68.00€
4		Part	Interior tailgate lining	Repair Time	-	Part Cost	-
		Position	Back	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
5		Part	Tailgate / Boot door	Repair Time	-	Part Cost	-
		Position	Back	Repair Cost	-	Gross Cost	170.00€
		Damages	Defective	Paint Time	2.00	Depreciation %	-
		Severity	-	Paint cost	170.00€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	170.00€
6		Part	Floor mat	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	-
		Damages	Perforated	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
7		Part	Carpet L	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	49.00€
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	49.00€	Net Cost	49.00€
8		Part	Interior cleaning	Repair Time	1.00	Part Cost	-
		Position	-	Repair Cost	75.00€	Gross Cost	75.00€
		Damages	Stained/dirty	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Cleaning	Flat Rate	75.00€	Net Cost	75.00€
9		Part	Door	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	-
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-

Summary Inspection

Gross Price	1,354.09€	Depreciation	-	Net Price	1,354.09€
-------------	-----------	--------------	---	-----------	-----------

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	75.00€	3.00	225.00€	-	-	225.00€
Paintwork	85.00€	3.80	323.00€	-	-	323.00€
Paint preparation	85.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	689.09€	-	-	689.09€
Flat Rate	117.00€	-	-	117.00€

Signatures
Signature Receiver
Signature Expert
Signature Customer / Driver

legrand



7/08/2026 8:35