



Expertise

Protocol number: 46833662
Order No. / Reference: 26657709
Inspection date: 30 Jul 2026

Manufacturer: Mazda

Model: 2 e-SKYACTIV G 90 M HYBRID Homura

VIN: JMZDJ6HC601452193



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mazda 2 e-SKYACTIV G 90 M HYBRID Homura	
Vehicle Identification number	JMZDJ6HC601452193
Mileage (Read)	15,027 km
First registration	7 Jun 2023
Number of holders	1
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	1,496 ccm / 4
Power	66 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Deep Crystal Blue Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	
Key is / should be	2 / 2	FZG documents	Registration and title documents unavailable
		Letter No.	HH046248
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	7118 / AIO 00040		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,540 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	185/60 R16 86H	Summer tyres on Light alloy	Toyo	5mm / 5mm
2)	185/60 R16 86H	Summer tyres on Light alloy	Toyo	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	185/65 R15 88T	Winter tyres on Steel	Falken	6mm / 6mm
2)	185/65 R15 88T	Winter tyres on Steel	Falken	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaautomatik

Standard equipment

- Front airbag (side airbags)
- Airbag head/shoulder airbags front and rear
- Rear Cross Traffic Alert (RCTA)
- Electrically folding exterior mirrors
- Exterior mirror caps in black
- third brake light
- Colored glazing
- Coming/leaving home light function
- Roof spoiler in car color
- Dynamic Stability Control (DSC) with Traction Control System (TCS)
- Wheels: 16" alloy wheels in black
- luggage compartment cover
- Transmission: 6-speed manual transmission
- rear window wiper
- Automatic air conditioning
- Headrests
- LED daytime running lights
- Steering wheel: Steering wheel control buttons for audio source and volume
- Steering column adjustable in height and length
- light sensor
- M-Hybrid System
- Mobility Kit
- Multi-information display
- Package: CONVENIENCE PACKAGE
- Radio: Mazda audio system with radio
- Radio accessories: Hands-free system with voice control and Bluetooth audio streaming
- Tire pressure monitoring system
- Rear seat backrest asymmetrically split and foldable (60:40)
- Seat belts: 3-point automatic seat belts for all seats
- Seats: Driver's seat height adjustable
- Seats: Heated seats for driver and front passenger
- Lane Change Assist Plus (BSM)
- Full LED headlights with LED light signature
- Central locking with remote control
- Airbag for driver and front passenger
- Anti-lock braking system
- Heated exterior mirrors
- Electrically adjustable exterior mirrors
- Hill Start Assist (HLA)
- City emergency brake assistant SCBS (Smart City Brake Support)
- Shark Fin roof antenna
- Digital tachometer, analog speedometer
- Rear parking sensors
- Vehicle dynamics control: G-Vectoring Control Plus (GVC)
- Electric windows, front and rear
- Cruise control system with speed limiter (Cruisematic)
- Back window, heater
- i-stop: Intelligent Mazda engine stop/start system
- Comfort turn signal function
- radiator grille honeycomb radiator grille
- Steering wheel: Leather steering wheel, leather gearshift knob and handbrake lever
- Steering wheel heating
- Reading lamps
- Red air vent rings
- Makeup mirrors for driver and front passenger
- Engine start/stop button
- Emergency Stop Signaling (ESS)
- Upholstery: Cloth
- Radio accessories: Android Auto and Wireless Apple CarPlay
- Rain sensor
- Rear view camera
- Rear side windows and rear window tinted
- Electric power steering
- Seats: Passenger seat height adjustable
- Seats: ISOFIX child seat anchors
- Lane Keeping Assist - Active with Steering Support (LAS)
- Exterior door handles painted in car color
- Electronic immobilizer

Extra equipment

- Paint finish: Metallic
- Navigation: Mazda SD navigation system (3D map display, high resolution - destination input via contact data from a smartphone possible - expandable with online services (fee applies) - arrow navigation additionally in the head-up display (optional with Sports-Line))



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) and the vehicle registration certificate Part 2 (title) were not available.
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Misc.	Inspection / maintenance - No evidence - No deduction
3	Fuel system	Tank cap - Scratch(es) - Smart repair
4	Bonnet	Insulation lining - Damage caused by marten / rodent - Replace
5	Front bumper	Front bumper - Scratch(es) - Paint
6	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear left side - Abrasion - No deduction
2	Rear bumper	Rear bumper - Abrasion - No deduction
3	Headlight	Headlight - right side - Stone chips - No deduction
4	Headlight	Headlight - left side - Stone chips - No deduction
5	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Radsatz ist nicht Bestandteil der vorliegenden Fahrzeugausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.





Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Damage 3: Fuel system: Tank cap - Scratch(es) - Smart repair



Damage 3: Fuel system: Tank cap - Scratch(es) - Smart repair



Damage 4: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace




Damage 5: Front bumper: Front bumper - Scratch(es) - Paint



Damage 5: Front bumper: Front bumper - Scratch(es) - Paint



Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint