



Expertise

Protocol number: 46069260  
Order No. / Reference: 26474408  
Inspection date: 18 Jun 2026

Manufacturer: Volkswagen

Model: Tiguan Allspace 2.0 TDI SCR DSG Life

VIN: WVGZZZ5N9NM172108



| Vehicle details                                 |                    |
|-------------------------------------------------|--------------------|
| Manufacturer / Type / Model / Equipment         |                    |
| Volkswagen Tiguan Allspace 2.0 TDI SCR DSG Life |                    |
| Vehicle Identification number                   | WVGZZZ5N9NM172108  |
| Mileage (Read)                                  | 163,085 km         |
| First registration                              | 8 Nov 2022         |
| Number of holders                               | 1                  |
| Next periodical technical inspection            | 10/2027            |
| (Report not on hand)                            |                    |
| Power / Engine displacement                     | 110 kw / 1,968 ccm |
| Fuel type / Cylinder                            | Diesel / 4         |
| Gearbox / Number of gears                       | Automatic / 7      |
| Type of drive                                   | Front drive        |
| Type of vehicle                                 | SUV                |
| Colour / colour code                            | Pure White (C9A)   |
| Doors / Seats                                   | 5 / 5              |
| Upholstery type                                 | Alcantara / cloth  |
| Colour of upholstery                            | Black-Anthracite   |
| Re-import                                       | no                 |
| readiness to drive                              | Roadworthy         |



## Vehicle details

|                                                  |                              |                                |                                                            |
|--------------------------------------------------|------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete     | <b>Next maintenance in</b>     | 8,400 km                                                   |
| <b>Last service on / at</b>                      | 01/2026 at 147,110 km        |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                        | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                              | <b>Letter No.</b>              | GM711555                                                   |
| <b>Previous damage / Accident</b>                | Detectable                   | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient                   | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | Not performed                | <b>Engine function test</b>    | Performed                                                  |
| <b>readiness to drive</b>                        | Roadworthy                   |                                |                                                            |
| <b>Manufacturer key number/ type code number</b> | 0603 / BZG 22349             |                                |                                                            |
| <b>Emission standard</b>                         | EURO6;WLTP;AP;PI/CI; M, N1 I | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,310 kg                     | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/55 R18 104W | Summer tyres on Light alloy | Continental  | 7mm / 7mm   |
| 2) | 235/55 R18 104W | Summer tyres on Light alloy | Continental  | 7mm / 7mm   |

### Additional tyres

| #  | Tyre size      | Type of tyre                                      | Manufacturer | Tread depth |
|----|----------------|---------------------------------------------------|--------------|-------------|
| 1) | 215/65 R17 99H | Winter tires (with run-flat tires) on Light alloy | Pirelli      | 6mm / 6mm   |
| 2) | 215/65 R17 99H | Winter tyres on Light alloy                       | Continental  | 5mm / 5mm   |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**



## Equipment



## Standard equipment

- Storage compartments in the overhead console
- Airbag, head airbag system including front side airbags (for front and rear passengers)
- Adaptive Cruise Control (ACC) "stop & go" with speed limiter
- Hill descent control
- Chrome applications on mirror adjustment switches, window regulator switches, door pull handles (interior door operation in matte chrome)
- Diesel particulate filter
- Display: Digital Cockpit Pro, multicolor, various selectable info profiles
- Electronic parking brake including Auto Hold function (Volkswagen's Auto Hold function is an extension of the electronic parking brake. The Auto Hold function prevents the vehicle from rolling away unintentionally when stationary or starting off, without the driver having to constantly apply the brakes. In this way, Auto Hold offers maximum driving comfort. - If the ABS wheel speed sensors detect rolling, the braking torque is automatically increased until the vehicle comes to a complete stop.)
- Pedestrian detection
- Luggage compartment floor height adjustable in 2 stages
- Transmission: 7-speed DSG
- Rear window heated
- Rear window wiper with intermittent function
- ISOFIX mounting points, also for i-Size child seats (device for attaching 2 child seats to the rear seats)
- Rear headrests (3)
- Front headrests (safety-optimized - adjustable lengthwise and height)
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- Illuminated makeup mirrors in the sun visors
- Fatigue detection
- Emergency braking assistant "Front Assist" (detects critical distance situations and helps to shorten the stopping distance - warns the driver visually and audibly in dangerous situations as well as with a preventive brake jolt)
- Radio
- Radio accessories: 8 speakers
- Rain sensor
- Wheels: AirStop tires 235/55 R 18, optimized for low rolling resistance
- Gearshift knob in leather
- Drawers under the front seats
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner (3 three-point automatic seat belts at the rear including belt tensioner for the outer rear seats - warning tone and light for unfastened seat belts at the front and rear)
- Seats: Lumbar support in the front
- Seats: Front seats with height adjustment
- Start-stop system with brake energy recuperation
- Airbag for driver and front passenger including knee airbag on the driver's side (passenger airbag deactivation - knee airbag on driver's side)
- Electrically adjustable and heated exterior mirrors
- Exterior mirror housings painted silver
- third brake light
- Chrome trim on the side windows
- Silver anodized roof rails
- Decorative inserts "Horizont Black" (for instrument panel and front door panels)
- Parking aid (acoustic warning signals for obstacles in the front and rear area)
- Electronic stability program with counter-steering support (including ABS, ASR, EDS, MSR and trailer stabilization)
- Automatic headlight control, with daytime running lights ("Leaving home" function and manual "Coming home" function)
- Electric windows front and rear
- High beam control Light Assist
- Windscreen made of laminated safety glass, heat and sound insulating
- Luggage compartment lighting (additional, removable and usable as a flashlight)
- Tailgate with electric opening and closing, adjustable opening angle
- Interior mirror automatically dimming
- LED license plate lighting
- Air conditioning "Air Care Climatronic" (3-zone temperature control - allergen filter - rear controls)
- Paint finish: Solid
- LED headlights
- Reading lights: 2 front and 2 rear
- Light in the front footwell
- front center armrest
- Non-smoking version (storage compartment and 12V socket at the front)
- Emergency call service (no registration required, service is activated upon delivery)
- Upholstery: Cloth
- Proactive occupant protection system in conjunction with "Front Assist"
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system
- Wheels: Tire Mobility Set omitted
- Wheels: Light alloy (4) "Frankfurt" 7 J x 18 (tires 235/55 R 18)
- Electromechanical power steering (speed-dependent control)
- Seats: Front passenger seat backrest folds down completely
- Seats: Comfort seats in the front (passenger seat backrest folds down completely - drawers under the front seats)
- Lane keeping assistant "Lane Assist"
- 12-volt power outlet (on the rear center console and in the luggage compartment)



- Power outlet: 2 USB-C ports on the front
- Bumpers in body color (lower bumper parts black)
- Textile floor mats front and rear
- Prepared for later activation: Navigation function "Discover Media" incl. "Streaming & Internet"
- Central locking without safe locking, with remote control and 2 remote keys

- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear

### Extra equipment

- Electrically adjustable, folding and heated exterior mirrors (with passenger-side mirror lowering function)
- Navigation system "Discover Media" incl. "Streaming & Internet"
- Package: Business Premium (DSG) (2 USB-C ports in the front, 1 USB-C charging port on the rear center console - Head-up display - Leather multifunction steering wheel, heated, with shift paddles - Automatically heated windshield washer nozzles in the front - Voice control - "Comfort" telephone interface with inductive charging function - Heated front seats)
- Seats: ergoActive front seats (front passenger seat backrest not foldable - ergoActive front seats height-adjustable, seat and backrest tilt adjustable, thigh support longitudinally adjustable - front lumbar support electrically adjustable and with massage function - seat center panels of the front seats and the outer rear seats in microfleece "ArtVelours" - top comfort seats in front)
- Airbag: Side airbags for the outer seats of the 2nd row.
- Anti-theft alarm system with safe locking (anti-theft alarm system with interior monitoring, backup horn and tow-away protection, central locking with safe locking, remote control and 2 remote folding keys)
- Foldable towbar (electric release)
- Mesh partition
- Package: Driver assistance package "Plus" without "Side Assist" and proactive occupant protection system (Driving assistant "Travel Assist", lane keeping assistant "Lane Assist" and "Emergency Assist" - parking steering assistant "Park Assist" incl. parking aid - traffic sign recognition)
- Park Assist system including parking aid
- Wheels: Light alloy (4) "Kingston" 7 J x 18
- Windows: Rear side windows and rear window tinted
- Wirelessly heated windshield (infrared-reflective)

### Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |
| readiness to drive   | The vehicle was roadworthy at the time of inspection.                                                                                                                        |

### Value reducing factors

| No. | Component group             | Description                                                           |
|-----|-----------------------------|-----------------------------------------------------------------------|
| 1   | Door - front left side      | Door - dent(s) - Smooth repair work                                   |
| 2   | Rear bumper                 | Rear bumper - Scratch(es) - Smart repair                              |
| 3   | Door - rear left side       | Door - Scratch(es) - Smart repair                                     |
| 4   | Side panel - rear left side | Side panel - Scratch(es) - Smart repair                               |
| 5   | Wheel / tyres               | Alloy rim - front left side - Scratched - Loss in value               |
| 6   | Instrument panel            | Air nozzle - centre - Damaged - Replace                               |
| 7   | Trim / covers               | Brightware / decorative strip (Stoßfänger hinten) - dent(s) - Replace |
| 8   | Door - rear left side       | Door - Dent / paintcoat damage - Repair and paint                     |
| 9   | Bonnet                      | Bonnet (Korrosion) - Dent / paintcoat damage - Repair and paint       |



## Wear and tear

| No. | Component group | Description                          |
|-----|-----------------|--------------------------------------|
| 1   | Rear bumper     | Spoiler - Scratch(es) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Previous damages

| No. | Previous damage                                    | Extent of damage (Net) |
|-----|----------------------------------------------------|------------------------|
| 1   | Rear, Provided by user / customer, from 5 Dec 2023 | 2.750,00 €             |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



**Damage 1:** Door - front left side: Door - dent(s) - Smooth repair work



**Damage 1:** Door - front left side: Door - dent(s) - Smooth repair work



**Damage 2:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage 2:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage 3:** Door - rear left side: Door - Scratch(es) - Smart repair



**Damage 3:** Door - rear left side: Door - Scratch(es) - Smart repair



**Damage 4:** Side panel - rear left side: Side panel - Scratch(es) - Smart repair




**Damage 4:** Side panel - rear left side: Side panel - Scratch(es) - Smart repair




**Damage 5:** Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



**Damage 5:** Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



**Damage 6:** Instrument panel: Air nozzle - centre - Damaged - Replace



**Damage 6:** Instrument panel: Air nozzle - centre - Damaged - Replace



**Damage 7:** Trim / covers: Brightware / decorative strip (Stoßfänger hinten) - dent(s) - Replace



**Damage 7:** Trim / covers: Brightware / decorative strip (Stoßfänger hinten) - dent(s) - Replace




**Damage 8:** Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 8:** Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 8:** Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 8:** Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 9:** Bonnet: Bonnet (Korrosion) - Dent / paintcoat damage - Repair and paint



**Damage 9:** Bonnet: Bonnet (Korrosion) - Dent / paintcoat damage - Repair and paint



**Damage 9:** Bonnet: Bonnet (Korrosion) - Dent / paintcoat damage - Repair and paint



**Damage 9:** Bonnet: Bonnet (Korrosion) - Dent / paintcoat damage - Repair and paint