



FORD KUGA

Vinnumber:	WF0FXXWPMFL59967	Versionname:	1.5 EcoBlue 88kW Aut. ST-Line X
First Registrationdate:	20/10/2020	Fiscalpower:	
Expertise Mileage:	146784	Power Kw:	88
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2112
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

225/60/18/104 V				
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				3.0
Tyre profile depth RL				5.0
Tyre profile depth RR				4.0
Tyre size FL				225/60 R 18 104 V
Tyre size FR				225/60 R 18 104 V
Tyre size RL				225/60 R 18 104 V
Tyre size RR				225/60 R 18 104 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2952,42
Interior, Damaged, Acceptable	0,00



Engine insulation, Broken, Replace	136,70
------------------------------------	--------



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)	385,64
--	--------



Bumper moulding F, Scratch(es), Repair and paint (complete)	161,81
---	--------




Door FL, Bad repair, Repair and paint (complete)	534,95
--	--------




Door RL, Bad repair, Repair and paint (complete)	534,95
--	--------



Door trim FL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Alloy rim RL, Scratch(es), Repair and paint (complete)	133,03
--	--------



Alloy rim FL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)	161,81
--	--------



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)

385,64



Wing RR, Bad repair, Repair and paint (complete)

517,89



Alloy rim RR, Scratch(es), Acceptable

0,00



Roof, Chemical polution, Acceptable

0,00

