



Expertise

Protocol number: 46090354  
Order No. / Reference: 26434655  
Inspection date: 22 Jun 2026

Manufacturer: Skoda  
VIN: TMBJU8NXXPY098155

Model: Octavia Combi 2.0 TSI DSG RS



| Vehicle details                         |                               |
|-----------------------------------------|-------------------------------|
| Manufacturer / Type / Model / Equipment |                               |
| Skoda Octavia Combi 2.0 TSI DSG RS      |                               |
| Vehicle Identification number           | TMBJU8NXXPY098155             |
| Mileage (Read)                          | 132,746 km                    |
| First registration                      | 17 Apr 2023                   |
| Number of holders                       | 1                             |
| Next periodical technical inspection    | 04/2026                       |
| (Report not on hand)                    |                               |
| Power / Engine displacement             | 180 kw / 1,984 ccm            |
| Fuel type / Cylinder                    | Petrol / 4                    |
| Gearbox / Number of gears               | Automatic / 7                 |
| Type of drive                           | Front drive                   |
| Type of vehicle                         | Station wagon                 |
| Colour / colour code                    | Black Magic Pearlescent (F9R) |
| Doors / Seats                           | 5 / 5                         |
| Upholstery type                         | Cloth                         |
| Colour of upholstery                    | Black-Red                     |
| Re-import                               | no                            |
| Vehicle with smoke odor                 | no                            |
| readiness to drive                      | Roadworthy                    |



## Vehicle details

|                                                  |                                     |                                |                                                            |
|--------------------------------------------------|-------------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete            | <b>Next maintenance in</b>     | 9,600 km                                                   |
| <b>Last service on / at</b>                      | 11/2025 at 116,928 km               |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                               | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                                     | <b>Letter No.</b>              | GQ561976                                                   |
| <b>Previous damage / Accident</b>                | Detectable                          | <b>Repainting</b>              | Detectable                                                 |
| <b>Inspection conditions</b>                     | Conditional: Light/moisture/dirt    | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | short drive on the company premises | <b>Engine function test</b>    | Performed                                                  |
| <b>readiness to drive</b>                        | Roadworthy                          |                                |                                                            |
| <b>Manufacturer key number/ type code number</b> | 8004 / AVC 00591                    |                                |                                                            |
| <b>Emission standard</b>                         | EURO6;WLTP;AP;PI/CI; M, N1 I        | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,040 kg                            | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 225/45 R18 95Y | Summer tyres on Light alloy | Continental  | 5mm / 5mm   |
| 2) | 225/45 R18 95Y | Summer tyres on Light alloy | Continental  | 5mm / 5mm   |

### Additional tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 225/45 R18 95V | Winter tyres on Light alloy | Pirelli      | 4mm / 4mm   |
| 2) | 225/45 R18 95V | Winter tyres on Light alloy | Pirelli      | 5mm / 5mm   |

### Replacement

| Typ | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
|     | Tirefit   | Expiration date 01/2027 |              |             |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



## Equipment

## Standard equipment

- Storage compartment in the luggage compartment with cargo element
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Ambient lighting (dashboard, front trim strips and footwell with selectable color climate) in the interior as well as logo projector on the outside)
- Automatically dimming exterior mirror (driver's side)
- Electrically adjustable and heated exterior mirrors
- Heated windshield washer nozzles including 5l washer fluid reservoir
- Glasses compartment in the headliner
- AERO roof rails in gloss black
- Digital Cockpit Plus
- Third brake light
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control system
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- Interior mirror automatically dimming
- Kessy, keyless entry and start-stop system
- Child safety lock for the rear doors and windows
- Removable boot cover
- Paint finish: Special paint finish, solid color
- LED fog lights
- LED license plate lights
- LED matrix headlights and dynamic high beam assist (AFS)  
(Dynamic and automatic headlight range control - headlight cleaning system including washer fluid level control)
- Rear center armrest with pass-through option
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Fatigue detection
- Pedals in stainless steel look
- Progressive steering
- Radio accessories: 2 USB-C ports on the front
- Radio accessories: Bluetooth hands-free system
- Radio accessories: SmartLink (Apple CarPlay - Android Auto)
- Tire pressure monitoring
- Tire mobility kit (tire repair spray incl. compressor)
- Seat belts (Three three-point seat belts in the rear)
- Safety lights in the front side doors
- Seats: Height-adjustable driver and passenger seats (including lumbar support)
- Storage compartments (storage compartments in the front door panels with 1.5l bottle holders, storage compartments in the rear door panels with 0.5l bottle holders, storage compartments in the doors with felt lining)
- Airbag, head airbags
- Airbag: Center airbag front
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Center section of the dashboard with microfiber cover in black and red decorative stitching
- Electrically folding exterior mirrors
- Hill start assist
- Hydraulic brake assist (HBA)
- black headliner
- Dark Carbon decorative trim
- Tachometer
- Electro-hydraulic front axle differential lock (VAQ)
- Electronic transverse differential lock (XDS+)
- Driving profile selection
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- Rear spoiler
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger, and with anti-allergen filter & activated carbon filter)
- LED taillights in crystal glass look and animated turn signals
- LED headlights with LED daytime running lights
- Remote release of the rear seat backrests in the trunk
- Steering wheel: height and reach adjustable
- Steering wheel: Leather steering wheel in sport design with multifunction buttons including shift paddles (with decorative stitching in red or grey - infotainment and driver assistance system operation)
- Front and rear parking sensors
- Upholstery: Cloth
- Radio: Bolero music system with 10" display
- Radio accessories: 8 speakers
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Voice control
- Rain sensor and driving light assistant ((Easy Light Assist) (Tunnel light, Coming Home, Leaving Home))
- Wheels: 18" Comet alloy wheels, black (7.5J x 18, ET 48 with 225/45 R18 tires)
- Seats: Heated front seats
- Seats: Rear seat backrest split 60:40, foldable
- Seats: Sports seats with integrated headrests in the front and height-adjustable headrests in the rear.



- SKODA Care Connect (SOS emergency call function (eCall+ including automatic activation in the event of an accident with airbag deployment) - Mobility service (connection option for rapid assistance in case of breakdown) - Information service (connection option to the hotline for all questions relating to vehicle functions) - Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level)
- Lashing eyes in the trunk
- Central locking including remote control integrated into the key and EASY Start
- Speed limiter
- Lane keeping assistant (Lane Assist)
- 12V socket in the trunk
- Sunset (rear window and rear side windows tinted dark)
- Telephone: Phonebox with inductive charging function (connection via external antenna)
- Phone: Wireless SmartLink for Apple CarPlay
- Textile floor mats
- Front door sill trims
- Immobiliser

### Extra equipment

- Paint finish: Pearl effect
- Package: Infotainment package Business Columbus (Style, RS) DSG (Columbus navigation system - Infotainment Online (3-year term), online map updates: for navigation, traffic situation, petrol stations and parking space search - 3 USB charging ports - Head-Up Display - Adaptive Cruise Control (ACC) - Traveller Assist system: - Traffic sign recognition - Adaptive Lane Keeping Assist - Emergency and traffic jam assist - Capacitate steering wheel with Hands Off Detection)

### Brief expert findings

|                      |                                                                                                                                                                                                                                      |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)                                                         |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.                                                            |
| Inspection           | A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive           | A short maneuvering and shunting exercise was carried out on the company premises.                                                                                                                                                   |
| Engine function test | An engine test run was performed.                                                                                                                                                                                                    |
| readiness to drive   | The vehicle was roadworthy at the time of inspection.                                                                                                                                                                                |

### Value reducing factors

| No. | Component group             | Description                                   |
|-----|-----------------------------|-----------------------------------------------|
| 1   | Side panel - rear left side | Side panel - dent(s) - Smooth repair work     |
| 2   | Misc.                       | Main inspection - Expired - Replace           |
| 3   | Door - rear left side       | Door - Dent / paintcoat damage - Smart repair |
| 4   | Bonnet                      | Bonnet (Und kratzer) - Paint defect - Paint   |

### Wear and tear

| No. | Component group | Description                             |
|-----|-----------------|-----------------------------------------|
| 1   | Vehicle glazing | Windscreen - Stone chips - No deduction |
| 2   | Body            | Body - Scratch(es) - No deduction       |

The vehicle shows signs of wear and tear commensurate with its age and use.



## Previous damages

### No. Previous damage

Extent of  
damage (Net)

1 Front, Provided by user / customer

## Repainting

### No. Repainting

1 Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent

## Paint coat thickness measurement

Side panel - rear right side 336 µm

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.





Figure 24: Misc.




**Figure 25:** Misc.




**Figure 26:** Misc.




**Damage 1:** Side panel - rear left side: Side panel - dent(s) - Smooth repair work




**Damage 1:** Side panel - rear left side: Side panel - dent(s) - Smooth repair work




**Damage 1:** Side panel - rear left side: Side panel - dent(s) - Smooth repair work




**Damage 3:** Door - rear left side: Door - Dent / paintcoat damage - Smart repair



**Damage 3:** Door - rear left side: Door - Dent / paintcoat damage - Smart repair




**Damage 3:** Door - rear left side: Door - Dent / paintcoat damage - Smart repair



**Damage 3:** Door - rear left side: Door - Dent / paintcoat damage - Smart repair



**Damage 4:** Bonnet: Bonnet (Und kratzer) - Paint defect - Paint



**Damage 4:** Bonnet: Bonnet (Und kratzer) - Paint defect - Paint



**Damage 4:** Bonnet: Bonnet (Und kratzer) - Paint defect - Paint



Damage 4: Bonnet: Bonnet (Und kratzer) - Paint defect - Paint



Damage 4: Bonnet: Bonnet (Und kratzer) - Paint defect - Paint



Damage 4: Bonnet: Bonnet (Und kratzer) - Paint defect - Paint




Damage 4: Bonnet: Bonnet (Und kratzer) - Paint defect - Paint

Anlage 3 zum Rückgabeprotokoll vom: \_\_\_\_\_  
zurückgegebenes Fahrzeug (amtl. Kennzeichen): LB-F194  
Folgende Schäden sind während der Laufzeit entstanden:

| Lfd. Nr. | Schadensbeschreibung in Stichworten / Schadenszeitpunkt                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1        | <p>Stoßstange zerkratzt, Scheinwerfer gebrochen</p> <p>Schadensmeldung an Leasinggesellschaft erfolgt: <input type="radio"/> ja <input checked="" type="radio"/> nein<br/>Rechnungskopie an Leasinggesellschaft gesandt: <input type="radio"/> ja <input checked="" type="radio"/> nein<br/>Falsch nein, Rechnungskopie bzw. Gutachten innerhalb einer Woche an Leasinggesellschaft schicken<br/>Wertminderung lt. Gutachten (wenn bekannt): _____ EUR</p> <p>Schadensart<br/><input checked="" type="radio"/> Kaskoschaden (selbstverursacht) <input type="radio"/> Haftpflichtschaden (fremdverursacht)</p> <p>Reparatur<br/><input checked="" type="radio"/> Reparatur durchgeführt <input type="radio"/> Reparatur gesteuert durch _____<br/><input type="radio"/> Reparatur nicht durchgeführt <input checked="" type="radio"/> Leasinggesellschaft *<br/><input type="radio"/> Mitarbeiter <input checked="" type="radio"/> Zurich Versicherung</p> |
| 2        | <p>Tür, hinten rechts Delle</p> <p>Schadensmeldung an Leasinggesellschaft erfolgt: <input type="radio"/> ja <input checked="" type="radio"/> nein<br/>Rechnungskopie an Leasinggesellschaft gesandt: <input type="radio"/> ja <input checked="" type="radio"/> nein<br/>Falsch nein, Rechnungskopie bzw. Gutachten innerhalb einer Woche an Leasinggesellschaft schicken<br/>Wertminderung lt. Gutachten (wenn bekannt): _____ EUR</p> <p>Schadensart<br/><input checked="" type="radio"/> Kaskoschaden (selbstverursacht) <input type="radio"/> Haftpflichtschaden (fremdverursacht)</p> <p>Reparatur<br/><input checked="" type="radio"/> Reparatur durchgeführt <input type="radio"/> Reparatur gesteuert durch _____<br/><input type="radio"/> Reparatur nicht durchgeführt <input checked="" type="radio"/> Leasinggesellschaft *<br/><input type="radio"/> Mitarbeiter <input checked="" type="radio"/> Zurich Versicherung</p>                     |
| 3        | <p>Schadensbeschreibung in Stichworten / Schadenszeitpunkt</p> <p>Schadensmeldung an Leasinggesellschaft erfolgt: <input type="radio"/> ja <input checked="" type="radio"/> nein<br/>Rechnungskopie an Leasinggesellschaft gesandt: <input type="radio"/> ja <input checked="" type="radio"/> nein</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |

Previous damage 1: Front



Previous damage 1: Front



**Previous damage 1: Front**



**Repainting 1: Side panel - rear right side**



**Repainting 1: Side panel - rear right side**



**Side panel - rear right side: 336 µm**



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBJU8NXXPY098155  
Hersteller / Modell: SKODA SKODA Octavia Combi 2.0 TSI DSG RS

| Datum      | KM-Stand | Beschreibung                                                                                                                                                                                                                                     |
|------------|----------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 25.03.2026 | 129.510  | Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne                                                                                           |
| 13.11.2025 | 116.928  | Getriebeöl ern/prüfen; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern                                                                                                           |
| 07.07.2025 | 104.211  | Batterie ern; Systemtest/Eigendiagnose                                                                                                                                                                                                           |
| 18.03.2025 | 89.195   | Bremsflüssigkeit; Bremsflüssigkeit ern; Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Ölwechsel - Hinterachse; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges                                                            |
| 25.07.2024 | 59.069   | Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern |
| 18.12.2023 | 30.943   | Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges                                                                                                                                                                         |