



Expertise

Protocol number: 46489002
Order No. / Reference: 26535270
Inspection date: 14 Jul 2026

Manufacturer: Opel

Model: Vivaro 1.5 D L

VIN: VXEVAYHVMNZ009357



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Vivaro 1.5 D L	
Vehicle Identification number	VXEVAYHVMNZ009357
Mileage (Read)	98,151 km
First registration	31 Mar 2022
Number of holders	1
Next periodical technical inspection	03/2027
Power / Engine displacement	88 kw / 1,499 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	TYPE HABILLAGE EXTERIEUR METALLISEE VERNIS
Doors / Seats	4 / 9
Upholstery type	Cloth
Colour of upholstery	Grey-Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	36,600 km
Last service on / at	10/2025 at 82,025 km		
Key is / should be	1 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ633226
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	3003 / BAX 00207		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,790 kg	Empty weight	

Tyres			
Mounted tyres			
#	Tyre size	Type of tyre	Tread depth
1)	215/65 R16 109T	All-season tyres on Steel	4mm / 4mm
2)	215/65 R16 109T	All-season tyres on Steel	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Storage compartments • Driver and passenger side airbags • Anti-lock braking system (ABS) with cornering brake control and brake assist • Exterior mirror housings in black • On-board computer • Diesel particulate filter, maintenance-free • Three-point seat belts in all seats • Windows: Side windows in the 2nd row, fixed • Speed controller and limiter • Tailgate, glazed • Child safety lock, mechanical, 2nd row of seats • Paint finish: Solid color paint • Steering column, adjustable for reach and height • Rear fog lights with integrated reversing lights • Radio accessories: Digital radio reception DAB+ (Digital Audio Broadcasting) • Wheels: Steel wheels 7 J x 16 with wheel hub cover • Side protection strips • Seats: Meltem fabric seats (9-seater) • Start/Stop System • Daytime running light • Doors: Sliding door, passenger side • Full glazing • Heat-insulating glazing, tinted • Ignition keys (2), both foldable | <ul style="list-style-type: none"> • ABS including brake assist and adaptive brake light • Airbag: Side airbag, 1st row of seats • Exterior mirrors, electrically adjustable, heated and manually folding • Hill Start Assist • third brake light • Tachometer • Electronic Stability Program (ESP Plus) • Electric front windows • Transmission: 6-speed transmission • Interior mirror, manually dimmable • Air conditioning, front with particle and odor filter • Steering wheel: Comfort steering wheel (PU), flattened at the bottom • Radio BT with Graphic Info Display • Tire pressure monitoring system • Wheels: Tire repair kit • Side impact protection • Speed-sensitive power steering • Sun visors, driver and passenger • 12-volt power outlet in the center console • Traction control with engine and brake intervention (TC Plus) • Electronic immobilizer • Central locking with remote control |
|---|--|

Extra equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • All-season tyres • Paint finish: Metallic • Radio: Multimedia Navi Pro with 7" touches | <ul style="list-style-type: none"> • Air conditioning: Auxiliary air conditioning, rear • Parkpilot, rear parking aid (with acoustic warning signal when reversing) |
|--|---|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Gearbox	Gearbox - Leaking - Perform diagnosis
2	Headlight	Headlight - right side (Leuchtmittel defekt) - Defective - Perform diagnosis
3	Bonnet	Radiator grille - Stone chips - Smart repair
4	Interior	Interior - Soiled - Clean
5	Front bumper	Front bumper (unpainted) - Damaged - Smart repair
6	Multimedia system	Radio - Non-operational - Perform diagnosis
7	Sliding door, right	Sliding door - Scratched - Smart repair
8	Side panel - rear left side	Side panel - Dent / paintcoat damage - Smart repair

Missing parts

Description

Equipment - Tirefit complete

Equipment - Vehicle key

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 26 Aug 2025	2.778,66 €

Repainting

No. Repainting

1 Side panel - rear right side

Paint coat thickness measurement

Side panel - rear right side 733 µm |

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.



Damage 1: Gearbox: Gearbox - Leaking - Perform diagnosis



Damage 1: Gearbox: Gearbox - Leaking - Perform diagnosis



Damage 2: Headlight: Headlight - right side (Leuchtmittel defekt) - Defective - Perform diagnosis




Damage 3: Bonnet: Radiator grille - Stone chips - Smart repair



Damage 3: Bonnet: Radiator grille - Stone chips - Smart repair




Damage 4: Interior: Interior - Soiled - Clean



Damage 4: Interior: Interior - Soiled - Clean



Damage 4: Interior: Interior - Soiled - Clean



Damage 5: Front bumper: Front bumper (unpainted) - Damaged - Smart repair



Damage 5: Front bumper: Front bumper (unpainted) - Damaged - Smart repair



Damage 5: Front bumper: Front bumper (unpainted) - Damaged - Smart repair



Damage 6: Multimedia system: Radio - Non-operational - Perform diagnosis




Damage 7: Sliding door, right: Sliding door - Scratched - Smart repair



Damage 7: Sliding door, right: Sliding door - Scratched - Smart repair



Damage 7: Sliding door, right: Sliding door - Scratched - Smart repair



Damage 7: Sliding door, right: Sliding door - Scratched - Smart repair



Damage 8: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 8: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 8: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 8: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair




Damage 8: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 8: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 8: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 8: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Missing part 1: Equipment: Tirefit complete - Missing - Replace



Missing part 2: Equipment: Vehicle key - Missing - Replace



Repainting 1: Side panel - rear right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VXEVAHYHVMNZ009357
Hersteller / Modell: OPEL OPEL Vivaro 1.5 D L

Datum	KM-Stand	Beschreibung
14.02.2026	91.533	Systemtest/Eigendiagnose
02.10.2025	82.025	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
25.03.2025	66.560	Batterie ern
19.03.2025	66.329	HU + AU
03.03.2025	65.700	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Reparatur Sonstiges; Wartung Sonstiges
18.12.2024	61.792	Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten
23.05.2024	44.768	Systemtest/Eigendiagnose
22.02.2024	38.543	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges