

APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	PEUGEOT
Model / version:	308 SW
Vin:	VR3FRHNPLNY637495
Plate:	
Mileage:	64082
First registration:	08/12/2022
Color:	Perla zwart





ADDITIONAL INFORMATION





Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES





VIN INFORMATION

depuis 10.22 16793	3-ème période 2022/avant 3-ème période 2024	3E PERIODE 2021/2023
avertisseur à deux tons	climatisation automatique	condenseur de 19,3 dm² et de 12 mm d'épaisseur
liquide de climatisation R1234YF	Keyless-Go	rétroviseurs électrique, rabattables et chauffants
rétroviseur int jour/nuit automatique	avertisseur de fatigue	système de navigation
6 haut-parleurs	instruments digitaux	Touchscreen 10"
aide au parking ar	garnissage tissu	équipement Active
volant en cuir multifonctions	Peugeot Connect Assistance	sièges av Confort
1199 cc (1,2 L) 81 KW HNP EB2ADT	radiateur de 28 dm² et de 18 mm d'épaisseur "F1"	6 vitesses MB6
suspension normale	système de freinage automatique avec caméra et radar (AEBS3)	colonne de direction réglable en profondeur
barre stabilisatrice av 27.500 Nm	205/55 R 16 .. V	7 J x 16
alternateur 120 A	ventilateur électrique 95 W	enjolveurs de roue 16"
5 portes (Wagon)	batterie 70 Ah EFBC	grille de calandre Perl noir
2 couches métallisée		

EQUIPMENT

Board computer:	Central locking:
-----------------	------------------

8/25/26, 2:40 PM

Appraisal report | 2CVF311

Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	3 mm			All-seasons		?
Front right	3 mm			All-seasons		?
Rear left	3 mm			All-seasons		?
Rear right	3 mm			All-seasons		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Grill	Broken
3	Wheel cover FL	Scratch(es)
4	Wheel cover FL	Scratch(es)
5	Bumper moulding R	Scratch(es)
6	Bumper R	Scratch(es)
7	Wheel cover RR	Scratch(es)
8	Wing RR	Dent(s) and scratch(es)
9	Wheel cover FR	Scratch(es)

Total: 8

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Damaged	✓	✗	✗


Total: 1

DAMAGES DETAILS

2 - Grill - Broken



3 - Wheel cover FL - Scratch(es)



4 - Wheel cover FL - Scratch(es)



5 - Bumper moulding R - Scratch(es)



6 - Bumper R - Scratch(es)



7 - Wheel cover RR - Scratch(es)



8 - Wing RR - Dent(s) and scratch(es)



9 - Wheel cover FR - Scratch(es)



1 - Bodywork - Damaged - Renta®

