



Expertise

Protocol number: 46373607
Order No. / Reference: 26445539
Inspection date: 7 Jul 2026

Manufacturer: Ford

Model: S-Max 2.0 EcoBlue Aut. TITANIUM

VIN: WF0JXXWPCJNS01562



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford S-Max 2.0 EcoBlue Aut. TITANIUM	
Vehicle Identification number	WF0JXXWPCJNS01562
Mileage (Read)	169,165 km
First registration	3 May 2022
Number of holders	1
Next periodical technical inspection	05/2027
(Report on hand)	
Power / Engine displacement	140 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Frost-Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Grey
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	22,000 km
Last service on / at	02/2026 at 162,636 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GK793774
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BQR 00323		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,555 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	235/55 R17 103V	Winter tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103Y	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	235/55 R17 103Y	Summer tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Power outlet: 12-volt connection in the luggage compartment and in the center console
- LED daytime running lights
- Traffic sign recognition system
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats
- Cigarette lighter
- Ambient lighting at the front
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Hill start assist
- roof console
- Diesel particulate filter (DPF)
- Electronic Shifter
- Lane keeping assist including lane keeping assist and driver fatigue warning
- Electronic parking brake
- Ford EasyFold: 2nd row seat backrests fold down electrically at the touch of a button.
- luggage compartment cover
- Cruise control system with intelligent speed limiter
- Back window, heater
- Interior lighting with delay circuit
- Intelligent security system
- Electric child safety lock
- Paint finish: Solid
- Steering wheel: Multifunction leather steering wheel
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Fog light
- Emergency brake light
- Front and rear parking pilot system
- Tire repair kit
- LED taillights
- Headlight dipped beam with switch-off delay including "greeting function"
- Seats: Driver and passenger seats, 4-way manually adjustable
- Seats: Front seats can be heated individually and variably.
- 230 volt socket
- Bumpers painted in body color
- Trays on the front seatbacks
- Premium carpet floor mats, front and rear
- Lashing eyes in the luggage compartment
- Immobiliser
- Central locking with remote control
- Storage compartments
- Anti-lock braking system (ABS)
- Attachment points for safety partition grilles
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires
- third brake light
- Roof rails "aluminum look"
- Tachometer
- Driver information system display 25.4 cm color
- Electric windows front and rear
- High Beam Assist
- Ford Easy Fuel
- Ford Power Start function
- Ford Power start function with Ford Key Free system
- Luggage compartment lighting
- Transmission: 8-speed automatic transmission
- rear window wiper
- Interior mirror, automatically dimming
- Isofix bracket
- Air conditioning with automatic temperature control
- Steering wheel: Steering column, adjustable in height and reach
- Front center console with padded armrest
- Ford navigation system including Ford SYNC 3 with AppLink, touchscreen, DAB/DAB+ and FordPass Connect
- Package: Winter
- Upholstery: Cloth
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Electromechanical power steering
- Seats: Flexible seating system "FoldFlatSystem (FFS)"
- Seats: Front sports seats
- Start-stop system



Extra equipment

- Package: Business III (Automatic) (Sony Navigation incl. Ford SYNC 3, AppLink, Touchscreen, Voice Control, Radio/CD Player, MP3-compatible, 2 USB ports, 390-watt premium sound system, 12 speakers, steering wheel remote control, Bluetooth hands-free system, FordPass Connect, eCall, DAB/DAB+, Adaptive LED headlights with glare-free high beam, ACC, Traffic Jam Assist, Pre-Collision Assist, Forward Collision Warning, Emergency Brake Assist, Front and Rear View Camera, Blind Spot Assist, Cross Traffic Alert, Dynamic Distance Control, Power Tailgate with Sensors, Ford Key Free System, Park Assist)
- .
- 2 kg powder fire extinguisher
- Anti-theft alarm system including double locking (with interior monitoring)
- Electrically swiveling towbar (including ESP trailer stabilization)
- Paint finish: Frost White
- Safety partition grille, mounting behind front seats

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Electrical system	Battery - Empty - Perform diagnosis
2	Equipment	Vehicle key with remote control (Batterie) - Empty - Replace
3	Equipment	Tirefit filler - Expired - Replace
4	Trim / covers	Door trim - rear right side - Deformed - Loss in value
5	Roof	Roof rail - left side - dent(s) - Smart repair
6	Interior	Interior (Mit Abfärbungen) - Scratch(es) - Loss in value
7	Sill - right side	Sill - Scratch(es) - Smart repair
8	Instrument panel	Indicator light (Notruf-System) - on - Perform diagnosis
9	Side panel - rear right side	Sill (Mit Dellen) - Scratch(es) - Smart repair
10	Side panel - rear left side	Side panel - Corrosion - Smart repair
11	Trim / covers	Roof lining - Broken / torn - Replace
12	Vehicle glazing	Windscreen - Stone chips - repair according to calculation

Wear and tear

No.	Component group	Description
1	Interior	Interior - Scratch(es) - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Body	Body (Flugrost) - Corrosion - No deduction
4	Boot lid / rear door	Rear spoiler - Scratch(es) - Smart repair

The vehicle shows signs of wear and tear commensurate with its age and use.



Missing parts

Description

Documents - Service book

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 25 Feb 2026	1.217,44 €
2	Front, Provided by user / customer, from 12 Jan 2026	1.317,46 €
3	Rear, Provided by user / customer, from 25 Feb 2026	1.386,78 €

Repainting

No. Repainting

1 Boot lid / rear door, Mudguard - left side, Mudguard - right side, Bonnet, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	181 µm	Mudguard - left side	195 µm
Mudguard - right side	221 µm	Bonnet	279 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Das Fahrzeug weist der Laufzeit entsprechende Gebrauchsspuren auf.

Winter - Radsatz ist kein Bestandteil des Lieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.




Damage 3: Equipment: Tirefit filler - Expired - Replace




Damage 4: Trim / covers: Door trim - rear right side - Deformed - Loss in value



Damage 4: Trim / covers: Door trim - rear right side - Deformed - Loss in value



Damage 5: Roof: Roof rail - left side - dent(s) - Smart repair



Damage 5: Roof: Roof rail - left side - dent(s) - Smart repair



Damage 6: Interior: Interior (Mit Abfärbungen) - Scratch(es) - Loss in value




Damage 6: Interior: Interior (Mit Abfärbungen) - Scratch(es) - Loss in value



Damage 6: Interior: Interior (Mit Abfärbungen) - Scratch(es) - Loss in value



Damage 6: Interior: Interior (Mit Abfärbungen) - Scratch(es) - Loss in value




Damage 6: Interior: Interior (Mit Abfärbungen) - Scratch(es) - Loss in value




Damage 6: Interior: Interior (Mit Abfärbungen) - Scratch(es) - Loss in value



Damage 6: Interior: Interior (Mit Abfärbungen) - Scratch(es) - Loss in value




Damage 7: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 7: Sill - right side: Sill - Scratch(es) - Smart repair




Damage 8: Instrument panel: Indicator light (Notruf-System) - on - Perform diagnosis



Damage 9: Side panel - rear right side: Sill (Mit Dellen) - Scratch(es) - Smart repair




Damage 9: Side panel - rear right side: Sill (Mit Dellen) - Scratch(es) - Smart repair



Damage 9: Side panel - rear right side: Sill (Mit Dellen) - Scratch(es) - Smart repair




Damage 9: Side panel - rear right side: Sill (Mit Dellen) - Scratch(es) - Smart repair




Damage 10: Side panel - rear left side: Side panel - Corrosion - Smart repair



Damage 10: Side panel - rear left side: Side panel - Corrosion - Smart repair



Damage 10: Side panel - rear left side: Side panel - Corrosion - Smart repair



Damage 11: Trim / covers: Roof lining - Broken / torn - Replace



Damage 11: Trim / covers: Roof lining - Broken / torn - Replace




Damage 11: Trim / covers: Roof lining - Broken / torn - Replace



Damage 11: Trim / covers: Roof lining - Broken / torn - Replace



Damage 12: Vehicle glazing: Windscreen - Stone chips - repair according to calculation



Damage 12: Vehicle glazing: Windscreen - Stone chips - repair according to calculation



Damage 12: Vehicle glazing: Windscreen - Stone chips - repair according to calculation



Wear and tear 4: Boot lid / rear door: Rear spoiler - Scratch(es) - Smart repair



Wear and tear 4: Boot lid / rear door: Rear spoiler - Scratch(es) - Smart repair



Repainting 1: Boot lid / rear door, Mudguard - left side, Mudguard - right side, Bonnet




Repainting 1: Boot lid / rear door, Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Boot lid / rear door, Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Boot lid / rear door, Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Boot lid / rear door, Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Boot lid / rear door, Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Boot lid / rear door, Mudguard - left side, Mudguard - right side, Bonnet



Repainting 1: Boot lid / rear door, Mudguard - left side, Mudguard - right side, Bonnet



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0JXXWPCJNS01562
Hersteller / Modell: FORD FORD S-Max 2.0 EcoBlue Aut. TITANIUM

Datum	KM-Stand	Beschreibung
19.02.2026	162.636	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
02.12.2025	154.409	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne
22.08.2025	143.068	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges
25.06.2025	135.708	Batterie ern; Systemtest/Eigendiagnose
21.05.2025	131.299	AU; Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Regelwartungsdienst
09.04.2025	126.387	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Systemtest/Eigendiagnose; Wartung Sonstiges
23.12.2024	110.969	Systemtest/Eigendiagnose
03.12.2024	110.969	Batterie ern; Systemtest/Eigendiagnose
20.11.2024	109.576	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne
29.10.2024	106.546	Motoröl b. Wartung; Ölwechsel
16.05.2024	89.097	Bremsentest; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/ Eigendiagnose; Wartung Sonstiges
12.09.2023	61.677	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
28.06.2023	50.198	Bremsklötze hinten; Bremsklötze vorne
09.12.2022	29.106	Motoröl b. Wartung; Regelwartungsdienst