

Vehicle details

VIN	VR3UKZXZ MJ892656	Brand	PEUGEOT	Maintenance date	-
Licence Plate		Model	e-2008 GT Pack EV 50kWh 136 5d	Maintenance mileage	-
Registration date	30/12/2021	Year	2021	Exterior Color	White Solid
Odometer	172 680 km	Engine size	-	Interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	21/07/2026	Inspection loc.			
					
					
					
					
					

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✗

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Hankook 215/55/18 Summer 5.0 mm



Hankook 215/55/18 Summer 5.0 mm




Hankook 215/55/18 Summer 5.0 mm



Hankook 215/55/18 Summer 5.0 mm

Exterior

2



Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

3



Part	Alloy wheel 18"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

4



Part	Wing
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

5



Part	Bumper moulding
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Roof
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



Part	Roof post A/B/C
Position	Right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

9



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

10



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

11



Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair


12



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

Others

1



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info