

MACDAM

Peugeot 2008 '19

Vehicle information



Make:	Peugeot	License:	
Gearbox:	Automatic	Body color:	
Model:	2008 '19	VIN:	VR3UKZKXZLJ820062
Fuel type:	Electric	Power:	100 kW
Version:	2008 EV Active 50kWh	First registration	30/09/2020
Mileage:	182844 km	N° of doors:	

Damage summary

Front	1
Interior	4
Left	4
Rear	2
Right	5
Roof & others	1

Commercial pictures





Options according to the inspector				
Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser
Radio multimedia	Yes	Telephone equipment	Yes	

Damages

Boot lid covering R

Scratch(es)
Smart repair
Rear



Charging cable (normal)

Missing
Replace
Rear



Door FL

Scratch(es)
Repair and paint (complete)
Left



Door FR

Bad repair
Repair and paint (complete)
Right



Door panel RL

Scratch(es)
Smart repair
Interior



Door RL
Scratch(es)
Repair and paint (complete)
Left



Door RR
Bad repair
Repair and paint (complete)
Right



Gear shift lever knob
Scratch(es)
Smart repair
Interior



Ignition key
Missing
Replace
Interior

Interior
Stain
Cleaning
Interior



Outside rear-view mirror housing R
Scratch(es)
Replace and paint
Right



Roof
Dent(s)
Repair and paint (complete)
Roof & others



Roof pillar L
Dent(s)
Repair and paint (complete)
Left



Roof pillar R
Chemical polution
Repair and paint (complete)
Right



Windscreen
Stone chip(s)
Windscreen repair
Front



Wing RL
Scratch(es)
Repair and paint (complete)
Left



Wing RR
Bad repair
Repair and paint (complete)
Right



Tyres	
	Front Left
	Summer
	215/65/16/89/H
	Michelin
	3.4 mm
	Front Right
	Summer
	215/65/16/89/H
	Michelin
	3.2 mm
	Rear Left
	Summer
	215/65/16/89/H
	Michelin
	4.1 mm
	Rear Right
	Summer
	215/65/16/89/H
	Michelin
	3.8 mm

Checks			
Certificate of Conformity	No	CO2 Emission	0
Digital maintenance	N/A	GPS storage	Yes
GPS storage	HD	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	1	Service book	Yes
User's manual	Yes		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.