



Expertise

Protocol number: 46696518
Order No. / Reference: 26726414
Inspection date: 24 Jul 2026

Manufacturer: Renault

Model: Megane EV60 220hp optimum charge Paket Techno

VIN: VF1RCB00670091620



Vehicle details	
Manufacturer / Type / Model / Equipment	
Renault Megane EV60 220hp optimum charge Paket Techno	
Vehicle Identification number	VF1RCB00670091620
Mileage (Read)	75,663 km
First registration	27 Dec 2022
Number of holders	1
Next periodical technical inspection	12/2027
(Report on hand)	
Fuel type	Electric
Power	55 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Arktis-Weiß Dach-Schwarz
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey-Black
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ466950
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	3333 / BPN 00016		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	2,158 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/45 R20 95T	Summer tyres on Light alloy	Goodyear	5mm / 4mm
2)	215/45 R20 95T	Summer tyres on Light alloy	Goodyear	6mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Active Driver Assist
- Airbag: Front side airbags, front and rear window airbags, and front center airbag
- Antenna: Shark fin antenna
- Dashboard in grey - textile
- Exit assistant - warns you if a vehicle is approaching from behind while you are about to open the door.
- Exterior mirrors painted black
- 12-inch digital speedometer display
- Front, rear and side parking aid with Easy Park Assist
- Electric window regulators front and rear with momentary switch and pinch protection
- Transmission: Automatic reduction gearbox
- Inductive smartphone charging pad
- Frameless, automatically dimming interior rearview mirror with rear-view camera display - The system uses a camera above the rear window to monitor the traffic behind the vehicle. - The image is displayed on a screen in the interior rearview mirror. - A switch on the underside of the interior rearview mirror allows the driver to toggle between the camera image and the conventional mirror function.
- LED light signature
- LED daytime running lights
- Steering wheel: Leather steering wheel
- Steering wheel: Paddle shifters on the steering wheel for recuperation
- Center console with storage compartment and center armrest
- Fatigue detection
- Emergency braking assistant with pedestrian, cyclist and intersection detection
- Radio: OpenR link infotainment system with 12-inch touchscreen - Arkamys Auditorium sound system - 6 speakers - Navigation system with Google Maps - Integrated Google Assistant - Wireless Android Auto & Apple CarPlay - Voice-controlled Google Assistant
- Wheels: Tire repair kit
- Rear view camera
- Seat belts - 3-point seat belts on all rear seats - Seat belt warning for front and rear seats
- Seats: Driver and passenger seats are heated
- Bumper in body color F1 Blade
- Adaptive cruise control
- Traffic sign recognition with speed adjustment
- Full LED headlights LED Pure Vision with adaptive front lighting system (cornering lights with bad weather function)
- Airbag: Airbag for driver and front passenger - passenger airbag can be deactivated
- Ambient lighting in the front doors, customizable
- Anti-lock braking system with electronic brake-force distribution (EBD)
- Exterior mirrors (2) electrically adjustable, folding and heated with memory function
- Connected Services
- eCall emergency call system
- Electronic Stability Program (ESP) - with hill start assist
- High beam assist
- Sound simulator
- Heated rear window
- Interior harmony Techno in grey fabric
- ISOFIX i-Size child seat attachment
- 360° 3D camera
- Keycard Handsfree
- Climate: Heat pump
- 2-zone automatic climate control
- Headrests (5)
- Charging cable Type 2/Type 2 (Mode 3) 5m length - 2.3 to 22kW AC
- Steering wheel: Heated steering wheel
- Steering wheel: Steering wheel adjustable for reach and height
- Light and rain sensor
- MULTI-SENSE with ambient lighting - for individual adjustment of the vehicle characteristics
- Fog light
- Emergency Lane Keeping Assist
- Upholstery: Fabric "Anthracite"
- Radio accessories: 2 USB ports in the front and rear seat rows
- Tires: Direct tire pressure monitoring system
- Wheels: 20" alloy wheels "Soren with stripes" with 215/45 R20 tires
- Reversing emergency braking assistant
- Rear side windows and rear window heavily tinted
- Safety distance warning system
- Seats: Passenger seat height adjustable
- Seats: Rear bench seat folds down asymmetrically (1/3 to 2/3 foldable)
- Blind spot warning system with active steering intervention
- Full LED light strip with 3D effect (moiré) and dynamic turn signal
- Central locking with remote control

Extra equipment

- Paintwork: Two-tone metallic paintwork, roof and exterior mirrors painted in roof color



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Body	B-pillar - left side - dent(s) - Smart repair
2	Wheel / tyres	Alloy rim - front right side - Scratched - Loss in value
3	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Scratched - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Dent / paintcoat damage - No deduction
2	Misc.	Inspection / maintenance - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Damage 1: Body: B-pillar - left side - dent(s) - Smart repair



Damage 1: Body: B-pillar - left side - dent(s) - Smart repair



Damage 2: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 3: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace




Damage 3: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace