

Expertise

Protocol number: 45941219
 Order No. / Reference: 26499938
 Inspection date: 15 Jun 2026

Manufacturer: Mercedes-Benz

Model: 317 CDI Sprinter Kompakt HA 9G-TRONIC

VIN: W1V9076311P517600



Vehicle details

Manufacturer / Type / Model / Equipment

Mercedes-Benz 317 CDI Sprinter Kompakt HA 9G-TRONIC

Vehicle Identification number	W1V9076311P517600
Mileage (Read)	184,250 km
First registration	11 Jan 2023
Number of holders	1
Next periodical technical inspection	02/2027
(Report on hand)	

Power / Engine displacement 125 kw / 1,950 ccm

Fuel type / Cylinder Diesel / 4

Gearbox / Number of gears Automatic / 9

Type of drive Rear drive

Type of vehicle Van

Colour / colour code Iridiumsilber Metallic

Doors / Seats 4 / 2

Upholstery type Cloth

Colour of upholstery Black

Re-import no



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	587 Tag(e)
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP665182
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BBH 98737		
Emission standard	EURO6;WLTP;AR;PI/CI;N1 III, N2	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Winter tyres on Steel rim with wheel cover	Sonstige	6mm / 6mm
2)	235/65 R16 115R	Winter tyres on Steel rim with wheel cover	Sonstige	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Summer tyres on Steel	Uniroyal	4mm / 4mm
2)	235/65 R16 115R	Summer tyres on Steel	Uniroyal	4mm / 4mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartment above windshield
- Rear towing eye
- ADAPTIVE ESP (latest generation) with load- and speed-dependent driving dynamics control
- Outdoor temperature display
- Battery: fleece battery 12 V / 92 Ah
- third brake light
- COC documents
- Tachometer
- Driving light assistant
- Generator 14 V / 200 A
- Transmission: 9G-TRONIC
- Grab handle for entry to the cargo area sliding door on the partition wall
- Instrument panel and combination instrument with various storage options
- Headrests (2), front
- Steering wheel adjustable for tilt and height
- Mercedes-Benz emergency call system
- Breakdown management
- Radio: Radio preparation
- Radio accessories: Communication module (LTE) for digital services
- Tires: Summer tires
- Sliding door on the right, cargo/passenger compartment
- Power steering
- Seats: Driver's seat armrest
- Seats: Driver's seat
- Speedometer km/h
- First aid kit
- Pre-installation for Remote Services Plus
- Immobiliser
- Central locking with radio remote control
- Registration certificate, Part II
- Storage compartment under cockpit
- Axle ratio $i = 3.923$
- Driver's side airbag
- Electrically adjustable and heated exterior mirrors, left and right
- Hill start assist
- Brake lights, adaptive
- Diesel particulate filter and SCR
- Entry handle on rear right corner pillar
- Electric window regulator for driver and passenger door
- Noise measures
- Seatbelt warning device for driver's seat
- Main tank 71 liters
- HOLD function
- KEYLESS start
- Child safety locks on doors in the passenger compartment
- Paint finish: Solid color paint
- Headlight range control
- Without weight increase/decrease: 3,500 kg
- Upholstery: Cloth
- Radio: Pre-installation for digital radio DAB
- Tires: Tires without specified make
- Tires: Premium protection tires (3 years)
- Wheels: Steel rims 6.5 J x 16
- Crosswind Assist
- Seats: Passenger seat armrest
- Seats: Adjustable passenger seat
- Start-stop function
- continuous partition wall
- Lashing eyes
- Warning triangle
- Heat-insulating glass
- Approval N1



Extra equipment

- Distance Assist DISTRONIC active
- Airbag: Thorax bag/pelvis/side bag for driver (battery master switch, single pole)
- Entrance rear door
- Battery master switch, single pole
- Reference mass of at least 2611 kg is necessary.
- Brake assist, active
- Digital operating instructions
- Chassis for comfort and cargo protection
- High Beam Assist
- Hinged lid for storage compartment
- Tempmatic controlled air conditioning
- Comfort roof control unit
- Cargo area floor with different paint finish
- leather steering wheel
- Cable duct on side wall
- MBUX multimedia system with 10.25-inch touchscreen (High-resolution 10.25-inch touchscreen, hard drive navigation including 3 years of free map data updates, Mercedes PRO features, LINGUATRONIC voice control, WLAN hotspot, multimedia connection unit for connecting portable devices via two USB-C interfaces, multimedia unit in piano black, outer ring of the air vents in matte silver, center fill speaker for improved sound and voice output, improved hands-free function, live traffic capability, digital operation)
- Package: Park Assist (MBUX multimedia system with 7-inch touchscreen - electrically folding exterior mirrors - blind spot assist - parking package with reversing camera)
- Rain sensor
- Wireless tire pressure monitoring system for front and rear axles
- Seats: Driver's seat box, low
- Seats: Comfort headrest, passenger
- Seats: Lumbar support for driver's seat
- Seat heating on driver's side
- Traffic Sign Assistant
- WET WIPER SYSTEM
- Heated windshield
- Passenger side airbag
- Airbag: Windowbag for driver and front passenger
- ATTENTION ASSIST (ATTENTION ASSIST can assist the driver on long, monotonous journeys by monitoring attention. If signs of fatigue or increasing inattention are detected, it suggests a break.)
- Front cupholder
- Lockable compartment in storage area above windshield
- Chassis stabilization level 1
- Seatbelt warning device for front passenger seat
- Hinged lids for storage compartments on the left and right
- Instrument cluster with color display
- Paint finish: Metallic
- LED High Performance Headlights
- Cable duct at rear portal
- Steering wheel: Multifunction steering wheel
- Halogen fog lights
- Package: Acoustics in conjunction with MBUX
- Package: Anti-theft package
- Package: Instrument panel charging package in conjunction with MBUX (The charging package expands the charging options in the cockpit with two 5V USB-C ports and one 12V socket. One USB port and the 12V socket are installed in the center storage compartment of the instrument panel, and another USB port is located in the lower part of the center console. This allows for the charging of electronic devices such as mobile phones within easy reach of the driver and front passenger.)
- Radio: Digital Radio DAB
- Tires: M+S tires
- Key: Multi-button radio remote control
- Seats: Armrest, driver and passenger door
- Seats: Comfort passenger seat
- Seats: Comfort headrest for driver
- Seats: Suspension seat comfort version, driver's seat
- 230V socket
- Workshop van interior fitting according to customer specifications
- Heat-insulating glass with band filter on the windshield

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (DSR fehlt) - No evidence - No deduction
2	Boot lid / rear door	Rear door - left side - Scratch(es) - Smart repair
3	Boot lid / rear door	Rear door - right side (Verkleidung innen) - Broken / torn - Replace
4	Body	Body - Glued / labelled - De-glue / neutralise
5	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Comments

- Der Sommerradsatz ist kein Bestandteil der Ausstattungsliste.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Damage 2: Boot lid / rear door: Rear door - left side - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Rear door - left side - Scratch(es) - Smart repair



Damage 3: Boot lid / rear door: Rear door - right side (Verkleidung innen)
- Broken / torn - Replace




Damage 3: Boot lid / rear door: Rear door - right side (Verkleidung innen)
- Broken / torn - Replace



Damage 4: Body: Body - Glued / labelled - De-glug / neutralise



Damage 4: Body: Body - Glued / labelled - De-glug / neutralise



Damage 4: Body: Body - Glued / labelled - De-glug / neutralise



Damage 4: Body: Body - Glued / labelled - De-glug / neutralise



Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint