



Expertise

Protocol number: 46683343
Order No. / Reference: 26694837
Inspection date: 23 Jul 2026

Manufacturer: Opel

Model: Combo Cargo 1.5 D Selection

VIN: W0VEFYHT2NN507488



Vehicle details

Manufacturer / Type / Model / Equipment

Opel Combo Cargo 1.5 D Selection

Vehicle Identification number	W0VEFYHT2NN507488
Mileage (Read)	190,181 km
First registration	10 Jun 2022
Number of holders	1
Next periodical technical inspection	06/2028
(Report on hand)	

Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	75 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Jade Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Grey-Black



Vehicle details			
Maintenance booklet / proof	Available / complete	Next maintenance in	38,840 km
Last service on / at	06/2026 at 189,033 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ644695
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AIQ 01112		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,985 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/65 R15 95V	All-season tyres on Steel	Goodyear	6mm / 6mm
2)	195/65 R15 95V	All-season tyres on Steel	Goodyear	4mm / 4mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	195/65 R15 95V	All-season tyres on Steel	Goodyear	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- All-weather tires
- Credit for all-weather tires
- Safety package including whisk

Standard equipment

- Cover strip for sliding door track (in black)
- ABS including brake assist and adaptive brake light
- Driver's side airbag
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Automatic dipped headlights
- Exterior mirrors, electrically adjustable, heated and manually folding
- Hill Start Assist
- On-board computer
- Tachometer
- Three-point seat belts on all seats (belt force limiter, front - double belt tensioners, front - warning tone and light for unfastened seat belts, front)
- Electric front windows
- Rear wing doors, asymmetrically split, sheet metal, 180° opening angle
- Headrests (2), front, height adjustable
- Steering wheel: Comfort steering wheel (PU), flattened at the bottom
- Radio BT (Audio: - Bluetooth audio streaming Phone: - Hands-free calling via Bluetooth interface - Display of phonebook and call lists - Up to 5 mobile phones can be paired General: - Use of the voice control of the paired smartphone possible (e.g. Siri, Google voice control) - USB interface - 4 speakers)
- Speed-sensitive power steering
- Seats: Driver's seat manually adjustable in 4 ways (length and backrest angle)
- Daytime running light
- Partition wall, closed
- Doors: Sheet metal insert, passenger side
- Lashing eyes (6) in the cargo area
- Heat-insulating glazing, tinted
- Central locking: Ignition keys (2), one of which is foldable
- GPS TC Truck XS
- Leather steering wheel N35
- Würth: Electrical/Carpentry NAG_20181113_04
- Storage compartments (storage compartment in the center console, front - storage shelf above the windshield, open (not in conjunction with radio removal) - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - glove compartment, open - storage compartment on dashboard, passenger side, closed)
- Exterior mirror housings in black
- Battery discharge protection
- Floor covering: Cargo area floor, painted
- Diesel particulate filter, maintenance-free (incl. SCR catalyst with AdBlue)
- Third brake light
- Electronic Stability Program (ESP Plus)
- Driver information display - LCD, black surround
- Transmission: 6-speed transmission
- Heating and ventilation system with particle and odor filter, front
- Paint finish: Solid color paint
- Steering column, adjustable for reach and height
- Upholstery: Cloth
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- Wheels: Steel wheels 6.5 J x 15 (tires 195/65 R15 SL 91H - wheel hub cover)
- Side impact protection
- Side protection strips (in black)
- Seats: Single passenger seat, fixed
- Start/Stop System
- 12-volt power outlet in the center console
- Traction control with engine and brake intervention (TC Plus)
- Doors: Sheet metal insert, driver's side
- Immobiliser
- Central locking with remote control



Extra equipment

- Electric windows, front, with one-touch function and anti-pinch protection (as well as comfort closing function via remote control of the central locking system - electrically adjustable, heated and folding exterior mirrors)
- Parking sensors, front and rear (fog lights)
- Wheels: Spare wheel, steel, 6.5 J x 15
- Rear view camera
- Seats: Double passenger seat (Electric parking brake - storage compartment on the backrest of the middle seat of the double passenger seat)
- Doors: Sliding door, passenger side, sheet metal
- Load securing (LED light in the cargo area - 4 additional load securing loops at half height (2 per side) - 12 Volt socket in the cargo area)
- Package: Cool & Sound 1 (Multimedia Radio (Bluetooth, Hands-free system, USB, Smartphone integration, 8" touchscreen color display, Cruise control, Steering wheel remote control) - Air conditioning, front)
- Seats: Driver's seat adjustable in 6 ways: length, height and backrest angle (with lumbar support and armrest)
- FlexCargo partition wall without window (with pass-through function below the passenger double seat including protective bag for the load)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door edge - Scratch(es) - Smart repair
2	Wing mirror - right side	Cap - Scratch(es) - Smart repair
3	Trim / covers	Carpet - front left side - Holes - Loss in value
4	Door - rear left side	Door - Malposition - Un- / install
5	Body	Body - Glued / labelled - De-glue / neutralise
6	Seat - front	Seat cover - left side - Holes - Replace
7	Side panel - rear left side	Side panel - Dent / paintcoat damage - Paint

Wear and tear

No.	Component group	Description
1	Steering system	Steering wheel - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Roof	Roof - Stone chips - No deduction
4	Mudguard - right side	Mudguard - right side - Stone chips - No deduction
5	Door - front right side	Door - Dent / paintcoat damage - No deduction
6	Door - rear right side	Door - Scratch(es) - No deduction
7	Rear bumper	Rear bumper - Scratch(es) - No deduction
8	Wing mirror - left side	Cap - Scratch(es) - No deduction
9	Body	Underbody - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Missing parts

Description

Engine - Engine cover

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side - left, Side right, Provided by user / customer, from 20 Jan 2025	5.407,26 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Interior 360° view



Figure 11: Cargo area



Figure 12: Cargo area



Figure 13: VIN



Figure 14: Mounted tyres



Figure 15: Mounted tyres




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents



Figure 19: Documents




Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.




Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair




Damage 3: Trim / covers: Carpet - front left side - Holes - Loss in value



Damage 3: Trim / covers: Carpet - front left side - Holes - Loss in value



Damage 4: Door - rear left side: Door - Malposition - Un- / install



Damage 4: Door - rear left side: Door - Malposition - Un- / install



Damage 4: Door - rear left side: Door - Malposition - Un- / install



Damage 4: Door - rear left side: Door - Malposition - Un- / install




Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 6: Seat - front: Seat cover - left side - Holes - Replace




Damage 6: Seat - front: Seat cover - left side - Holes - Replace



Damage 6: Seat - front: Seat cover - left side - Holes - Replace



Damage 6: Seat - front: Seat cover - left side - Holes - Replace



Damage 6: Seat - front: Seat cover - left side - Holes - Replace



Damage 6: Seat - front: Seat cover - left side - Holes - Replace



Damage 7: Side panel - rear left side: Side panel - Dent / paintcoat damage - Paint



Damage 7: Side panel - rear left side: Side panel - Dent / paintcoat damage - Paint



Damage 7: Side panel - rear left side: Side panel - Dent / paintcoat damage - Paint



Wear and tear 5: Door - front right side: Door - Dent / paintcoat damage - No deduction




Wear and tear 5: Door - front right side: Door - Dent / paintcoat damage - No deduction



Wear and tear 5: Door - front right side: Door - Dent / paintcoat damage - No deduction



Wear and tear 5: Door - front right side: Door - Dent / paintcoat damage - No deduction



Wear and tear 9: Body: Underbody - Scratch(es) - No deduction



Wear and tear 9: Body: Underbody - Scratch(es) - No deduction



Wear and tear 9: Body: Underbody - Scratch(es) - No deduction



Missing part 1: Engine: Engine cover - Missing - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VEFYHT2NN507488
Hersteller / Modell: OPEL OPEL Combo Cargo 1.5 D Selection

Datum	KM-Stand	Beschreibung
19.06.2026	189.033	AU; Keilrippenriemen; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges; Wasserpumpe ern
18.11.2025	152.941	Kraftstofffilter ern; Luftfiltereinsatz ern; Systemtest/Eigendiagnose
03.11.2025	152.941	Batterie ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
30.04.2025	118.128	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
26.09.2024	81.974	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
03.07.2024	71.018	AU; Systemtest/Eigendiagnose
12.01.2024	39.728	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges