



IDENTIFICATION VEHICLE

Driver name: ASSE I
Make: BMW
Model / version: X1
Vin: WBA71AB0105V30458
Plate: 128156
Mileage: 128156
SOH:
First registration: 14/04/2022
Color: 475 Saphirsch


ADDITIONAL INFORMATION






Category:
Transmission:
Interior color:
Metallic paint: ☒
Type of lining:
Board computer reset: ☒

DOCUMENTS

Certificate of conformity: ☒
Registration certificate: ☒
Registration certificate 2: ☒
Insurance certificate: ☐ ?
Maintenance book:
Number of keys: 2
Original key: ☒

PICTURES





VIN INFORMATION

Radio
8 rapports
Projecteurs antibrouillard à LED
Lettre repère (J)
Largeur avant 7,5
Diamètre arrière 17
Indice de vitesse avant H
Largeur arrière 225
Accoudoir central avant
1.50 litre
Métallisée vernissée

Volant cuir
Aide au stationnement avant
Caméra avant

Système navigation
4 roues motrices
Equipement Advantage
Diamètre avant 17
Largeur arrière 7,5
Hauteur avant 55
Indice de vitesse arrière H
Climatisation automatique
Hybride essence
92 kw
Rétroviseur intérieur jour/nuit automatique
Volant sport
Aide au stationnement arrière
Régulateur automatique de la distance

Transmission automatique
Projecteurs à LED
Matière : alliage
Diamètre arrière 17
Diamètre avant 17
Hauteur arrière 55
Largeur avant 225
Climatisation réfrigérant 1234YF
1499 cm3
125 ch
Garnitures tissu
Volant multifonction
Assistance au parking
Ouverture du coffre électriquement

Appel de secours	Fixotoit noir	Protection piéton
Freinage d'urgence assistée autonome (urbain)	Avertisseur de collision avant	Contrôle pression des pneus
depuis 03.22	mesures CO2 étendues	Teleservices
tuner DAB	Connected Drive Services	protection acoustique des piétons
pack de rangement	boulons antivol de roue	encarts intérieurs oxyde d'argent foncé mat avec accents noir brillant
spécifique Europe		

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	×	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	×
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	1	Fast charging cables:	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm			Summer	Aluminium	?
Front right	4 mm			Summer	Aluminium	?
Rear left	4 mm			Summer	Aluminium	?
Rear right	4 mm			Summer	Aluminium	?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Dashboard - Boordcomputer resetten	Not original part
2	Interior	Stain
3	Boot lid covering R	Broken
5	Bumper moulding R	Scratch(es)
6	Bumper trim R	Dent(s) and scratch(es)
7	Indicator FL	Crack
8	Wing FL	Dent(s)

Total: 7




ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
4	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS


1 - Dashboard - Boordcomputer resetten - Not original part



2 - Interior - Stain



3 - Boot lid covering R - Broken



5 - Bumper moulding R - Scratch(es)



6 - Bumper trim R - Dent(s) and scratch(es)










7 - Indicator FL - Crack





8 - Wing FL - Dent(s)



4 - Bodywork - Dent(s) and scratch(es) - Renta®





SIGNATURE
