



Expertise

Protocol number: 46466139
Order No. / Reference: 26521300
Inspection date: 10 Jul 2026

Manufacturer: Mercedes-Benz

Model: EQE 300 Electric Art

VIN: W1KEG1BB1PF023922



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz EQE 300 Electric Art	
Vehicle Identification number	W1KEG1BB1PF023922
Mileage (Read)	197,169 km
First registration	5 Apr 2023
Number of holders	1
Next periodical technical inspection	03/2028
(Report on hand)	
Power / Engine displacement	180 kw /
Fuel type / Cylinder	Electric / 0
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Saloon car
Colour / colour code	POLARWEISS - UNILACK
Doors / Seats	4 / 5
Upholstery type	Artificial leather
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	3,174 km
Last service on / at	01/2026 at 170,344 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ146537
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BIN 00869		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,880 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/45 R19 104V	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	255/45 R19 104V	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/45 R19 104V	Winter tyres on Light alloy	Goodyear	8mm / 8mm
2)	255/45 R19 104V	Winter tyres on Light alloy	Goodyear	3mm / 3mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS - Anti-lock Braking System
- Airbag: Automatic passenger airbag deactivation
- Airbag: Windowbag all around
- Ambient lighting
- Brake assist, active
- Door sills with "Mercedes-Benz" lettering
- Driver display with 25.4 cm (10.25") screen diagonal
- Flex Bottle Holder
- Velour floor mats
- Transmission: Direct drive
- Instrument panel and door sills in ARTICO man-made leather, space grey
- Rear headrests (3)
- Paint finish: Solid
- Charging cable for wallbox and public charging station, 5m, smooth, 11kW
- Charging system: AC charging system 11kW
- LED taillights in 3D helix design
- Mercedes-Benz emergency call system
- Center console in high-gloss black
- Navigation accessories: Pre-installation for navigation services
- Navigation: MBUX Navigation Premium
- Package: Parking package with reversing camera
- PRE-SAFE system
- Radio: MBUX multimedia system
- Radio accessories: Communication module (LTE Advanced) for using Mercedes me connect
- Remote Services Premium
- Remote and extended Charging Services Premium
- Heated windshield washer system
- Seats: Rear seat backrests foldable 40/20/40 split
- Seats: Comfort seats
- Cruise control
- Door center panels and transition from the center console to the instrument panel in ARTICO man-made leather
- Pre-installation for remote and navigation services
- Decorative elements with fine textured black finish
- Airbag for driver and front passenger
- Airbag: Kneebag for driver
- Acoustic environmental protection
- Traction control (ASR)
- DYNAMIC SELECT
- Electronic Stability Program (ESP)
- Chassis: Comfort chassis
- Rear seat belt status indicator in the instrument cluster
- Speed Limit Assistant
- Black fabric headliner
- Climate: Pre-conditioning
- THERMATIC automatic climate control with 2 climate zones
- Front headrests are height-adjustable
- Charging cable for household socket, 5m, smooth
- Charging system: Direct current charging system (DC charging)
- LED High Performance Headlights
- Steering wheel: Multifunction sports steering wheel in ARTICO man-made leather
- Navigation accessories: Pre-installation for Live Traffic Information
- Navigation: Hard disk navigation
- Package: Interior lighting package
- Upholstery: ARTICO leatherette/fabric
- Radio: Extended MBUX functions
- Radio accessories: Digital radio
- Tire pressure monitoring system
- Remote Services Plus
- Remote and Charging Services Premium
- Wheels: 48.3 cm (19") light alloy wheels in a 10-spoke design
- Seats: i-Size child seat attachment
- Seats: Heated seats for driver and front passenger
- TIREFIT
- URBAN GUARD Vehicle Protection Plus
- Pre-installation for digital key handover
- High-visibility vest for drivers



Extra equipment

- Charging cable for wallbox and public charging station, 8m, smooth 22kW (This charging cable, also called Mode 3 cable, allows you to charge the vehicle battery at the wallbox or at public charging stations with up to 22 kW (Type 2, 3-phase, 32 A).)
- Package: Electric Art Line Exterior (Black panel radiator grille with central Mercedes star - Front apron in body color with chrome trim elements in the upper and lower sections - Side skirts painted in black with chrome door trim strips - Rear apron painted in body color with a grained black lower section and chrome trim element - Belt and window line trim strips in chrome - 48.3 cm (19") alloy wheels in 5-twin-spoke design (R39) painted in high-gloss black and polished with 255/45 R19 tires on 8.5J x 19 ET47.5)
- Paint finish: MANUFAKTUR uni
- Paint finish: Solid polar white
- Upholstery: NEOTEX/ARTICO leatherette black/space grey
- Wheels: 48.3 cm (19") light alloy wheels in a 5-twin-spoke design
- Center console fine texture look black
- Package: Premium Package (Advanced Plus Package contents - Active ambient lighting - Burmester surround sound system - THERMOTRONIC automatic climate control - Driving Assistance Package Plus: Active Assistance - DISTRONIC distance control, speed limit, traffic jam, steering, braking, lane keeping, blind spot PRE-SAFE PLUS PRE-SAFE Impulse Side - DIGITAL LIGHT - Parking Package with 360° camera - URBAN GUARD vehicle protection Plus - MBUX Augmented Reality for navigation)
- Steering wheel: Multifunction sports steering wheel in leather (with steering wheel shift paddles (428) and steering wheel trim in silver chrome - control via touch control panels)
- Telephone accessories: Multifunction telephony in conjunction with Adv./Adv Plus/Premium/Premium Plus package (wireless connection of a compatible mobile phone to the external antenna - Bluetooth and WLAN pairing wirelessly via NFC (Near Field Communication) technology)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Body	Underbody panelling (Links und Rechts) - Scratched - Replace
2	Trim / covers	Door trim - rear right side - Soiled - Clean
3	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
4	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
5	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
6	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Loss in value
7	Sill - right side	Trim - Scratch(es) - Replace
8	Door - rear left side	Door - Scratch(es) - Paint
9	Rear bumper	Rear bumper - Scratch(es) - Paint
10	Bonnet	Bonnet - Stone chips - Paint
11	Front bumper	Front bumper - Stone chips - Paint



Wear and tear

No.	Component group	Description
1	Front bumper	Spoiler - Scratch(es) - No deduction
2	Sill - left side	Trim - Scratch(es) - No deduction
3	Rear bumper	Spoiler - Scratch(es) - No deduction
4	Vehicle glazing	Rear window - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 21 Sept 2023	1.965,66 €

Repainting

No.	Repainting
1	Mudguard - left side, Professionally carried out, Invoice of repair done Non-existent
2	Bonnet, Professionally carried out, Invoice of repair done Non-existent
3	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
4	Door - rear left side, Professionally carried out, Invoice of repair done Non-existent
5	Door - front left side, Professionally carried out, Invoice of repair done Non-existent
6	Roof rail - left side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof rail - left side	826 µm	Mudguard - left side	197 µm
Bonnet	194 µm	Side panel - rear left side	220 µm
Door - rear left side	224 µm	Door - front left side	319 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Damage 1: Body: Underbody panelling (Links und Rechts) - Scratched - Replace



Damage 1: Body: Underbody panelling (Links und Rechts) - Scratched - Replace



Damage 1: Body: Underbody panelling (Links und Rechts) - Scratched - Replace




Damage 1: Body: Underbody panelling (Links und Rechts) - Scratched - Replace




Damage 2: Trim / covers: Door trim - rear right side - Soiled - Clean



Damage 2: Trim / covers: Door trim - rear right side - Soiled - Clean



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value




Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value




Damage 7: Sill - right side: Trim - Scratch(es) - Replace



Damage 7: Sill - right side: Trim - Scratch(es) - Replace



Damage 8: Door - rear left side: Door - Scratch(es) - Paint



Damage 8: Door - rear left side: Door - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 10: Bonnet: Bonnet - Stone chips - Paint



Damage 10: Bonnet: Bonnet - Stone chips - Paint



Damage 10: Bonnet: Bonnet - Stone chips - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Damage 11: Front bumper: Front bumper - Stone chips - Paint



Wear and tear 1: Front bumper: Spoiler - Scratch(es) - No deduction



Wear and tear 1: Front bumper: Spoiler - Scratch(es) - No deduction



Wear and tear 2: Sill - left side: Trim - Scratch(es) - No deduction



Wear and tear 2: Sill - left side: Trim - Scratch(es) - No deduction




Wear and tear 2: Sill - left side: Trim - Scratch(es) - No deduction



Wear and tear 3: Rear bumper: Spoiler - Scratch(es) - No deduction



Wear and tear 3: Rear bumper: Spoiler - Scratch(es) - No deduction



Wear and tear 4: Vehicle glazing: Rear window - Scratch(es) - No deduction



Wear and tear 4: Vehicle glazing: Rear window - Scratch(es) - No deduction



Repainting 1: Mudguard - left side



Repainting 2: Bonnet



Repainting 3: Side panel - rear left side



Repainting 4: Door - rear left side



Repainting 5: Door - front left side



Repainting 6: Roof rail - left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1KEG1BB1PF023922

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ EQE 300 Electric Art

Datum	KM-Stand	Beschreibung
19.03.2026	178.878	AU
17.01.2026	170.344	Regelwartungsdienst
26.07.2025	142.823	Regelwartungsdienst
21.02.2025	115.780	Regelwartungsdienst
21.08.2024	87.377	Regelwartungsdienst
25.03.2024	58.072	Regelwartungsdienst
20.10.2023	29.833	Regelwartungsdienst