



Expertise

Protocol number: 45914975
Order No. / Reference: 26437548
Inspection date: 11 Jun 2026

Manufacturer: Opel	Model: Astra 1.5 D Start/Stop Sports Tourer Automatik Business Edition
VIN: W0VBD8EVXN8038401	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Start/Stop Sports Tourer Automatik Business Edition	
Vehicle Identification number	W0VBD8EVXN8038401
Mileage (Read)	143,914 km
First registration	1 Mar 2022
Number of holders	1
Next periodical technical inspection	04/2027
(Report on hand)	
Power / Engine displacement	90 kw / 1,496 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 9
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Quarz Grau
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	6 %
Last service on / at	07/2025 at 129,643 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ638179
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / ALL 00261		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,980 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm
2)	205/55 R16 91V	Summer tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 ignition keys
- Airbag for driver and passenger side
- Airbag: Head airbags, 1st and 2nd row (outer seats)
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- black roof rails
- Diesel particulate filter (DPF)
- Electronic Stability Program Plus (ESP Plus)
- Speed controller with limiter
- Back window, heater
- Interior lighting, front and rear
- Air conditioning
- trunk light
- Front headrests
- LED headlights
- Steering wheel: Leather steering wheel
- Lighting equipment
- Parkpilot, rear parking aid
- Upholstery: Cloth
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire repair kit
- Wheels: Designer wheels, 7 J x 16 with tires 205/55 R16
- Power steering
- Luggage compartment safety net
- Seats: Comfort seats, front
- 12V power outlet in the center console
- Pre-installation for child seat mounting system "ISOFIX"
- Heat-insulating glazing, green tinted, and windshield
- Storage compartments
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Automatic activation of the hazard warning lights
- Hill Start Assist
- On-board computer
- Roof design line, above in black
- Decorative trim strips Antelao Sand/Polar Silver
- Tachometer
- Electric windows front and rear
- Transmission: 9-speed automatic transmission
- rear window wiper
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- Rear headrests (3)
- Cargo area cover
- LED daytime running lights
- Steering column, height and reach adjustable
- Fog light
- Pedals: Disengaging safety pedals
- Quickheat rapid heating system
- Radio: Multimedia radio with 7" touchscreen color display
- Tire pressure monitoring system
- Rear seat backrest folds forward in a 60:40 split
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control and interior switches

Extra equipment

- Paint finish: Pearl effect
- Sliding center armrest, front (with storage compartments and cup holders)
- Package: Business Edition Plus package (Ergonomic active seat, certified by the Campaign for Healthy Backs (AGR), driver - two-zone automatic climate control - Park Pilot, front and rear parking aid)
- Rear view camera
- Steering wheel: Heated leather steering wheel and seat heating, multi-stage, driver and front passenger (including rear footwell heating)
- Radio: Multimedia Navi (Multimedia Radio, 7" touchscreen color display with USB port, hands-free system, voice control, Bluetooth audio streaming, smartphone integration via Apple CarPlay and Android Auto - Navigation system with integrated memory - Road map for over 30 European countries - Map display in 2D and 3D - Dynamic route guidance via map and/or arrow display and voice prompts - Dynamic destination guidance via enhanced Traffic Message Channel (TMCpro))



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Broken / torn - Replace
2	Wing mirror - left side	Cap - Scratch(es) - Smart repair
3	Body	Body - Glued / labelled - De-glue / neutralise
4	Sill - right side	Sill - dent(s) - Smooth repair work
5	Door - rear left side	Door - Scratch(es) - Smart repair
6	Side panel - rear left side	Sill - dent(s) - Smooth repair work
7	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
8	Door - rear right side	Door - Dent / paintcoat damage - Paint
9	Rear bumper	Rear bumper - Scratch(es) - Paint
10	Front bumper	Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Misc.	Inspection / maintenance (30 000 er) - Missing - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Side panel - rear left side	Side panel - Scratch(es) - No deduction
4	Door - front left side	Door (Türkante) - Scratch(es) - No deduction
5	Side panel - rear right side	Side panel - Scratch(es) - No deduction
6	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Professionally repaired, Invoice of repair done Non-existent, from 15 Jun 2022	2.935,80 €

Repainting

No.	Repainting
1	Mudguard - left side, Bonnet, Professionally carried out

Paint coat thickness measurement

Mudguard - left side	297 µm	Bonnet	107 µm
----------------------	--------	--------	--------



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN




Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents




Figure 17: Documents




Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Damage 1: Wheel / tyres: Wheel cover - front right side - Broken / torn - Replace



Damage 1: Wheel / tyres: Wheel cover - front right side - Broken / torn - Replace



Damage 2: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 3: Body - Body - Glued / labelled - De-glue / neutralise



Damage 4: Sill - right side: Sill - dent(s) - Smooth repair work




Damage 4: Sill - right side: Sill - dent(s) - Smooth repair work



Damage 5: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 5: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 6: Side panel - rear left side: Sill - dent(s) - Smooth repair work




Damage 6: Side panel - rear left side: Sill - dent(s) - Smooth repair work




Damage 7: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage 7: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 8: Door - rear right side: Door - Dent / paintcoat damage - Paint



Damage 8: Door - rear right side: Door - Dent / paintcoat damage - Paint




Damage 8: Door - rear right side: Door - Dent / paintcoat damage - Paint




Damage 8: Door - rear right side: Door - Dent / paintcoat damage - Paint



Damage 8: Door - rear right side: Door - Dent / paintcoat damage - Paint




Damage 8: Door - rear right side: Door - Dent / paintcoat damage - Paint



Damage 8: Door - rear right side: Door - Dent / paintcoat damage - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint




Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Damage 10: Front bumper: Front bumper (Halter + Spoiler (L/R) + Aufpralldämpfer erneuert) - Scratched - Paint



Wear and tear 5: Side panel - rear right side: Side panel - Scratch(es) - No deduction



Wear and tear 5: Side panel - rear right side: Side panel - Scratch(es) - No deduction



Wear and tear 6: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Wear and tear 6: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Repainting 1: Mudguard - left side, Bonnet



Repainting 1: Mudguard - left side, Bonnet



Repainting 1: Mudguard - left side, Bonnet



Repainting 1: Mudguard - left side, Bonnet



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VBD8EVXN8038401

Hersteller / Modell: OPEL OPEL Astra 1.5 D Start/Stop Sports Tourer Automatik
Business Edition

Datum	KM-Stand	Beschreibung
17.09.2025	135.834	Bremsinspektion vo + hi; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
07.07.2025	129.643	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
23.04.2025	125.037	AU
16.12.2024	114.168	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
21.05.2024	88.948	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
16.02.2024	74.529	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben vorne
08.08.2023	61.793	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges