

Expertise

Protocol number: 45831245
Order No. / Reference: 26466629
Inspection date: 8 Jun 2026

Manufacturer: Volkswagen

Model: T-Roc 2.0 TDI SCR Life

VIN: WVGZZA1ZRV033375



Vehicle details

Manufacturer / Type / Model / Equipment

Volkswagen T-Roc 2.0 TDI SCR Life

Vehicle Identification number WVGZZA1ZRV033375

Mileage (Read) 199,326 km

First registration 4 Dec 2023

Number of holders 1

Next periodical technical inspection 12/2026
(Report not on hand)

Power / Engine displacement 85 kw / 1,968 ccm

Fuel type / Cylinder Diesel / 4

Gearbox / Number of gears Manual / 6

Type of drive Front drive

Type of vehicle SUV

Colour / colour code Ascot Gray (A7A)

Doors / Seats 5 / 5

Upholstery type Cloth

Colour of upholstery Black-Grey



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	14,300 km
Last service on / at	11/2025 at 154,582 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY222208
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / COS 00433		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,920 kg	Empty weight	

Tyres

Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 99H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	215/60 R16 99H	Winter tyres on Light alloy	Continental	6mm / 6mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 95V	Summer tyres on Light alloy	Falken	3mm / 3mm
2)	215/60 R16 95V	Summer tyres on Light alloy	Falken	4mm / 4mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- 2 USB-C ports at the front, 2 USB-C charging ports at the rear of the center console
- Airbag: Head airbag system for front and rear passengers including front side airbags
- Hill start assist
- Vehicle tool kit
- black roof rails
- Diesel particulate filter
- Tachometer
- Electronic parking brake including auto-hold function
- Automatic headlight control, with LED daytime running lights
- Pedestrian detection
- Luggage compartment floor height-adjustable and removable
- Rear window wiper with intermittent function
- ISOFIX mounting points
- Rear headrests (3)
- Paint finish: Solid
- Steering wheel: Multifunction steering wheel in leather
- front center armrest
- Non-smoking version
- Emergency call service
- Upholstery: Cloth
- Rain sensor
- Wheels: Light alloy (4) "Chester" 6.5 J x 16
- LED taillights, dark red
- Drawer under the right front seat
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Front seats with height adjustment
- Lane keeping assistant "Lane Assist"
- Bumpers in body color
- Textile floor mats front and rear
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking without safe locking, with remote control and 2 remote keys
- Airbag for driver and front passenger, with front passenger airbag deactivation
- App Connect
- Electrically adjustable, folding, and heated exterior mirrors with memory function
- third brake light
- Decorative inlays "Pewter matt"
- Digital cockpit, multi-colored, various selectable information profiles
- Electronic Stability Program with counter-steering support
- Electric windows front and rear
- Windscreen made of laminated safety glass, heat-insulating
- Transmission: 6-speed manual transmission
- Rear window heated
- Interior mirror automatically dimming
- Air conditioning with active combination filter
- Front headrests
- LED headlights
- Illuminated makeup mirrors in the sun visors
- Fatigue detection
- Emergency braking assistant "Front Assist"
- Park Assist system including parking aid
- Radio "Composition"
- Tire pressure monitoring system
- Wheels: Tire Mobility Set
- Gearshift knob in leather
- electromechanical power steering
- Seats: Comfort seats in the front
- Seats: Rear seat backrest asymmetrically split and foldable with center armrest
- Start-stop system with brake energy recuperation
- Telephone interface
- Ambient lighting with logo projection
- Prepared for "We Connect" and "We Connect Plus"
- Green thermal insulation glazing, sides and rear

Extra equipment

- Rear View reversing camera



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wing mirror - left side	Cap - Scratch(es) - Smart repair
2	Door - rear left side	Door edge - Scratch(es) - Smart repair
3	Front bumper	Air-inlet grille (links, rechts, + Kunststoffeinsatz) - Broken / torn - Replace
4	Front bumper	Front bumper - Stone chips - Paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 22 Feb 2024	1.806,28 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Damage 1: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 1: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 2: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 2: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 3: Front bumper: Air-inlet grille (links, rechts, + Kunststoffeinsatz) - Broken / torn - Replace



Damage 3: Front bumper: Air-inlet grille (links, rechts, + Kunststoffeinsatz) - Broken / torn - Replace



Damage 3: Front bumper: Air-inlet grille (links, rechts, + Kunststoffeinsatz) - Broken / torn - Replace



Damage 3: Front bumper: Air-inlet grille (links, rechts, + Kunststoffeinsatz) - Broken / torn - Replace



Damage 3: Front bumper: Air-inlet grille (links, rechts, + Kunststoffeinsatz) - Broken / torn - Replace



Damage 3: Front bumper: Air-inlet grille (links, rechts, + Kunststoffeinsatz) - Broken / torn - Replace



Damage 3: Front bumper: Air-inlet grille (links, rechts, + Kunststoffeinsatz) - Broken / torn - Replace



Damage 3: Front bumper: Air-inlet grille (links, rechts, + Kunststoffeinsatz) - Broken / torn - Replace



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVGZZZA1ZRV033375

Hersteller / Modell: VOLKSWAGEN VW T-Roc 2.0 TDI SCR Life

Datum	KM-Stand	Beschreibung
18.02.2026	184.399	Luftfiltereinsatz ern; Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges
13.02.2026	183.245	Systemtest/Eigendiagnose
21.11.2025	154.582	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
24.06.2025	124.351	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
06.01.2025	91.771	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
19.09.2024	61.769	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
25.04.2024	32.920	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges