



Expertise

Protocol number: 46903819
Order No. / Reference: 26833275
Inspection date: 4 Aug 2026

Manufacturer: Mercedes-Benz

Model: V 220 d lang 9G-TRONIC Edition

VIN: W1V44781313944841



Vehicle details

Manufacturer / Type / Model / Equipment

Mercedes-Benz V 220 d lang 9G-TRONIC Edition

Vehicle Identification number W1V44781313944841

Mileage (Read) 255,750 km

First registration 24 May 2022

Number of holders 1

Fuel type Diesel

Engine displacement / Cylinder 1,950 ccm / 4

Power 120 kW

Gearbox / Number of gears Automatic / 9

Type of drive Rear drive

Type of vehicle Van

Colour / colour code Selenite Grey Metallic
7992

Doors / Seats 4 / 6

Upholstery type Cloth

Colour of upholstery Grey-Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	706 Tag(e)
Last service on / at	05/2024 at 135,419 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GH648215
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / AAY 02042		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	3,100 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100Y	Summer tyres on Light alloy	Bridgestone	6mm / 6mm
2)	245/45 R18 100Y	Summer tyres on Light alloy	Goodyear	4mm / 4mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101V	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	225/55 R17 101V	Winter tyres on Light alloy	unterschiedliche Hersteller	6mm / 8mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- Exhaust gas purification SCR Generation 4
- ADAPTIVE BRAKE with dry braking in wet conditions and hill start assist
- Driver airbag
- Airbag: Windowbag for driver and front passenger
- Outer armrests for individual seats, 2nd rear row
- Increased gross vehicle weight to 3,100 kg
- Electric vent windows in the rear passenger compartment (left and right in the passenger compartment)
- Exit lights in the side doors
- Outdoor temperature display
- Battery: fleece battery 12 V / 92 Ah
- Illuminated mirrors for sun visor
- Lighting in the rear grab handle
- BlueEFFICIENCY package (including fuel efficiency generator and ECO start/stop function)
- Direct steering (with speed-dependent power steering and variable steering ratio)
- ECO start/stop function
- Electronic Stability Program (ESP) (including Anti-lock Braking System (ABS) and Traction Control System (ASR))
- Vehicle key: Electronic key in chrome look
- Front left window, fixed in side wall/sliding door
- Electric window regulator comfort front/front.
- Generator 14 V / 250 A
- Transmission: 9-speed automatic, 9G-TRONIC (including DIRECT SELECT selector lever, steering wheel shift paddles and DYNAMIC SELECT)
- Grab handle in the rear
- Tailgate with window including rear window heating (and wiper/washer system)
- Mechanical child safety lock in the sliding doors
- TEMPMATIC air conditioning (semi-automatic controlled with pollen filter)
- Instrument cluster with color display
- Comfort roof control unit
- Convenient opening and closing with IR radio remote control
- Paint finish: Metallic
- Steering wheel: Multifunction steering wheel with trip computer
- Trunk light
- Mercedes-Benz emergency call system
- Navigation accessories: Pre-installation for navigation
- Package: Parking package with reversing camera (including PARKTRONIC with HOLD function)
- Package: Exterior sports package (7 J x 17 alloy wheels, 20-spoke design, with 225/55 R 17 tires on 7 J x 17 - brake calipers with Mercedes-Benz lettering - sports suspension)
- Breakdown management
- Upholstery: Santos fabric
- Screw-in towing eye front/rear
- Adaptive brake light flashing
- Passenger airbag
- Airbag: Thorax-pelvis sidebags for driver and front passenger
- Armrests for seating in the passenger compartment
- Attention Assist (can detect typical signs of fatigue via steering behavior and warn the driver of impending microsleep)
- Exterior mirrors left and right heated, electrically adjustable from inside (painted in car color, with aspherical curved mirror glass and integrated turn signal light)
- Front footwell lighting
- Hill start assist
- Tinted rear windows, black glass
- Diesel particulate filter
- Electronic tachometer
- Third brake light
- Electrical components for trailer socket
- Driving light assistant
- Chassis: Sport chassis with lowered suspension and selective damping system
- Front right window, fixed in side wall/sliding door
- electric parking brake
- Generator management
- Seatbelt warning device for front passenger seat
- Seatbelt warning device for driver's seat
- Grab handle for entry
- Lockable and illuminated glove compartment
- Interior headliner in grey fabric
- ISOFIX child seat attachment points in the rear and Top Tether attachment points on the back of the rear seat backrest
- TEMPMATIC automatic climate control in the rear (additional heat exchanger/evaporator with blower in the passenger compartment)
- Communication module (LTE) for digital services
- Front headrests
- leather steering wheel
- Steering column mechanically adjustable in height and length
- Headlight range control
- Center console with roller blind
- Package: Aerodynamics
- Package: Mirror package (including automatically dimming interior and exterior mirrors on the driver's side, automatically folding exterior mirrors on the left and right, and ambient lighting)
- Package: Lane Keeping Assist Package (including Lane Keeping Assist, Blind Spot Assist)
- Radio accessories: Digital radio (DAB) (for the DAB, DMB and DAB+ standards)
- Tire pressure monitoring
- Wheels: Comfort tires
- Disc brakes on front and rear axles
- Halogen headlights



- Radio: MBUX Multimedia System Mid (17.8 cm (7") touch display - Bluetooth hands-free system - Media interface - WiFi hotspot function - Personalization for up to 8 people - Predictive function - Flash drive - USB-C port - Radio)
- Windscreen wipers with rain sensor
- Sliding door, right
- electric power steering
- Seat: Single seat, 1st rear row, left
- Seat: Single seat, 1st rear row, right
- Seat: Single seat, 2nd rear row, left
- Seat: Comfort passenger seat (with height and backrest adjustment, seat surface tilt adjustment, removable inner armrest)
- Seats: Seat rail system with quick-release fasteners
- Heated driver's seat
- Storage net for driver's seat backrest
- 12V socket in the trunk/cargo area
- Bumpers and attachments painted in body color
- Carpet for the front vehicle interior (including luggage net in the passenger footwell)
- Ambient lighting tailgate
- Pre-installation for Remote Services Plus (remote vehicle status query - Eco display - personalization - remote door locking and unlocking - geographic vehicle monitoring - vehicle location - vehicle tracking - parking service monitoring)
- Heat-insulating glass all around
- Decorative elements piano lacquer look, black, glossy

- Crosswind Assist
- 3-point safety belts (including mechanical belt height adjustment, belt force limiter and belt tensioner for driver and front passenger)
- Seat: Single seat, 2nd rear row, right
- Seat: Comfort driver's seat (with height and backrest adjustment, seat cushion tilt adjustment, removable inner armrest)
- Passenger seat heating
- Storage net on the passenger seat backrest
- 12V socket
- 12V power outlets for the rear seat rows, right and left
- Cruise control and variable speed limiter SPEEDTRONIC
- Carpet in the rear
- Touchpad
- First aid kit
- Warm air duct to the passenger compartment
- Warning triangle
- Maintenance interval indicator "ASSYST"
- Electronic immobilizer (including locking system with 3-channel radio remote control in the electronic key in chrome look, optical locking feedback and emergency opening (approved by AZT and TÜV))

Extra equipment

- Anodized roof rails
- Chassis: Sport suspension with lowered ride height and selective damping system in conjunction with AMG Line
- LED Intelligent Light System (cornering light (below 40 km/h) - active curve illumination - motorway illumination - ambient lighting - dynamic headlight range control - high beam assist - country road illumination - LED daytime running lights integrated into the main headlights - fog lights - rear lights (tail, brake, rear fog, reversing and indicator lights)
- Decorative elements in piano black look, glossy, in conjunction with AMG Line or Design Package

- Display: 26 cm (10.25") HD touch display
- Luggage securing net
- Fuel tank with larger volume 70 l
- Navigation: Navigation Plus (including live traffic information)
- Wheels: Alloy wheels 7.5Jx18, 5-spoke design
- Seat: Single seat, 1st rear row, right, in conjunction with reclining package
- Seat: Lumbar support, passenger seat
- Seat: Lumbar support driver's seat
- Tie-down rings for seat rails, removable (4 pieces)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - Loss in value
2	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
3	Body	Underbody panelling - Broken / torn - Replace
4	Side panel - rear right side	Side panel (Einschlüsse-Mehrkosten möglich) - Unprofessionally repaired - Conditioning
5	Door - front left side	Door (Lack Druckstelle) - Unprofessionally repaired - Smart repair
6	Roof	Roof (Anätzung-Mehrkosten möglich) - Paint defect - Conditioning
7	Side panel - rear left side	Side panel (Läufer-Mehrkosten möglich) - Unprofessionally repaired - Conditioning
8	Trim / covers	Roof lining - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
2	Trim / covers	Boot lining - Scratch(es) - No deduction
3	Front bumper	Front bumper - Scratch(es) - No deduction
4	Bonnet	Bonnet - Dent / paintcoat damage - No deduction
5	Vehicle glazing	Windscreen - Stone chips - No deduction
6	Door - rear right side	Door - Scratch(es) - No deduction
7	Seat - front	Seat cover - right side - Scratch(es) - No deduction
8	Boot lid / rear door	Boot lid - Dent / paintcoat damage - No deduction
9	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 19 Jan 2026	3.303,93 €
2	Side - left, Provided by user / customer, from 21 Mar 2024	17.376,03 €

Repainting

No.	Repainting
1	Roof rail - left side, Professionally carried out, Invoice of repair done Non-existent
2	Bonnet, Professionally carried out, Invoice of repair done Non-existent
3	Side panel - rear left side, Unprofessionally carried out, Invoice of repair done Non-existent
4	Door - front left side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof rail - left side	180 µm	Bonnet	248 µm
Side panel - rear left side	627 µm	Door - front left side	779 µm



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.





Figure 30: Misc.



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Loss in value



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 3: Body: Underbody panelling - Broken / torn - Replace



Damage 3: Body: Underbody panelling - Broken / torn - Replace



Damage 4: Side panel - rear right side: Side panel (Einschlüsse-Mehrkosten möglich) - Unprofessionally repaired - Conditioning




Damage 4: Side panel - rear right side: Side panel (Einschlüsse-Mehrkosten möglich) - Unprofessionally repaired - Conditioning



Damage 4: Side panel - rear right side: Side panel (Einschlüsse-Mehrkosten möglich) - Unprofessionally repaired - Conditioning



Damage 5: Door - front left side: Door (Lack Druckstelle) - Unprofessionally repaired - Smart repair



Damage 5: Door - front left side: Door (Lack Druckstelle) - Unprofessionally repaired - Smart repair



Damage 6: Roof: Roof (Anätzung-Mehrkosten möglich) - Paint defect - Conditioning




Damage 6: Roof: Roof (Anätzung-Mehrkosten möglich) - Paint defect - Conditioning




Damage 6: Roof: Roof (Anätzung-Mehrkosten möglich) - Paint defect - Conditioning



Damage 7: Side panel - rear left side: Side panel (Läufer-Mehrkosten möglich) - Unprofessionally repaired - Conditioning




Damage 7: Side panel - rear left side: Side panel (Läufer-Mehrkosten möglich) - Unprofessionally repaired - Conditioning



Damage 7: Side panel - rear left side: Side panel (Läufer-Mehrkosten möglich) - Unprofessionally repaired - Conditioning



Damage 8: Trim / covers: Roof lining - Broken / torn - Replace



Damage 8: Trim / covers: Roof lining - Broken / torn - Replace



Wear and tear 3: Front bumper: Front bumper - Scratch(es) - No deduction



Wear and tear 3: Front bumper: Front bumper - Scratch(es) - No deduction



Wear and tear 8: Boot lid / rear door: Boot lid - Dent / paintcoat damage - No deduction



Wear and tear 8: Boot lid / rear door: Boot lid - Dent / paintcoat damage - No deduction



Wear and tear 8: Boot lid / rear door: Boot lid - Dent / paintcoat damage - No deduction



Wear and tear 8: Boot lid / rear door: Boot lid - Dent / paintcoat damage - No deduction



Wear and tear 9: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - No deduction




Wear and tear 9: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - No deduction



Repainting 1: Roof rail - left side



Repainting 1: Roof rail - left side



Repainting 2: Bonnet



Repainting 2: Bonnet



Repainting 3: Side panel - rear left side



Repainting 3: Side panel - rear left side



Repainting 4: Door - front left side



Repainting 4: Door - front left side