



Expertise

Protocol number: 46901206
Order No. / Reference: 26801193
Inspection date: 5 Aug 2026

Manufacturer: Opel	Model: Astra 1.5 D Start/Stop Sports Tourer Automatik Elegance
VIN: W0VBE8EV0M8017827	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Start/Stop Sports Tourer Automatik Elegance	
Vehicle Identification number	W0VBE8EV0M8017827
Mileage (Read)	106,412 km
First registration	15 Jun 2021
Number of holders	1
Next periodical technical inspection	06/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,496 ccm / 3
Power	90 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Argonsilber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	4 %
Last service on / at	12/2025 at 100,256 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA209425
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1844 / ALM 00183		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,980 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Light alloy	Michelin	6mm / 6mm
2)	205/55 R16 91V	Summer tyres on Light alloy	Michelin	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	115/70 R16 92M	Summer tyres on Steel	Continental	5 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaautomatik

Standard equipment

- 2 ignition keys
- Airbag for driver and passenger side
- Airbag: Head airbags, 1st and 2nd row (outer seats)
- Ambient lighting, front doors
- Automatic activation of the hazard warning lights
- Hill Start Assist
- On-board computer
- Roof rails, silver
- Diesel particulate filter (DPF)
- Electronic Stability Program Plus (ESP Plus)
- Front camera
- Transmission: 9-speed automatic transmission
- rear window wiper
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- Rear headrests (3)
- Cargo area cover
- LED daytime running lights
- Steering wheel: Leather steering wheel
- Lighting equipment
- Electric parking brake
- Pedals: Disengaging safety pedals
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire pressure monitoring system
- Power steering
- Luggage compartment safety net
- Seats: Ergonomic active seat
- 12V power outlet in the center console
- Pre-installation for child seat mounting system "ISOFIX"
- Heat-insulating glazing, green tinted, and windshield
- Storage compartments
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- Decorative trim strips in piano black
- Tachometer
- Electric windows front and rear
- Speed controller with limiter
- Back window, heater
- Interior lighting, front and rear
- Automatic climate control, two zones
- trunk light
- Front headrests
- LED headlights
- Light alloy wheels 7 J x 16 in a "10-spoke" design
- Steering column, height and reach adjustable
- Sliding center armrest, front
- Parkpilot, rear parking aid
- Quickheat rapid heating system
- Radio: Multimedia radio with 7" touchscreen color display
- Rear seat backrest folds forward in a 60:40 split
- Seat belts: Three-point seat belts in all seats
- Visibility equipment
- Start/Stop System
- Traction Control (TC) Plus
- Immobiliser
- Central locking with remote control and interior switches



Extra equipment

- Connectivity services (emergency call)
- Detachable trailer hitch (including trailer stability program TSP)
- Fog light
- Heated windscreen, ThermoTec
- Package: Navigation Package 3 oKP
- Package: Winter Premium (Heated seats, multi-stage, driver and front passenger (automatic regulation in conjunction with dual-zone automatic climate control) - Heated leather steering wheel - Electric parking brake - 2 USB ports, rear - Rear footwell heating)
- Paint finish: Metallic
- Parkpilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards)
- Phone: Wireless charging including 2 USB ports, rear
- Upholstery: Alcantara trim (Ergonomic active seat, certified by the German Campaign for Healthy Backs (AGR) - incl. seat contact surfaces partially in Alcantara (2nd row center, headrests, door panels, seat bolsters in imitation leather) - length, height and tilt adjustable - electro-pneumatic lumbar support adjustable in height and length - extendable thigh support - interior trim - pocket on the front seat backs)
- Wheels: Emergency spare wheel, steel 4Jx16
- Electric sliding/tilting sunroof (with pre-selection function and spoiler position, including anti-pinch protection, comfort closing function via remote control of the central locking system (only in conjunction with electric windows, front and rear), and manually operated sunshade)
- Electric tailgate with foot sensor (Sensor-controlled electric tailgate, self-opening and closing via foot gesture or push of a button, including keyless locking and starting system Keyless Open & Start)
- Package: Elegance Package (IntelliLux LED Matrix headlights - LED taillights - Multimedia Navi Pro voice control touchscreen color display multimedia radio Apple CarPlay/Android Auto Bluetooth - Solar Protect heat-insulating glazing, heavily tinted, in the rear)
- Traffic sign assistant with pedestrian detection, front (detection of speed limits, no-overtaking zones and their cancellation, additional information signs (e.g., for wet conditions, slippery surfaces, left/right directions) on standard traffic signs, beginning and end of motorways, expressways and traffic-calmed areas, display of the detected sign in the driver information display (depending on traffic sign quality, visibility and weather conditions), automatic activation between 14 km/h and 200 km/h (during the day) or 150 km/h (at night))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Boot lining (Auf beiden Seiten fehlt die Verriegelung) - Damaged - Replace
2	Door - front right side	Door - dent(s) - Smooth repair work
3	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
5	Misc.	Main inspection - Due - Replace
6	Sill - left side	Sill - Dent / paintcoat damage - Smart repair
7	Side panel - rear left side	Sill - Dent / paintcoat damage - Smart repair
8	Wheel / tyres	Alloy rim - rear right side - Scratched - Replace
9	Vehicle glazing	Rear window - Scratch(es) - Replace
10	Door - rear left side	Door - Scratch(es) - Paint
11	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
12	Door - front left side	Door - Dent / paintcoat damage - Repair and paint



Wear and tear

No.	Component group	Description
-----	-----------------	-------------

1	Bonnet	Bonnet - Stone chips - No deduction
---	--------	-------------------------------------

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No. Repainting

1	Boot lid / rear door, Side panel - rear right side, Door - rear right side, Professionally carried out
---	--

Paint coat thickness measurement

Boot lid / rear door	249 µm	Side panel - rear right side	859 µm
Door - rear right side	313 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Navigation




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Damage 1: Trim / covers: Boot lining (Auf beiden Seiten fehlt die Verriegelung) - Damaged - Replace




Damage 1: Trim / covers: Boot lining (Auf beiden Seiten fehlt die Verriegelung) - Damaged - Replace




Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 3: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 3: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 6: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace




Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 9: Vehicle glazing: Rear window - Scratch(es) - Replace



Damage 9: Vehicle glazing: Rear window - Scratch(es) - Replace



Damage 9: Vehicle glazing: Rear window - Scratch(es) - Replace



Damage 10: Door - rear left side: Door - Scratch(es) - Paint




Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint




Damage 10: Door - rear left side: Door - Scratch(es) - Paint




Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Boot lid / rear door: 249 µm



Side panel - rear right side: 859 µm



Door - rear right side: 313 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VBE8EV0M8017827

Hersteller / Modell: OPEL OPEL Astra 1.5 D Start/Stop Sports Tourer Automatik Elegance

Datum	KM-Stand	Beschreibung
01.06.2026	105.705	Batterie ern; Systemtest/Eigendiagnose
02.12.2025	100.256	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
12.08.2025	93.099	Getriebeöl ern/prüfen; Systemtest/Eigendiagnose
17.06.2025	92.672	Systemtest/Eigendiagnose
05.05.2025	92.434	Ladeluftschlauch ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
22.01.2025	141.350	Systemtest/Eigendiagnose; Wartung Sonstiges; Wasserpumpe ern
28.06.2024	80.025	HU + AU; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
19.04.2024	74.635	Reparatur Sonstiges; Systemtest/Eigendiagnose
25.03.2024	72.854	Systemtest/Eigendiagnose; Wasserpumpe ern
12.03.2024	72.563	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
14.06.2023	50.543	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
03.02.2023	30.000	Systemtest/Eigendiagnose
15.09.2022	37.134	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges