



Expertise

Protocol number: 46378562
Order No. / Reference: 26462054
Inspection date: 7 Jul 2026

Manufacturer: Mazda

Model: 2 SKYACTIV-G 90 M HYBRID Homura

VIN: JMZDJ6HC601451188



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mazda 2 SKYACTIV-G 90 M HYBRID Homura	
Vehicle Identification number	JMZDJ6HC601451188
Mileage (Read)	22,715 km
First registration	10 May 2023
Number of holders	1
Next periodical technical inspection	05/2028
(Report on hand)	
Power / Engine displacement	66 kw / 1,496 ccm
Fuel type / Cylinder	Hybrid Petrol / E / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Jet Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	80 %
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HH046238
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	7118 / AIO 00004		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,540 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	185/65 R15 88T	Winter tyres on Steel	Falken	6mm / 6mm
2)	185/65 R15 88T	Winter tyres on Steel	Falken	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	185/60 R16 86H	Summer tyres on Light alloy	Toyo	5mm / 5mm
2)	185/60 R16 86H	Summer tyres on Light alloy	Toyo	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Front airbag (side airbags)
- Airbag head/shoulder airbags front and rear
- Electrically adjustable and heated exterior mirrors
- Hill Start Assist (HLA)
- Colored glazing
- Shark Fin roof antenna
- Tachometer
- Vehicle dynamics control: G-Vectoring Control Plus (GVC)
- Wheels: 16" alloy wheels in black (with tires 5.5J 185/60 R16)
- Cruise control system with speed limiter (Cruisematic)
- Back window, heater
- i-stop: Intelligent Mazda engine stop/start system
- Headrests
- Steering wheel: Leather steering wheel, leather gearshift knob and handbrake lever
- Steering column adjustable in height and length
- Red air vent rings
- Makeup mirrors for driver and front passenger
- Engine start/stop button
- Emergency Stop Signaling (ESS)
- Upholstery: Cloth
- Radio: Mazda audio system with radio (17.8 cm (7 inch) color display, high resolution, usable as a touchscreen when the vehicle is stationary - Multi Commander for convenient and safe operation - Digital radio tuner (DAB+) - two USB ports and AUX port - Internet radio application: via the aha and Stitcher apps - 6 speakers)
- Radio accessories: Hands-free system with voice control and Bluetooth audio streaming
- Rear view camera
- Rear side windows and rear window tinted
- Power steering
- Seats: Passenger seat height adjustable
- Seats: ISOFIX child seat anchors
- Daytime running lights, halogen
- Exterior door handles painted in car color
- Central locking with remote control
- Airbag for driver and front passenger
- Anti-lock braking system
- Exterior mirror caps in black
- third brake light
- Coming/leaving home light function
- Roof spoiler in car color
- Dynamic Stability Control (DSC) with Traction Control System (TCS)
- Electric windows, front and rear
- luggage compartment cover
- Transmission: 6-speed manual transmission
- rear window wiper
- Comfort turn signal function
- LED headlights with automatic headlight range control
- Steering wheel: Steering wheel control buttons for audio source and volume
- Reading lamps
- M-Hybrid System
- Mobility kit (compressor and tire sealant)
- Multi-information display
- Package: Touring Package (Rear Cross Traffic Alert (RCTA), warning of impending collision with cross traffic when reversing out of a parking space - Rear parking sensors - Automatic climate control - Light and rain sensor - Heated seats for driver and front passenger - Blind Spot Monitoring (BSM), warning of vehicles in the "blind spot" or risk of collision when changing lanes)
- Radio accessories: Enhanced voice control
- Radio accessories: Social media integration
- Tire pressure monitoring system (indirectly via ABS)
- Rear seat backrest asymmetrically split and foldable (60:40)
- Seat belts: 3-point automatic seat belts for all seats
- Seats: Driver's seat height adjustable
- Lane Keeping Assist - Active with Steering Support (LAS)
- Phone accessories: Enhanced smartphone integration
- Electronic immobilizer

Extra equipment

- Paint finish: Metallic
- winter tires
- Navigation: Mazda SD navigation system (3D map display, high resolution - destination input via contact data from a smartphone possible - expandable with online services (fee applies) - arrow navigation additionally in the head-up display (optional with Sports-Line))



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (Wartungsnachweis nicht vorhanden) - No evidence - No deduction
2	Instrument panel	Indicator light (Reifendruckkontrolle) - on - Perform diagnosis
3	2nd wheel set	1 alloy rim - Scratched - Loss in value
4	Rear bumper	Rear bumper - Scratched - Smart repair
5	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	Interior	Interior - Scratch(es) - No deduction
5	Door - front left side	Door edge - Scratch(es) - No deduction
6	Side panel - rear right side	Sill - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Documents - Service book (Digitaler Nachweis)

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Damage 2: Instrument panel: Indicator light (Reifendruckkontrolle) - on - Perform diagnosis



Damage 3: 2nd wheel set: 1 alloy rim - Scratched - Loss in value




Damage 3: 2nd wheel set: 1 alloy rim - Scratched - Loss in value




Damage 3: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 3: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 4: Rear bumper: Rear bumper - Scratched - Smart repair




Damage 4: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 5: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint