



Expertise

Protocol number: 46536047
Order No. / Reference: 26501140
Inspection date: 13 Apr 2026

Manufacturer: Mercedes-Benz
VIN: W1KEG1BB5PF023793

Model: EQE 300 Electric Art



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz EQE 300 Electric Art	
Vehicle Identification number	W1KEG1BB5PF023793
Mileage (Read)	104,361 km
First registration	21 Feb 2023
Number of holders	1
Next periodical technical inspection	02/2026
(Report not on hand)	
Power / Engine displacement	109 kw / 0 ccm
Fuel type / Cylinder	Electric / 0
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Saloon car
Colour / colour code	Schwarz uni
Doors / Seats	4 / 5
Upholstery type	Leather
Colour of upholstery	Black
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	293 Tag(e)
Last service on / at	12/2024 at 77,151		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ147968
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2222 / BIN 00869		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,880 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/45 R19 104V	Winter tyres on Light alloy	Goodyear	8mm / 8mm
2)	255/45 R19 104V	Winter tyres on Light alloy	Goodyear	8mm / 8mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/45 R19 104Y	Summer tyres on Light alloy	Goodyear	6mm / 6mm
2)	255/45 R19 104Y	Summer tyres on Light alloy	Goodyear	6mm / 6mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS - Anti-lock Braking System
- Airbag: Automatic passenger airbag deactivation
- Airbag: Windowbag all around
- Ambient lighting
- Brake assist, active
- Door sills with "Mercedes-Benz" lettering
- Driver display with 25.4 cm (10.25") screen diagonal
- Flex Bottle Holder
- Velour floor mats
- Transmission: Direct drive
- Instrument panel and door sills in ARTICO man-made leather, space grey
- Rear headrests (3)
- Paint finish: Solid
- Charging cable for wallbox and public charging station, 5m, smooth, 11kW
- Charging system: AC charging system 11kW
- LED taillights in 3D helix design
- Mercedes-Benz emergency call system
- Center console in high-gloss black
- Navigation accessories: Pre-installation for navigation services
- Navigation: MBUX Navigation Premium
- Package: Parking package with reversing camera
- PRE-SAFE system
- Radio: MBUX multimedia system
- Radio accessories: Communication module (LTE Advanced) for using Mercedes me connect
- Remote Services Premium
- Remote and extended Charging Services Premium
- Seats: Rear seat backrests foldable 40/20/40 split
- Seats: Comfort seats
- Cruise control
- Door center panels and transition from the center console to the instrument panel in ARTICO man-made leather
- Pre-installation for remote and navigation services
- Decorative elements with fine textured black finish
- Airbag for driver and front passenger
- Airbag: Kneebag for driver
- Acoustic environmental protection
- Traction control (ASR)
- DYNAMIC SELECT
- Electronic Stability Program (ESP)
- Chassis: Comfort chassis
- Rear seat belt status indicator in the instrument cluster
- Speed Limit Assistant
- Black fabric headliner
- Climate: Pre-conditioning
- THERMATIC automatic climate control with 2 climate zones
- Front headrests are height-adjustable
- Charging cable for household socket, 5m, smooth
- Charging system: Direct current charging system (DC charging)
- LED High Performance Headlights
- Steering wheel: Multifunction sports steering wheel in ARTICO man-made leather
- Navigation accessories: Pre-installation for Live Traffic Information
- Navigation: Hard disk navigation
- Package: Interior lighting package
- Upholstery: ARTICO leatherette/fabric
- Radio: Extended MBUX functions
- Radio accessories: Digital radio
- Tire pressure monitoring system
- Remote Services Plus
- Remote and Charging Services Premium
- Heated windshield washer system
- Seats: i-Size child seat attachment
- Seats: Heated seats for driver and front passenger
- TIREFIT
- URBAN GUARD Vehicle Protection Plus
- Pre-installation for digital key handover
- High-visibility vest for drivers



Extra equipment

- Radiator grille with Mercedes-Benz pattern (The black panel radiator grille features finely designed stars)
- Package: Electric Art Line Exterior (Black panel radiator grille with central Mercedes star - Front apron in body color with chrome trim elements in the upper and lower sections - Side skirts painted in black with chrome door trim strips - Rear apron painted in body color with a grained black lower section and chrome trim element - Belt and window line trim strips in chrome - 48.3 cm (19") alloy wheels in 5-twin-spoke design (R39) painted in high-gloss black and polished with 255/45 R19 tires on 8.5J x 19 ET47.5)
- Upholstery: NEOTEX/ARTICO leatherette black/space grey
- Wheels: 48.3 cm (19") light alloy wheels in 5-twin-spoke design (black high-gloss painted and diamond-turned with 255/45 R19 on 8.5J x 19 ET47.5)
- Heat-insulating dark tinted glass
- Steering wheel: Multifunction sports steering wheel in leather (with steering wheel shift paddles (428) and steering wheel trim in silver chrome - control via touch control panels)
- Package: Premium Package (Advanced Plus Package contents - Active ambient lighting - Burmester surround sound system - THERMOTRONIC automatic climate control - Driving Assistance Package Plus: Active Assistance - DISTRONIC distance control, speed limit, traffic jam, steering, braking, lane keeping, blind spot PRE-SAFE PLUS PRE-SAFE Impulse Side - DIGITAL LIGHT - Parking Package with 360° camera - URBAN GUARD vehicle protection Plus - MBUX Augmented Reality for navigation)
- Seats: Heated rear seats (Comfortable warmth in cooler weather for your rear passengers too: the heated seats quickly bring the seat cushions and backrests of the outer rear seats to a pleasant temperature. The intensity can be selected in three levels. Intelligent and convenient: the heated seats switch off automatically.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - Due - Perform
2	Box	Load sill - Scratched - Smart repair
3	Body	Underbody panelling - Damaged - Replace
4	2nd wheel set	1 alloy rim - Scratched - Loss in value

Wear and tear

No.	Component group	Description
1	2nd wheel set	1 alloy rim - Scratch(es)
2	Door - front left side	Door - Scratch(es)
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Bonnet	Bonnet - Stone chips - No deduction
5	Wheel / tyres	Alloy rim - rear left side (Gehört nicht zur Ausstattung) - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 17 Jun 2025	1.220,04 €
2	Front, Provided by user / customer, from 11 Sept 2025	2.167,66 €
3	Rear, Side right, Provided by user / customer, from 8 Apr 2025	2.250,37 €

Repainting

No. Repainting

- Side panel - rear right side

Paint coat thickness measurement

Side panel - rear right side 198 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Comments

- Wartungshistorie gemäß Auftraggeber Informationen.
- Für den montierten Radsatz wurde kein Nachweis erbracht.
- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.





Figure 22: Misc.



Figure 23: Misc.



Damage 2: Box: Load sill - Scratched - Smart repair



Damage 2: Box: Load sill - Scratched - Smart repair



Damage 3: Body: Underbody panelling - Damaged - Replace



Damage 3: Body: Underbody panelling - Damaged - Replace



Damage 3: Body: Underbody panelling - Damaged - Replace



Damage 3: Body: Underbody panelling - Damaged - Replace



Damage 4: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 4: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 4: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Wear and tear 3: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 4: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 5: Wheel / tyres: Alloy rim - rear left side (Gehört nicht zur Ausstattung) - Scratched - No deduction



Wear and tear 5: Wheel / tyres: Alloy rim - rear left side (Gehört nicht zur Ausstattung) - Scratched - No deduction



Repainting 1: Side panel - rear right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1KEG1BB5PF023793

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ EQE 300 Electric Art

Datum	KM-Stand	Beschreibung
01.12.2024	77.151	Regelwartungsdienst
20.03.2024	42.139	Regelwartungsdienst