

MACDAM

Volkswagen ID.4 '21 BEV


Vehicle information

Make:	Volkswagen	License:	
Gearbox:	Automatic	Body color:	
Model:	ID.4 '21 BEV	VIN:	WVGZZZE2ZMP024808
Fuel type:	Electric	Power:	150 kW
Version:	ID.4 77kWh Life	First registration	22/06/2021
Mileage:	168547 km	N° of doors:	

Damage summary

Front	2
Interior	3
Left	2
Rear	4
Right	5

Commercial pictures





Options according to the inspector				
Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser
Radio multimedia	Yes	Telephone equipment	Yes	

Damages

Alloy rim FR

Scratch(es)

Repair and paint (complete)

Right



Alloy rim RR

Scratch(es)

Repair and paint (complete)

Right





Boot lid covering R

Scratch(es)

Smart repair

Rear



Bumper F

Scratch(es)

Repair and paint (complete)

Front



Bumper trim F

Scratch(es)

Replace

Front



Charging cable (normal)

Missing
Replace
Rear



Door FR

Dent(s) and scratch(es)
Repair and paint (complete)
Right




Door frame RL

Dent(s) and scratch(es)
Repair and paint (complete)
Left



Door RR

Scratch(es)
Repair and paint (complete)
Right



Ignition key

Worn
Replace
Interior



Rear light R

Scratch(es)
Replace
Rear



Shutter / cover
Missing
Replace
Interior



Tailgate / Boot
Dent(s)
Repair and paint (complete)
Rear



User's manual
Missing
Replace
Interior

Wheel arch cover FL
Scratch(es)
Replace
Left



Wing RR
Dent(s)
Repair and paint (complete)
Right



Tyres			
Front Left			
Summer			
235/55/19/101/T			
Hankook			
2.9 mm			
Front Right			
Summer			
235/55/19/101/T			
Hankook			
2.9 mm			
Rear Left			
Summer			
235/55/19/101/T			
Hankook			
3.4 mm			
Rear Right			
Summer			
235/55/19/101/T			
Hankook			
3.7 mm			

Checks			
Certificate of Conformity	No	CO2 Emission	0
Digital maintenance	Yes	GPS storage	Yes
GPS storage	HD	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	2	Service book	N/A
User's manual	No		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.